

Nebraska Harvest Center  
925 280th Street  
Seward NE 68434  
Phone: (402) 643-4050  
Fax: () -  
Email: inquiry@nebharv.com  
www.nebharv.com

Doc/Invoice: 01-25955  
Date: 2/13/2015  
Customer Id: CLAAS FINANCIAL  
Phone: .....  
Customer PO:  
Salesperson:  
User:

## SERVICE INVOICE

Claas Financial Services LLC

Ship To:  
Claas Financial Services LLC

Opened: 1/27/2015  
Work Order No: 01-27049  
My Reference: 740 C4800442  
Responsible Tech: N.Emons  
Meter: 871.0 hours  
Pickup Date:

Make: lexion  
Model: 740TT  
Serial: C4800442  
Unit No: 671  
Delivery Date:

Recon					
Item/Tag	Type	Description/Model/Serial Number	Quantity	Tax	Price
<b>Recon Kit</b>					
Installed the Recon kit on the machine					
CLFRR700	PA	CLA - FRR KIT - 700 SERIES	1.00	N	
	SL	Recondition of Used Equipment - Shop		N	
<b>Total Recon Kit</b>					
<b>01 Valves</b>					
Adjusted the engine valves					
	SL	Recondition of Used Equipment - Shop		N	
<b>Total 01 Valves</b>					
<b>02 APS</b>					
Replaced 4 APS cap holders that were bent over					
	SL	Recondition of Used Equipment - Shop		N	
6176310	PA	CLA - PADDLE	4.00	N	
<b>Total 02 APS</b>					
<b>03 Knives</b>					
Replaced all the rotary chopper knives					
	SL	Recondition of Used Equipment - Shop		N	
3531950	PA	CLA - KNIFE SECTION	52.00	N	
<b>Total 03 Knives</b>					
<b>05 Belt</b>					
Removed the stage 1 cylinder belt and replaced the APS belt					
	SL	Recondition of Used Equipment - Shop		N	
2361720	PA	CLA - HEXAGONAL NUT	1.00	N	

Nebraska Harvest Center  
925 280th Street  
Seward NE 68434  
Phone: (402) 643-4050  
Fax: () -  
Email: inquiry@nebharv.com  
www.nebharv.com

Doc/Invoice: 01-25955  
Date: 2/13/2015  
Customer Id:  
Phone:  
Customer PO:  
Salesperson:  
User:

## SERVICE INVOICE

Claas Financial Services LLC

Ship To:  
Claas Financial Services LLC

Opened:	1/27/2015	Make:	lexion
Work Order No:	01-27049	Model:	740TT
My Reference:	740 C4800442	Serial:	C4800442
Responsible Tech:	N.Emons	Unit No:	671
Meter:	871.0 hours	Delivery Date:	

Pickup Date:					
6672511	PA	CLA - POWER BAND BELT	1.00	N	

### Total 05 Belt

#### 7 Full Service

Changed all the air filters, engine oil and filter, fuel filters and changed all the heavy oils

	SL	Recondition of Used Equipment - Shop		N	
1R-0749	PA	OTH - Fuel Filter TIER 4	2.00	N	
1R-1808	PA	OTH - Oil Filter	1.00	N	
0773672	PA	CLA - FILTER ELEMENT	1.00	N	
0773821	PA	CLA - FILTER SAFTEY CAR	1.00	N	
1474300	PA	CLA - AGRISHIFT MT 80W-90	3.00	N	
1474370	PA	CLA - AGRIGREASE EP 2	24.00	N	
1474450	PA	CLA - AGRHYD HV 46 Multigrade	2.00	N	
1474830	PA	CLA - AGRIMOT ULTRATEC 10W-40	2.00	N	
5100541	PA	CLA - FILTER ELEMENT	1.00	N	
5596460	PA	CLA - POCKET FILTER	2.00	N	
7836620	PA	CLA - CHANGEABLE FILTER	1.00	N	

### Total 7 Full Service

#### Inspection

Inspected the machine and made a quote

	SL	Inspection-Service		N	
--	----	--------------------	--	---	--

### Total Inspection

Nebraska Harvest Center  
925 280th Street  
Seward NE 68434  
Phone: (402) 643-4050  
Fax: () -  
Email: inquiry@nebharv.com  
www.nebharv.com

Doc/Invoice: 01-25955  
Date: 2/13/2015  
Customer Id:  
Phone:  
Customer PO:  
Salesperson:  
User:

## SERVICE INVOICE

Claas Financial Services LLC

Ship To:  
Claas Financial Services LLC

Opened: 1/27/2015  
Work Order No: 01-27049  
My Reference: 740 C4800442  
Responsible Tech: N.Emons  
Meter: 871.0 hours  
Pickup Date:

Make: lexion  
Model: 740TT  
Serial: C4800442  
Unit No: 671  
Delivery Date:

Customer Id: **CLAAS FINANCIAL**

ON Account

Signature: \_\_\_\_\_

1