



Custom Track Service Percent Worn

**FOLEY EQUIPMENT
COMPANY**

SHERWOOD LEASING INC

Prepared By : CRAIG ROY

Phone Number : (785) 825-4661

Cell Number : (785) 452-1151

Model :	330CL	Hour Meter Reading :	12,167	Inspection Date :	8/26/2016
Manufacturer :	Caterpillar	Hours Per Week :	17	Next Inspection Date :	2/26/2017
Serial Number :	DKY03714	Odometer Reading :		Next Inspection Hours :	12,667
Equipment Number :	20.58L	Forward Odometer Reading :		Last Service Date :	8/26/2016
Link Manufacturer :	Caterpillar	Reverse Odometer Reading :			
Roller Manufacturer :	Caterpillar	Job Site :	Sherwood Shop Wichita	<u>Underfoot Conditions</u>	
Idle Manufacturer :	Caterpillar		<u>Left</u> <u>Right</u>	Impact :	Low
		Track Sag :		Abrasion :	Moderate
		Frame Extension :		Moisture :	Moderate
		Maximum :		Packing :	Moderate
		Dry Joints :		Bushing Allowable Wear :	Greater
				Link Allowable Wear :	Greater

	Status		Date Installed		SMU Installed		Hours on Wear Surface			Measurement (Inches)		Percent Worn			
Position	Left	Right	Left	Right	Left	Right	Left	Right	Tool Used	Left	Right	Left	Right		
LINKS (127) 6Y2589 Sections : 49 Track Group : Link Assembly :															
	Replaced	Replaced	7/6/2010	7/6/2010	6,556	6,556	5,611	5,611	Ultrasonic	1.26	1.27	35 %	32 %		
BUSHINGS (420,1024) 2010827 Grease Lubricated Track															
Internal	Replaced	Replaced	7/6/2010	7/6/2010	6,556	6,556	5,611	5,611	Tape	34.20	34.20	30 %	30 %		
External	Replaced	Replaced	7/6/2010	7/6/2010	6,556	6,556	5,611	5,611	Ultrasonic	0.28	0.33	82 %	67 %		
SHOES (2823) Master Shoes : Triple Grouser Width : 31.50 (Inches)															
	Original	Original	7/6/2010	7/6/2010	6,556	6,556	5,611	5,611	Ultrasonic	1.48	1.50	26 %	23 %		
IDLERS (4426) Front : 1362422 Rear : Conventional															
Front	Original	Original	6/20/2005	6/20/2005	0	0	12,167	12,167	Depth Gauge	0.83	0.90	18 %	40 %		
CARRIER ROLLERS (4722) 6Y5323 Conventional															
Front	Replaced	Replaced	8/26/2016	6/20/2005	12,167	0	0	0	Caliper	6.30	6.00	0 %	30 %		
2	Replaced	Replaced	8/26/2016	6/20/2005	12,167	0	0	0	Caliper	6.30	6.01	0 %	29 %		
TRACK ROLLERS (5333,) Single Flange : 1791486 Double Flange :															
	L	R													
Front	S	S	Original	Original	6/20/2005	6/20/2005	0	0	12,167	12,167	Ultrasonic	1.60	1.57	93 %	101 %
2	S	S	Original	Original	6/20/2005	6/20/2005	0	0	12,167	12,167	Ultrasonic	1.70	1.69	67 %	69 %
3	S	S	Original	Original	6/20/2005	6/20/2005	0	0	12,167	12,167	Ultrasonic	1.72	1.73	61 %	59 %
4	S	S	Original	Original	6/20/2005	6/20/2005	0	0	12,167	12,167	Ultrasonic	1.72	1.73	61 %	59 %
5	S	S	Original	Original	6/20/2005	6/20/2005	0	0	12,167	12,167	Ultrasonic	1.72	1.72	61 %	61 %
6	S	S	Original	Original	6/20/2005	6/20/2005	0	0	12,167	12,167	Ultrasonic	1.70	1.70	67 %	67 %
7	S	S	Original	Original	6/20/2005	6/20/2005	0	0	12,167	12,167	Ultrasonic	1.67	1.69	75 %	69 %
8	S	S	Original	Original	6/20/2005	6/20/2005	0	0	12,167	12,167	Ultrasonic	1.67	1.68	75 %	72 %
9	S	S	Original	Original	6/20/2005	6/20/2005	0	0	12,167	12,167	Ultrasonic	1.53	1.55	112 %	107 %
Swapped	---	---	---	---	---	---	---	---	---	---	---	---	---	86 %	86 %

Notes : Pins and bushings not turned. Hours on some of the undercarriage items are not known. Both l.h. top carriers got replaced at this time.

The sprocket rims are in fair condition.