

A-Z Services, LLC

(405) 922-2293

21

Date Of Inspection	Boom Inspection	Dielectric Test	Inspected By
	5-2016	5-2016	MRK

Certification: This vehicle has been inspected by A-Z Services, Inc.

FMCSA ANNUAL VEHICLE INSPECTION LABEL

NO.

A RECORD OF THIS VEHICLE'S ANNUAL VEHICLE REPORT IS MAINTAINED AT: [X] MOTOR CARRIER [ ] OTHER ENTITY

Choctaw Electric cooperative
COMPANY/NAME

PO Box 758
STREET

Hugo, OK 74743
CITY, STATE, ZIP CODE

TELEPHONE

113742
MOTOR CARRIER IDENTIFICATION NUMBER

VEHICLE IDENTIFICATION: IF THE VEHICLE IS NOT READILY, CLEARLY, AND PERMANENTLY MARKED, CHECK ONE AND COMPLETE.

[X] FLEET UNIT [ ] VEHICLE ID [ ] LICENSE/REGISTRATION NUMBER 21

CERTIFICATION: THIS VEHICLE HAS PASSED AN INSPECTION IN ACCORDANCE WITH 49CFR 396.17 THROUGH 396.23.

Copyright 2015 J. J. Keller & Associates, Inc. • Neenah, WI
JJKeller.com • (800) 327-6868 • Printed in the USA

1340 (Rev. 10/15)

MONTH:

JAN [ ] FEB [ ]
MAR [ ] APR [ ]
MAY [ ] JUNE [ ]
JULY [ ] AUG [ ]
SEPT [ ] OCT [ ]
NOV [ ] DEC [ ]

YEAR:

[ ] 2016
[ ] 2017 [ ] 2018