Hale's Sales and Service

Invoice

Ph. 316.772.5853 Fax 316.772.0043 804 SE 125th N Sedgwick, KS 67135

| Rep./ Tech. | Date | Invoice # |
|-------------|------------|-----------|
| | 10/10/2017 | 24845 |

| Bill To | | |
|--------------|--|--|
| Hale's Sales | | |
| | | |
| | | |
| | | |
| | | |

| P.O. Number | Terms | |
|-------------|----------------|--|
| | Due on receipt | |

| Quantity | Item Code | Description | Price Each | Amount |
|----------|----------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|----------------|
| | WORK PERFORMED | 991038-000439 60" gravely. hrs. 478. Customer states engine grinds when turning over. Check out and replaced flywheel and starter due to missing teeth. also replaced ignition switch and arm safety switch due to corrosion. Changed oil and filter, replaced fuel and air filters, replaced spark plugs, replaced blades, and installed new battery. LABOR | 75.00 | 0.00 375.00 |
| 1 | 2402523s | Kohler flywheel | 160.80 | 160.80 |
| 1 | SWITCH | ignition switch | 24.00 | 24.00 |
| 1 | 781211 | SAFETY SWITCH -ARMS | 6.65 | 6.65 |
| 1 | 07160 | FUEL FILTER IN LINE | 8.34 | 8.34 |
| 1 | 3208306s | Kohler air cleaner | 15.89 | 15.89 |
| 1 | 4508301S | KOHLER PRE CLEANER | 3.98 | 3.98 |
| 1 | SP30 | SP-30 BATTERY | 58.30 | 58.30 |
| 1 | 5205002S | KOHLER OIL FILTER | 8.71 | 8.71 |
| 2 | 10W30 | 10W30 | 5.79 | 11.58 |
| 1 | 3209808S | Kohler Starter | 159.76 | 159.76 |
| 3 | BLADE | 603992 | 14.01 | 42.03 |

No returns on ELECTRICAL parts, 30% Restock fee on returnable parts, NO Returns on Special Order Parts. WARRANTY DOES NOT PAY FOR TRANSPORTATION CHARGES. All Equipment Sales are Final.

Total

\$875.04