

Make:FREIGHTLINER  
FLD120

1FUVDSEBOYLF41259

2000

**Repairs to Vehicle:**

**Date**

REPLACED DRIVER SIDE REAR DRIVE SLACK ADJUSTER REPLACED PASSENGER SIDE FRONT	5/9/2017
REPLACED HOOD	5/23/2017
NEW STEER TIRES 11R24.5	6/5/2017
Charged A/c, Repair oil pan, change oil	11-Jun
NEW CLUTCH AND CLUTCH BRAKE	6/14/2017
8 new drive tires	6/23/2017
CHANGED OIL PAN AND COMPLETE SERVICE	6/26/2017
NEW OIL PAN	7/9/2017
NEW PUSHER SPRINGS	8/3/2017
NEW PUSHER TIRES AND WHEELS	8/7/2017
NEW OIL PAN AND FULL SERVICE	8/23/2017
REPAIRED EXHAUST TIGHTEND DIFF FRONT DRIVE AXLE	9/19/2017
REPAIRED BATTERY CABLE END	10/11/2017
REPLACED WATER PUMP REPLACED AC CLUTCH NEW ALTERNATOR BELT	11/2/2017
REPLACED CLUTCH AND NEW CLUTCH BRAKE NEW FUEL LINES TO TANK	12/11/2017

RETURN POLICY: All claims and returned goods must be accompanied by this invoice and in their original packaging. All returns may be subject to a handling fee. To ensure full credit, all cores must be returned in their original container within 30 days of the original purchase date and meet vendor core requirements. Returns after 30 days and returns on electrical or special order parts are not allowed.

DATE ENTERED 02 NOV 17	YOUR ORDER NO. [REDACTED]	DATE SHIPPED 02 NOV 17	INVOICE DATE 02 NOV 17	INVOICE NUMBER 509102B
---------------------------	------------------------------	---------------------------	---------------------------	---------------------------

PAGE 1 OF 1

S  
O  
L  
D  
  
T  
O

ACCOUNT NO. F16878

S  
H  
I  
P  
  
T  
O

ARMSTRONG RENTALS LLC  
[REDACTED]

SHIP VIA	EMPLOYEE	SLSM.	B/L NO.	TERMS	F.O.B. POINT	LIST	NET	AMOUNT	BIN
WILL CALL	2884	LN2		NET 10TH	LINCOLN, NE				
QTY	SHIP	R.O.	PART NO.	DESCRIPTION					
1	1	0	DR/8700018	35SI REMAN					LS04
			REMAN PART S/N:	DUE: 02DEC17					LS08
1	1	0	DDE/R23539929	S60 WATER					
			Part number	DDE/R23539929	replaces				DDE/R23539602
			REMAN PART S/N:	DUE: 02DEC17					LS02
1	1	0	ABP/N83-303123T	CLUTCH					LS02
1	1	0	ABP/N83-304201T	COMPRESS					BELTRK
1	1	0	GT/4080585DF	BELT-MICRO					
			05-11897961						

ANY NEW PARTS PURCHASED FOR INSTALLATION ON NEW VEHICLES PURCHASED WITHIN THE FIRST 6 MONTHS MAY BE SUBJECT TO FET. CUSTOMER IS RESPONSIBLE FOR THE PAYMENT DIRECTLY TO THE IRS.

Now you can pay online! It is quick & easy. Select Make A Payment at the bottom our website [truckcentercompanies.com](http://truckcentercompanies.com) Mastercard/Visa/Discover

PARTS	[REDACTED]
SUBLET	
FREIGHT	0.00
SALES TAX	0.00
<b>TOTAL</b>	[REDACTED]

TOTALS

CUSTOMER'S SIGNATURE  
X

PRINTED NAME: \_\_\_\_\_

DEALER CODE TJFD

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUM
	101
DATE 2-12-17	

MOTOR CARRIER OPERATOR <i>Armstrong Rentals</i>	INSPECTOR NAME (PRINT OR TYPE)
ADDRESS	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. <input type="checkbox"/> YES
CITY, STATE, ZIP CODE	VEHICLE IDENTIFICATION (✓ AND COMPLETE) <input type="checkbox"/> LIC. PLATE NO. <input type="checkbox"/> VIN <input type="checkbox"/> OTHER <i>ME 3-6931</i>
VEHICLE TYPE <input type="checkbox"/> TRACTOR <input type="checkbox"/> TRAILER <input type="checkbox"/> TRUCK <input type="checkbox"/> BUS <input type="checkbox"/> (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED							
OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
✓			<b>1. BRAKE SYSTEM</b>	✓			<b>6. SAFE LOADING</b>
✓			a. Service Brakes	✓			a. Part(s) of vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway.
✓			b. Parking Brake System	✓			b. Protection against shifting cargo.
✓			c. Brake Drums or Rotors	✓			c. Container securement devices on intermodal equipment.
✓			d. Brake Hose	✓			<b>7. STEERING MECHANISM</b>
✓			e. Brake Tubing	✓			a. Steering Wheel Free Play
✓			f. Low Pressure Warning Device	✓			b. Steering Column
✓			g. Tractor Protection Valve	✓			c. Front Axle Beam and All Steering Components Other Than Steering Column
✓			h. Air Compressor	✓			d. Steering Gear Box
✓			i. Electric Brakes	✓			e. Pitman Arm
✓			j. Hydraulic Brakes	✓			f. Power Steering
✓			k. Vacuum Systems	✓			g. Ball and Socket Joints
			<b>2. COUPLING DEVICES</b>				h. Tie Rods and Drag Links
✓			a. Fifth Wheels	✓			i. Nuts
✓			b. Pintle Hooks	✓			j. Steering System
✓			c. Drawbar/Towbar Eye	✓			<b>8. SUSPENSION</b>
✓			d. Drawbar/Towbar Tongue	✓			a. Any U-bolt(s), spring hanger(s), or other axle positioning part(s) cracked, broken, loose or missing resulting in shifting of an axle from its normal position.
✓			e. Safety Devices	✓			b. Spring Assembly
✓			f. Saddle-Mounts	✓			c. Torque, Radius or Tracking Components
			<b>3. EXHAUST SYSTEM</b>				<b>9. FRAME</b>
✓			a. Exhaust system leaking forward of or directly below the driver/sleeper compartment.	✓			a. Frame Members
✓			b. Bus exhaust system leaking or discharging in violation of standard.	✓			b. Tire and Wheel Clearance
✓			c. Exhaust system likely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of the motor vehicle.	✓			c. Adjustable Axle Assemblies (Sliding Subframes)
			<b>4. FUEL SYSTEM</b>				
✓			a. Visible leak.	✓			
✓			b. Fuel tank filler cap missing.	✓			
✓			c. Fuel tank securely attached.	✓			
			<b>5. LIGHTING DEVICES</b>				
✓			All lighting devices and reflectors required by Part 393 shall be operable.	✓			
							<b>10. TIRES</b>
							a. Tires on any steering axle of a power unit.
							b. All other tires.
							<b>11. WHEELS AND RIMS</b>
							a. Lock or Side Ring
							b. Wheels and Rims
							c. Fasteners
							d. Welds
							<b>12. WINDSHIELD GLAZING</b>
							Requirements and exceptions as stated pertaining to any crack, discoloration or vision reducing matter (reference 393.60 for exceptions).
							<b>13. WINDSHIELD WIPERS</b>
							Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.
							<b>14. OTHER</b>
							List any other condition(s) which may prevent safe operation of this vehicle.

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, \_\_\_\_\_ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 393

# INVOICE

Invoice # IN-017544  
SO # SO-0025400  
Date 12/06/2017  
Writer Tim McCurdy  
Page 1 of 1

Cust acct# 012218 Cust PO#

Sold to: Armstrong Rentals, LLC

Ship to: Armstrong Rentals, LLC

Contact

Payment terms Due on the 10th

Ship via None Specified  
Prepay and Add

Contact phone

Work Order No. WO - WO-0003035

999\_WORKORDER

Condition

Part number	Description	Ord	Del	B/O	List Price	Unit price	Ext. price
<b>Labor</b>							
072_MU-155698-12XB10	15.5 CLUTCH	1	1	0			
<b>**Core exchange**</b>							
029_306VV	PILOT BRG W/VITON SEAL	1	1	0			
077_SCB200	2" HINGED CLUTCH BRAKE	1	1	0			
022_CLT008P	8" CLUTCH LUBE TUBE	1	1	0			
110_4305230	INSPECT COVER 2BOLT W/GROMMET	1	1	0			
<b>Shop supplies</b>							

Total merchandise

Total cores

Total labor

Tax amount

total