

COPY

INVOICE I 770
 Date 09/15/2015
 Date Open 04/03/2015

Page: 1 of 6

Ship To :

Written By Mark		Terms INHOUSE		Time 11:13:51	Customer Po # INHOUSE		Promised	Phone		Ship Via
Unit # 158		Plate #	Year 2005	Make INTERNATION	Model 9200	Mileage/Hrs 0/0.0		VIN 2HSCEAPR75C155919		Engine

Qty	Description	Price	Amount
	Complaint : DETAIL TRUCK Cause : Correction :		
1.000	LABWARRANTY DETAIL		
1.000	NEWS18988 CHROME BUMPER		
1.000	SUBLET ITEM 2 DETAIL		
	Complaint : CHECK AND REPAIR FOR ENGINE HAS CRACK ON SIDE OF HEAD. Cause : REMOVED VALVE COVER AND FOUND ROCKER HAD DAMAGED HEAD. Correction : REMOVED ENGINE AND DISASSEMBLED. REASSEMBLED ENGINE WITH OVERHAUL KIT AND NEW RECON CYLINDER HEAD. REINSALLED IN CHASSIS. FILLED WITH NEW OIL AND COOLANT. RAN AND CHECKED OPERATION. OK		
4.000	CUM3163075 APEX RED PAINT		
2.000	CUM3682076 O RING		
4.000	CUM3682826 SEAL,GROMMET		
1.000	MAS2712 RED THREADLOCKER		
1.000	MIA6306 PILOT BEARING		
1.000	CUM4965690 ACC DRIVE SUPPORT GASKET		
2.000	NFC49764 3" COARSE ROLOC PAD		

Parts..... 10788.73
 Labor..... 5719.32
 Sublet..... 1621.33
 Freight..... 64.94

TOTAL Continued

COPY

INVOICE I 770
Date 09/15/2015
Date Open 04/03/2015

Page: 2 of 6

Ship To :

Written By Mark		Terms INHOUSE		Time 11:13:51		Customer Po # INHOUSE		Promised		Phone		Ship Via			
Unit # 158		Plate #		Year 2005		Make INTERNATION		Model 9200		Mileage/Hrs 0/0.0		VIN 2HSCEAPR75C155919		Engine	

Qty	Description		Price	Amount
1.000	CUM3335548	THERMOSTAT SEAL		
1.000	CUM3058653	O RING		
1.000	CUM3678838	THREADED PLUG		
1.000	CUM3103015	GROMMET		
1.000	CUM4298220	STUD		
5.000	CUM4985492	LOCK NUT		
1.000	CUM3101268	FLANGE GASKET		
2.000	NFC40536	36 LINER CLAMP		
1.000	CUM3678756	O RING		
1.000	PETVL2443	1/2 SHUT OFF		
1.000	OMG35-H1904	3/4 HOSE TO 1/2 INCH PIPE		
2.000	NFC31150	BLUE BUTT CONNEC		
1.000	EAT127760	CLUTCH BRAKE		
1.000	NFC40630	TORQUE CLAMP		
1.000	MMM08880	BRAKLEEN		
2.000	NFC48413	4-1/8-4-7/16 SPR		
1.000	NFC40510	HOSE CLAMP #10		
10.00	NFC80352	RIVET WASHER 3/16IDX1/20D		

Parts..... 10788.73
Labor..... 5719.32
Sublet..... 1621.33

Freight..... 64.94

TOTAL Continued

COPY

INVOICE I 770
Date 09/15/2015
Date Open 04/03/2015

Page: 3 of 6

Ship To :

Written By Mark		Terms INHOUSE		Time 11:13:51		Customer Po # INHOUSE		Promised		Phone		Ship Via			
Unit # 158		Plate #		Year 2005		Make INTERNATION		Model 9200		Mileage/Hrs 0/0.0		VIN 2HSCEAPR75C155919		Engine	

Qty	Description		Price	Amount
3.000	NFC82165	10 X 1 PHIL SCREW		
7.000	NFC82163	10 X 3/4 PHIL SCREW		
1.000	CUM4088712	TEMP SENSOR		
1.000	FRTINCOMING	FREIGHT INCOMING FOR TEMP SENSOR.		
5.000	HTPORING	O RING		
1.000	CUM3682229	IDLER PULLEY		
1.000	CUM3678724	O RING		
1.000	CUM3081695	WATER OUTLET ORING		
1.000	CUM4352290	OVERHAUL KIT		
1.000	CUM4089910RX	PUMP, WATER		
1.000	CUM4331387RX	CYLINDER HEAD		
1.000	CUM186780	SEAL,THERMOSTAT		
1.000	CUM4088665PX	INJECTOR		
1.000	CUM4985562	GASKET GEAR HOUSING		
1.000	CUM4962722	RECTANGULAR STRIP SEAL		
1.000	CUM3104263	ISX FRONT MAIN SEAL		
2.000	CUM3684338	CONNECTION GASKET		
1.000	CUM4059172	O RING		

Parts..... 10788.73
Labor..... 5719.32
Sublet..... 1621.33
Freight..... 64.94

TOTAL Continued

COPY

INVOICE I 770
 Date 09/15/2015
 Date Open 04/03/2015

Page: 4 of 6

Ship To :

Written By Mark		Terms INHOUSE		Time 11:13:51		Customer Po # INHOUSE		Promised		Phone		Ship Via			
Unit # 158		Plate #		Year 2005		Make INTERNATION		Model 9200		Mileage/Hrs 0/0.0		VIN 2HSCEAPR75C155919		Engine	

Qty	Description	Price	Amount
1.000	CUM4965688 FLYWHEEL HOUSING GASKET		
1.000	CUM4376196 OIL COOLER GASKET		
2.000	CUM109080 O RING		
1.000	CUM4965569 REAR CRANK SEAL / ISX		
2.000	CUM212161 O RING		
2.000	CUM3049221 O RING		
1.000	SUBLET ITEM 3 CAMSHAFT POLISH		
1.000	CUM4088712 TEMP. SENSOR		
1.000	FRTINCOMING		
	FREIGHT INCOMING		
	TEMP. SENSOR		
1.000	EUCE6000A NUT 33MM		
1.000	SUR560 8" CONVEX MIRROR		
1.000	FLEWF2126 WATER FILTER		
1.000	FLELF9080 PAC,LF		
1.000	FLEFF2200 PAC,FF		
1.000	SPI107276S RTV SPICER SEALANT		
2.000	INT1664726C2 INSULATOR		

Parts..... 10788.73
 Labor..... 5719.32
 Sublet..... 1621.33
 Freight..... 64.94

TOTAL Continued

COPY

INVOICE I 770
 Date 09/15/2015
 Date Open 04/03/2015

Page: 5 of 6

Ship To :

Written By Mark		Terms INHOUSE		Time 11:13:51		Customer Po # INHOUSE		Promised		Phone		Ship Via			
Unit # 158		Plate #		Year 2005		Make INTERNATION		Model 9200		Mileage/Hrs 0/0.0		VIN 2HSCEAPR75C155919		Engine	

Qty	Description	Price	Amount
2.000	INT1664724C2 INSULATOR		
1.000	FRTINCOMING FREIGHT INCOMING INSULATORS		
1.000	SPI5-676X U JOINT		
17.00	CHVBULK DELO 400LE BULK		
1.000	FLEFS1000 FILTER		
1.000	CUM4935092 FUEL PUMP		
14.00	FLECC36077 RED EXTENDED LIFE RED 50/50 MIX		
Complaint : TRANSMISSION REPAIR. Cause : Correction :REPLACED SYNCRO IN REAR OF TRANS.			
1.000	NFC13141 2X1 FLAP WHEEL		
1.000	FULK2921 FRO GASKET KIT		
1.000	FULK3492 SYNCHRONIZER LARGE PIN		
1.000	ARMPA50 ARMOR SEMI GLOSS		
1.000	LUB105 LUBRIPLATE105 GR		

Parts..... 10788.73
 Labor..... 5719.32
 Sublet..... 1621.33
 Freight..... 64.94

TOTAL Continued

COPY

INVOICE	770
Date	09/15/2015
Date Open	04/03/2015

Page: 6 of 6

Ship To :

Written By Mark		Terms INHOUSE		Time 11:13:51		Customer Po # INHOUSE		Promised		Phone		Ship Via			
Unit # 158		Plate #		Year 2005		Make INTERNATION		Model 9200		Mileage/Hrs 0/0.0		VIN 2HSCEAPR75C155919		Engine	

Qty	Description	Price	Amount
25.00	CHV40WTRANSBULK DELO ESI 40W TRANSMISSION OIL		

Parts.....	10788.73
Labor.....	5719.32
Sublet.....	1621.33
Freight.....	64.94

TOTAL	18194.32
-------	----------