

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD

REPORT NUMBER 40687051	FLEET UNIT NUMBER White Pine MACK
DATE 19 Dec 2017	

MOTOR CARRIER OPERATOR Lyle Krumm	INSPECTOR'S NAME (PRINT OR TYPE) Lyle Krumm
ADDRESS 48711 212 nd ST	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 393.19 ☒ YES
CITY, STATE, ZIP CODE Elkton, MD 21926	VEHICLE IDENTIFICATION # AND COMPLETE: ☐ LIC. PLATE NO. ☒ VIN ☐ OTHER 1M1AE02K53W001217
VEHICLE TYPE ☒ TRACTOR ☐ TRAILER ☐ TRUCK ☐ BUS ☐ OTHER:	INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED

OK	NO	ITEM	OK	NO	ITEM	OK	NO	ITEM
		1. BRAKE SYSTEM			6. SAFE LOADING			10. TIRES
		a. Service Brakes			a. Part(s) of vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway.			a. Tires on any steering axle of a power unit.
		b. Parking Brake System			b. Protection against shifting cargo.			b. All other tires.
		c. Brake Drums or Rotors			c. Container securement devices on intermodal equipment.			c. Installation of speed-restricted tires unless specifically designated by motor carrier.
		d. Brake Hose						
		e. Brake Tubing						
		f. Low Pressure Warning Device						
		g. Tractor Protection Valve						
		h. Air Compressor						
		i. Electric Brakes						
		j. Hydraulic Brakes						
		k. Vacuum Systems						
		l. Antilock Brake System						
		m. Automatic Brake Adjusters						
		7. COUPLING DEVICES			7. STEERING MECHANISM			11. WHEELS AND RIMS
		a. Fifth Wheels			a. Steering Wheel Free Play			a. Lock or Side Ring
		b. Pintle Hooks			b. Steering Column			b. Wheels and Rims
		c. Drawbar/Towbar Eye			c. Front Axle Beam and All Steering Components Other Than Steering Column			c. Fasteners
		d. Drawbar/Towbar Tongue			d. Steering Gear Box			d. Welds
		e. Safety Devices			e. Pitman Arm			
		f. Saddle Mounts			f. Power Steering			
		8. EXHAUST SYSTEM			g. Ball and Socket Joints			
		a. Exhaust system leaking forward of or directly below the driver/sleeper compartment.			h. Tie Rods and Drag Links			
		b. Bus exhaust system leaking or discharging in violation of standard.			i. Nuts			
		c. Exhaust system likely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of the motor vehicle.			j. Steering System			
		9. FUEL SYSTEM			8. SUSPENSION			12. WINDSHIELD GLAZING
		a. Visible leak.			a. Any U-bolt(s), spring hanger(s), or other axle positioning part(s) cracked, broken, loose or missing resulting in shifting of an axle from its normal position.			Requirements and exceptions as stated pertaining to any crack, discoloration or vision reducing matter (reference 393.60 for exceptions).
		b. Fuel tank filler cap missing.			b. Spring Assembly			
		c. Fuel tank securely attached.			c. Torque, Radius or Tracking Components			
		10. LIGHTING DEVICES			9. FRAME			13. WINDSHIELD WIPERS
		All lighting devices and reflectors required by Part 393 shall be operable.			a. Frame Members			Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.
					b. Tire and Wheel Clearance			
					c. Adjustable Axle Assemblies (Sliding Subframes)			
								14. MOTORCACH SEATS
								Any passenger seat that is not securely fastened to the vehicle structure.
								15. OTHER
								List any other condition(s) which may prevent safe operation of this vehicle.

IF THE "OK" OR "NO" COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK ☐ NEEDS REPAIR ☐ NA IF IT/AS DO NOT APPLY. REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN