

Invoice

Date	Invoice #
10/28/2009	3171

P.O. No.	Terms	Project
	Due on receipt	

Quantity	Description	Rate	Amount
77.5	New fuel filter Replaced both oil pressure sending units Installed drive axel's and filled planetary's with oil Hrs. Labor Parts Out side Labor freight 6 Gallons 80/90 Gear Oil 10 Gallons AW32 Hydraulic Oil 8 Gallons anti-freeze 6 Gallons 15/40 Motor Oil Sales Tax		
		Total	\$12,291.96

Invoice

Date	Invoice #
10/28/2009	3171

P.O. No.	Terms	Project
	Due on receipt	

Quantity	Description	Rate	Amount
	<p>Engine Overhaul - 963 Cat. S/N #11Z00456</p> <p>Hours at time of repair 9458</p> <p>Steam clean engine compartment Remove 3304 engine and disassemble</p> <p>Found crankshaft BAD - Main bearings had spun in block Balance shaft bearings had spun in block</p> <p>Purchased a recondition block from Dean Machinery Purchased the following new Parts Crank shaft Two connecting rods Balance shafts Oil pump assembly Oil cooler Piston and liner kits Standard rod, main and thrust bearings Balance shaft bearings Cam shaft bearings Idler gear bearings Rear gear train bearings All new gaskets and seals Installed new thermostat Cylinder head rebuilt by Road Builders Two connection rods recondition Installed new fan belts Installed new water hoses Installed new heater water valves Install new radial seal air filter kit and filters New engine oil filter and oil Cleaned primary fuel screen and installed</p>		
		Total	