

UNIT# TW1196  
S&S TRUCKING INC

K09182

732936

## INVOICE

PAGE 1

SERVICE ADVISOR: 1776 CHRIS FELLERS

SERVICE ADVISOR: 1776 CHRIS FELLERS									
COLOR	YEAR	MAKE/MODEL		VIN		LICENSE	MILEAGE IN / OUT		TAG
	99	FREIGHTLINER FLD		1FUPDDZB8XDA13818			885476/885476		
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED		PO NO.	RATE	PAYMENT	INV. DATE	
27MAY99 IS			17:00 20NOV08			85.00	CASH	20NOV08	
R.O. OPENED		READY		OPTIONS: STK:TW1196 ENG:11922499 TRN:LB98039448					
				AXL:AVA98248465					
01:07 19NOV08		20:10 20NOV08							
LINE OPCODE TECH TYPE HOURS									
A CHECK FOR LOW BATTERY									
LIST						NET		TOTAL	

A CHECK FOR LOW BOOST AND LOW POWER.

100 ENGINE

1738 CPT

8 D2006-4285 T-BOLT CLAMP

1 DHT/FR2C CHARGE AIR COOLER

CORE CHARGE C

2 DN/P534816 AIR PRMYRS

3 WASHER WASHER

1 BOLT BOLT

2 NUT NUT

-1 DHT/FR2C CORE RETURN

PARTS:                      LABOR:                      OTHER:                      0.00                      TOTAL LINE A:                      1753.37

TEST DROVE WITH DRIVER, HOOKED UP LAPTOP AND MONITORED ENGINE AND SENSORS. UNIT HAD HARD TIME BUILDING BOOST PRESSURE. BROUGHT TRUCK INTO SHOP, PRESSURE TESTED AIR INTAKE SYSTEM, FOUND CAC CLAMPS LEAKING, TIGHTENED CLAMPS AND RECHECKED, FOUND CAC LEAKING BADLY. HAD HOLE IN RH SIDE OF TANK. GOT APPROVAL TO REPLACE. REMOVED AIR TUBING, REMOVED A/C CONDENSOR AWAY FROM COOLER. REMOVED COOLER AND INSTALLED NEW COOLER INTO POSITION, REINSTALLED A/C CONDENSOR BACK INTO POSITION. REINSTALLED ALL AIR TUBING AND USED ALL NEW CLAMPS PER CUSTOMER REQUEST. WHILE COOLER WAS OUT, BLEW RADIATOR OUT FOR ANY DEBREE, CLEANING OUT THE COOLER FINS. CUSTOMER TEST DROVE AND RECHECKED OPERATION, ALL OK AT THIS TIME.

\*\*\*\*\*

B\*\* EXPRESS LUBE, ROTELLA

PM1 EXPRESS LUBE

1776IFREE

1 DN/P553000 LUBE SPIN

1 DN/P551000 FF/WS SPIN

10 SLO/5070719 ROTELLA 15W40

(N/C)

(N/C)

(N/C)

(N/C)

PARTS:                      0.00                      LABOR:                      0.00                      OTHER:                      0.00                      TOTAL LINE B:                      0.00

\*\*\*\*\*

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
EPA FEE	
SUBLET AMOUNT	
SHOP FEES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	



3048

UNIT# TW1196  
S&S TRUCKING INC

K09182

732575

INVOICE

PAGE 1

SERVICE ADVISOR: 1709 MARK E BENSON

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG
	99	FREIGHTLINER FLD	1FUPDDZB8XDA13818		875000/875000	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT
27MAY99 IS			WAIT 05NOV08			CASH
R.O. OPENED	READY	OPTIONS: STK:TW1196 ENG:11922499 TRN:LB98039448				
		AXL:AVA98248465				
09:58 27OCT08	09:11 07NOV08					
LINE OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
A REPAIR AS PER ESTIMATE, SEE QUOTE						
100 ENGINE						
1704 CPT						
1724 CPT						

1 3406742RX HEAD,CYL 96N14  
CORE CHARGE C  
1 4089371 SET,UPPER ENGINE GASKET  
6 3070136 SEAL,O RING  
6 3070137 SEAL,O RING  
6 3070138 SEAL,O RING  
1 3804303 KIT,OIL PAN GASKET  
3 3068135 GASKET,ENG BRAKE HOUSING  
2 181213 ELBOW,PLAIN ADAPTER  
2 4973373 THERMOSTAT  
6 3803742 KIT,CYLINDER  
6 4058941 SEAL,O RING  
2 3803682 HARNESS,WIRING  
4 3054948 RING,LINER SEAL  
4 3M/7485 COARSE-3" ROLOC  
6 3M/7480 ROLOC 2" COARSE  
4 3M/8880 BRAKE CLEANER  
4 3803682 HARNESS,WIRING  
6 4058947 NOZZLE,PISTON COOLING  
2 3054948 RING,LINER SEAL  
2 PHM/1-52246 TERM WIRE INSULAT RI  
1 PHM/1-2256 TERM WIRE INSULAT NY  
12 3M/41977 15" TIE THIN  
2 PHM/1-1961 TERM WIRE SEALED CRI  
3 BOLT BOLT  
1 NUT NUT  
1 3202117 GASKET,CONNECTION  
1 BRZ/B9224-0411-FRB CLAMP  
3 3066311 GASKET,ROCKER LEVER COVER

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
EPA FEE	
SUBLET AMOUNT	
SHOP FEES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	



4 of 8

K09182

732575

UNIT# TW1196

S&amp;S TRUCKING INC

INVOICE

PAGE 2

SERVICE ADVISOR: 1709 MARK E BENSON

SERVICE ADVISOR: 1709 MARK E BENSON

COLOR	YEAR	MAKE/MODEL	VIN		LICENSE	MILEAGE IN / OUT		TAG
	99	FREIGHTLINER FLD	1FUPDDZB8XDA13818			875000/875000		
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	
27MAY99 IS			WAIT 05NOV08			CASH	07NOV08	
R.O. OPENED		READY	OPTIONS: STK:TW1196 ENG:11922499 TRN:LB98039448					
			AXL:AVA98248465					
09:58 27OCT08		09:11 07NOV08						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
1	GT/4175-2-1/2	RAD	HSE	4175 - 0026			
1	BRZ/CT-300-L-SS	CLAMP	2 1/4 - 3 1/8				
1	DN/P553000	LUBE	SPIN				
1	DN/P551000	FF/WS	SPIN				
6	3M/7480	ROLOC	2" COARSE				
6	OWI/AAA003	ANTIFREEZE	GREEN				
11	MBL/988738	DELVAC	1300 15W40 BULK				
2	PHM/1-52116	TERM WIRE	INSULAT RI				
-1	3406742RX	CORE	RETURN				

PARTS:                      LABOR:                      OTHER:                      0.00                      TOTAL LINE A:                      7956.92

TALK WITH CUSTOMER ON ENGINE REPAIRS,MADE UP ESTIMATE OF REPAIRS,CUSTOMER SUPPLIED NEW MAIN- ROD BEARINGS,ALSO ADVISED TO REUSE TWO HEADS & REPLACE ONLY ONE CYL HEAD. DRAIN COOLANT & ENGINE OIL,DISASSEMBLE ENGINE & SAVE BACK TWO HEADS FOR REUSE,CLEAN ENGINE BLOCK & INSPECT COUNTERBORE,REMOVE MAIN BRGS, INSTALL NEW MAIN BRG SET,TORQUE TO SPECS INSTALL NEW LINER SHIMS,CLEAN UP NEW LINERS AND INSTALL,CHK LINER PROTRUSION,OK.INSTALL RODS ON NEW PISTONS,NEW RING SETS,INSTALL PISTONS WITH NEW ROD BRGS,TORQUE TO SPECS,INSTALL OIL PAN WITH NEW GASKETS & SEALS,INSTALL ONE REMAN HEAD AND REUSE TWO THAT WERE TAKEN OFF,TORQUE ALL HEAD BOLTS TO SPECS,CLEAN & REUSE INJECTORS WITH NEW O/RINGS,SET ENGINE OVERHEAD TO SPECS, INSPECT ENGINE BRAKES,OK AT THIS TIME,INSTALL AND SET TO SPECS,REASSEMBLE ENGINE,CHANGE OIL FILTER,NEW OIL,START AND RUN ENGINE TO CHECK OPERATION.

\*\*\*\*\*

B\*\* RESEAL CAM FOLLOWERS WITH NEW GASKETS

100 ENGINE

- 1704 CPT
- 3 3068473 GASKET,CAM FOL HOUSING
- 1 3076226 GASKET,AIR COMPRESSOR
- 1 3076225 GASKET,ACC DRIVE SUPPORT
- 1 4026171 GASKET,FUEL PUMP
- 1 3046200 SPIDER,JAW COUPLING
- 1 3800616 KIT,SEAL

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
EPA FEE	
SUBLET AMOUNT	
SHOP FEES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	





6 of 8

K09182

732575

UNIT# TW1196

INVOICE

S&S TRUCKING INC  
100 N. WASHINGTON ST.

PAGE 4

SERVICE ADVISOR: 1709 MARK E BENSON

SERVICE ADVISOR: 1709 MARK E BENSON

COLOR	YEAR	MAKE/MODEL	VIN		LICENSE	MILEAGE IN / OUT		TAG
	99	FREIGHTLINER FLD	1FUPDDZB8XDA13818			875000/875000		
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	
27MAY99 IS			WAIT 05NOV08		85.00	CASH	07NOV08	
R.O. OPENED		READY		OPTIONS: STK:TW1196 ENG:11922499 TRN:LB98039448				
09:58 27OCT08		09:11 07NOV08		AXL:AVA98248465				
LINE OPCODE TECH TYPE HOURS					LIST	NET	TOTAL	

We are truck people, specializing in nothing but trucks. You depend on trucks; you can depend on us. If you're not satisfied with the service you receive please see our GM.

Dealer Code :

dispute	DESCRIPTION	TOTALS
pay for	LABOR AMOUNT	
of any	PARTS AMOUNT	
binding	EPA FEE	
merican	SUBLET AMOUNT	
itation	SHOP FEES	
jury or	TOTAL CHARGES	
recover	LESS INSURANCE	
mages,	SALES TAX	
	PLEASE PAY THIS AMOUNT	10093.30

7 of 8

CUSTOMER #: K09182  
UNIT# TW1196

735911C

S&S TRUCKING INC

INVOICE

PAGE 1

SERVICE ADVISOR: 1767 GARY SEIM

COLOR	YEAR	MAKE/MODEL	VIN		LICENSE	MILEAGE IN / OUT		TAG
	99	FREIGHTLINER FLD	1FUPDDZB8XDA13818			927658/927658		
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	
27MAY99 DD			17:00 14JUN09		85.00	CASH	14JUN09	
R.O. OPENED		READY		OPTIONS: STK:TW1196 ENG:11922499 TRN:LB98039448				
14:33 12JUN09		13:58 14JUN09		AXL:AVA98248465				

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
A REPAIR FOR OIL LEAK AT ACC DRIVE WE REPLACED RO732575 OCT 27 2008							
100 ENGINE							
		1724	CP				
		1767	CP				
		1776	CP				

1 3M/8880 BRAKE CLEANER  
1 3078307RX DRIVE,ACC 94N14  
CORE CHARGE C  
1 110855 GASKET,FUEL PUMP  
2 3103015 SEAL,GROMMET  
1 3046200 SPIDER,JAW COUPLING  
1 4026171 GASKET,FUEL PUMP  
1 3076226 GASKET,AIR COMPRESSOR  
1 3076225 GASKET,ACC DRIVE SUPPORT  
1 BW/236577N GASKET  
1 GT/17436E EXTENDED LIFE V-BELT  
4 BOLT BOLT  
4 WASHER WASHER  
-1 3078307RX CORE RETURN  
4 BOLT BOLT

PARTS:                      LABOR:                      OTHER:                      0.00                      TOTAL LINE A:                      1468.40

DRAIN COOLANT REMOVE FUEL PUMP, AIR COMPRESSOR MOVE A/C COMPRESSOR  
OUT OF WAY REMOVE ACCE DRIVE PULLEY FOUND ACC DRIVE SHAFT CRACKED  
ADVISE CUSRIMER TO GET AUTH TO REPLACE. REMOVE ACC DRIVE CLEAN SEALING  
SURFACES. INSTALL NEW ACC DRIVE. REINSTALL PULLEYS, AIR COMPRESSOR,  
FULE PUMP AND BELTS REPOSITION A/C COMPRESSOR AND TIGHTEN. REFILL WITH  
COOLANT. RUN ENGINE TO CHECK FOR LEAKS STEAM CLEAN.

\*\*\*\*\*

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
EPA FEE	
SUBLET AMOUNT	
SHOP FEES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER #: K09182  
UNIT# TW1196

735911C

## INVOICE

S&S TRUCKING INC  
100 N. W. 100th Ave.

PAGE 2

SERVICE ADVISOR: 1767 GARY SEIM

COLOR	YEAR	MAKE/MODEL	VIN		LICENSE	MILEAGE IN / OUT		TAG
	99	FREIGHTLINER FLD	1FUPDDZB8XDA13818			927658/927658		
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	
27MAY99 DD			17:00 14JUN09			CASH	14JUN09	
R.O. OPENED		READY		OPTIONS: STK:TW1196 ENG:11922499 TRN:LB98039448				
14:33 12JUN09		13:58 14JUN09		AXL:AVA98248465				
LINE OPCODE TECH TYPE HOURS					LIST	NET	TOTAL	

You have choices when it comes to truck parts and service. When choosing a shop, don't choose short-term savings over technical expertise. Today's engines leave little margin for error and what you save today can cost more in missed maintenance tomorrow.  
Dealer Code :

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
EPA FEE	
SUBLET AMOUNT	
SHOP FEES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	1536.24