

5/1/2018

VEHICLE HISTORY DOT

DB 7131

1

Vehicle Truck #38
Year/Make 2009 DODGE 1 TON BUCKET 4V4
Vin # 3D6WD76L59G548152

License 45A3ZU
Service Interval 3000 Miles
Location Puxico, Mo

Tire Size
front 225 70R195
rear 225 70R195

Date	Mileage	Code	Maintenance	Service by
8/24/2009		15 Hydraulic/Digger System	Replaced bushings and drive sheave spacer, replaced belts	terex
9/21/2009		15 Hydraulic/Digger System	Dielectric and structural testing	Amec
10/13/2009		20 Miscellaneous	bug shield	cashs
11/2/2009		15 Hydraulic/Digger System	pm boom inspection	terex
11/27/2009		20 Miscellaneous	tail pipe extension	harolds
12/16/2009		13 Tires	6 new tires	simmons
12/26/2009	3833	14 Regular Maintenance	oil, oil filter, air filter	harolds
1/4/2010		13 Tires	4 new tires	simmons
1/8/2010	4666	13 Tires	mounted new tire	harolds
1/19/2010		16 Inspections/Testing	Dot inspection.	briver
1/21/2010		20 Miscellaneous	install running boards	cashs
1/30/2010	7260	14 Regular Maintenance	oil, oil filter, air filter	harolds
2/27/2010		20 Miscellaneous	new winch and bumper	terex
3/27/2010	10245	14 Regular Maintenance	oil, oil filter, air filter	harolds
3/31/2010		13 Tires	mounted 6 tires	simmons
4/30/2010	13995	14 Regular Maintenance	oil, oil filter, air filter	harolds
6/14/2010		15 Hydraulic/Digger System	pm boom inspection	terex
7/31/2010	20048	14 Regular Maintenance	oil, oil filter, air filter	harolds

Vehicle	<u>Truck #38</u>	License	<u>45A3ZU</u>	Tire Size
Year/Make	<u>2009 DODGE 1 TON BUCKET 4V4</u>	Service Interval	<u>3000 Miles</u>	front <u>225 70R195</u>
Vin #	<u>3D6WD76L59G548152</u>	Location	<u>Puxico, Mo</u>	rear <u>225 70R195</u>

9/10/2010	22159	18 Electrical System	2 batteries	harolds
9/25/2010	23479	14 Regular Maintenance	oil, oil filter, air filter	harolds
9/29/2010		13 Tires	tire change	puxico farm tire
9/30/2010		16 Inspections/Testing	Dielectric and strucural testing	Amec
10/30/2010	25357	18 Electrical System	tail light replaced	harolds
12/3/2010		15 Hydraulic/Digger System	pm boom, replaced hyd filter	terex
12/15/2010		13 Tires	6 new tires	simmons
12/21/2010	27117	20 Miscellaneous	upper radiator hose	harolds
12/24/2010	27533	14 Regular Maintenance	oil, oil filter, air filter	harolds
1/21/2011		12 Brakes	installed trailer brake controller	terex
1/29/2011	30833	14 Regular Maintenance	oil, oil filter, air filter	harolds
2/9/2011		14 Regular Maintenance	wiper blades	auto tire
4/12/2011		17 Windshield/Mirrors	new windshield	brownings
4/24/2011		12 Brakes	replaced caliper and pins	cashes
4/28/2011	35966	18 Electrical System	rear signal light	harolds
5/20/2011		15 Hydraulic/Digger System	pm boom, changed filter	terex
5/30/2011	38980	14 Regular Maintenance	oil, oil filter, air filter	harolds
7/12/2011		13 Tires	flat tire	puxico farm tire
7/30/2011	42912	14 Regular Maintenance	oil, oil filter, air filter	harolds
8/9/2011		15 Hydraulic/Digger System	repaired winch	terex

Vehicle	<u>Truck #38</u>	License	<u>45A3ZU</u>	Tire Size
Year/Make	<u>2009 DODGE 1 TON BUCKET 4V4</u>	Service Interval	<u>3000 Miles</u>	front <u>225 70R195</u>
Vin #	<u>3D6WD76L59G548152</u>	Location	<u>Puxico, Mo</u>	rear <u>225 70R195</u>

8/29/2011		13 Tires	tire change	puxico farm tire
9/24/2011	47463	20 Miscellaneous	idler pulley	harolds
9/24/2011	47443	14 Regular Maintenance	oil, oil filter, air filter	harolds
10/4/2011		15 Hydraulic/Digger System	repaired winch	terex
11/22/2011		13 Tires	6 new tires	simmons
11/23/2011	49292	15 Hydraulic/Digger System	pm boom, changed filter	terex
11/30/2011	55641	14 Regular Maintenance	oil, oil filter, air filter	harolds
12/27/2011	51726	18 Electrical System	2 batteries	harolds
1/28/2012	53828	14 Regular Maintenance	oil, oil filter, air filter	harolds
2/15/2012	54469	20 Miscellaneous	cleaned and repaired sensor on filter, installed air to air boot	briver
3/7/2012	55953	12 Brakes	new front brakes	harolds
3/7/2012	55953	18 Electrical System	wire up spotlight (drivers side)	harolds
3/8/2012	55953	12 Brakes	rear brakes and rotors	harolds
3/31/2012	59602	14 Regular Maintenance	oil, oil filter, air filter	harolds
4/3/2012	59602	13 Tires	flat tire	harolds
5/3/2012		15 Hydraulic/Digger System	pm boom	terex
5/26/2012	60858	18 Electrical System	replaced 2 parking lights	harolds
6/30/2012	62863	14 Regular Maintenance	oil, oil filter, air filter	harolds
7/28/2012	64022	13 Tires	flat repair right front tire	harolds

5/1/2018

VEHICLE HISTORY DOT

4

Vehicle Truck #38
Year/Make 2009 DODGE 1 TON BUCKET 4V4
Vin # 3D6WD76L59G548152

License 45A3ZU
Service Interval 3000 Miles
Location Puxico, Mo

Tire Size
front 225 70R195
rear 225 70R195

8/31/2012	65339	14 Regular Maintenance	oil, oil filter, air filter	harolds
9/21/2012		20 Miscellaneous	replaced pump drive belt	terex
10/10/2012	67067	20 Miscellaneous	radiator dirty/cleaned	terex
10/27/2012	68847	14 Regular Maintenance	oil, oil filter, air filter	harolds
11/8/2012		12 Brakes	hydro boost on brakes, brake fluid, flush,bleed	harolds
11/12/2012		15 Hydraulic/Digger System	pm boom,filter,oil10 mic,synthetic replc,inspection	terex
12/3/2012		14 Regular Maintenance	antifreeze,o ring,cooling fan,egr cooling	black river truck
12/31/2012	69874	13 Tires	6 new tires	simmons
1/11/2013		20 Regular Maintenance	replaced hydraulic pump and clutch	Foley's
1/11/2013		18 Electrical System	connect battery ground	Foley's
1/21/2013		16 Inspections/Testing	Dot inspection.	black river truck
1/21/2013		20 Regular Maintenance	replaced broken belt/idler/pump bracket	Foley's
1/26/2013	70915	14 Regular Maintenance	oil, oil filter, air filter	harolds
3/30/2013	75645	14 Regular Maintenance	oil, oil filter, air filter	harolds
5/6/2013	76599	15 Hydraulic/Digger System	pm boom inspection	altec
6/10/2013		15 Hydraulic/Digger System	installed new lug on rope	altec
6/29/2013	78868	14 Regular Maintenance	oil, oil filter, air filter	harolds
7/16/2013	79411	15 Hydraulic/Digger System	advised sprvisr dodge will have repair cruise control and reset p t o throttle	altec
9/23/2013		16 Inspections/Testing	dielectric & structural	Amec

5/1/2018

VEHICLE HISTORY DOT

Vehicle Truck #38
Year/Make 2009 DODGE 1 TON BUCKET 4V4
Vin # 3D6WD76L59G548152

License 45A3ZU
Service Interval 3000 Miles
Location Puxico, Mo

Tire Size
front 225 70R195
rear 225 70R195

10/29/2013		14 Regular Maintenance	oil,oil filter,fuel filter,antifreeze,wiper solvent,brake fl	barker noe
11/5/2013	83687	15 Hydraulic/Digger System	pm boom inspection	altec
11/29/2013	83938	13 Tires	6 new tires,dismount/mount,drill/stud tires	simmons
12/30/2013		18 Electrical System	2 batteries	barker noe
1/31/2014		15 Hydraulic/Digger System	damaged latch on bin door(will return/complete job)	altec
2/1/2014		16 Inspections/Testing	Dot inspection.	black river truck
2/19/2014		16 Inspections/Testing	dielectric and structural testing	amec
2/20/2014		15 Hydraulic/Digger System	repaired wiring to worn switch of spotlight	altec
3/15/2014		14 Regular Maintenance	oil, oil filter, air filter	barker noe
4/19/2014		13 Tires	9 wheel studs and lug nuts	barker noe
4/21/2014		14 Regular Maintenance	2 wiper blades	barker noe
6/14/2014		14 Regular Maintenance	oil, oil filter, air filter	barker noe
6/14/2014		14 Regular Maintenance	brake fluid/wiper solvent	barker noe
7/10/2014	92224	15 Hydraulic/Digger System	scheduled maintenance/boom inspection	altec
8/30/2014	94614	14 Regular Maintenance	oil, oil filter, air filter	harolds
10/31/2014	97007	18 Electrical System	battery	harolds
10/31/2014	97007	13 Tires	flat	harolds
11/10/2014		18 Electrical System	new battery on driver side	harolds

5/1/2018

VEHICLE HISTORY DOT

6

Vehicle	<u>Truck #38</u>	License	<u>45A3ZU</u>	Tire Size
Year/Make	<u>2009 DODGE 1 TON BUCKET 4V4</u>	Service Interval	<u>3000 Miles</u>	front <u>225 70R195</u>
Vin #	<u>3D6WD76L59G548152</u>	Location	<u>Puxico, Mo</u>	rear <u>225 70R195</u>

11/19/2014	97795	20 Miscellaneous	replace seat cushions,bottom/rear cover	cashs
11/30/2014	98288	14 Regular Maintenance	oil, oil filter, air filter	harolds
1/31/2015	99901	13 Tires	flat	harolds
2/28/2015	102417	14 Regular Maintenance	oil, oil filter, air filter	harolds
3/31/2015	103701	12 Brakes	front/rear brake pads, bracket for rr calipher	harolds
3/31/2015	103701	13 Tires	2 studs/2 lug nuts	harolds
4/21/2015		18 Electrical System	tail light replaced	harolds
4/25/2015	105504	14 Regular Maintenance	oil, oil filter, air filter	harolds
5/28/2015		15 Hydraulic/Digger System	scheduled maintenance/boom inspection	altec
5/30/2015	108209	18 Electrical System	drivers side spot light	harolds
6/27/2015	109401	14 Regular Maintenance	oil, oil filter, air filter	harolds
7/25/2015	112769	14 Regular Maintenance	oil, oil filter, air filter	harolds
8/18/2015		14 Regular Maintenance	air filter/fuel filter	harolds
8/18/2015		13 Tires	tire change	harolds
8/20/2015	114524	14 Regular Maintenance	1 fuel filter	cashs
8/27/2015		16 inspections/testing	d&s test	amec
8/29/2015		14 Regular Maintenance	oil, oil filter, air filter	harolds
9/26/2015	116826	14 Regular Maintenance	oil, oil filter, air filter	harolds
11/4/2015	119339	13 Tires	6 new tires	simmons
11/29/2015	120417	14 Regular Maintenance	oil, oil filter, air filter	harolds
2/26/2016		15 Hydraulic/Digger System	installed new single hand controller placard	altec

5/1/2018

VEHICLE HISTORY DOT

7

Vehicle Truck #38
Year/Make 2009 DODGE 1 TON BUCKET 4V4
Vin # 3D6WD76L59G548152

License 45A3ZU
Service Interval 3000 Miles
Location Puxico, Mo

Tire Size
front 225 70R195
rear 225 70R195

2/27/2016	124246	14 Regular Maintenance	oil, oil filter, air filter	harolds
4/30/2016	127505	14 Regular Maintenance	oil, oil filter, air filter	harolds
5/12/2016		11 body repairs	drive belt,tensoner,power steering cap	harolds
5/25/2016	128536	13 Tires	9 wheel studs,lud nuts	harolds
6/25/2016	130505	14 Regular Maintenance	oil, oil filter, air filter	harolds
8/19/2016		14 Regular Maintenance	fuel filter	cashs
8/22/2016	134552	15 Hydraulic/Digger System	pm inspection	altec
8/23/2016		16 Inspections/Testing	dielectric/structural	Amec
9/17/2016	135991	14 Regular Maintenance	90 wt oil	harolds
9/30/2016	136428	14 Regular Maintenance	oil, oil filter, air filter	harolds
10/10/2016		15 Hydraulic/Digger System	repaired hydraulic leak at outrigger controls	altec
11/9/2016	138253	20 Miscellaneous	replaced assy	harry blackwell
11/22/2016		18 Electrical System	rreplaced both batteries	harry blackwell
12/5/2016		13 Tires	6 new tires	simmons
12/31/2016	140064	14 Regular Maintenance	oil, oil filter, air filter	harolds
1/19/2017	141510	14 Regular Maintenance	2 wiper blades	harolds
2/1/2017		16 Inspections/Testing	dielectric & structural	Amec
2/7/2017	142417	15 Hydraulic/Digger System	correction 2/8/17 pm inspection	altec
2/25/2017	143181	14 Regular Maintenance	oil, oil filter, air filter	harolds
3/28/2017	144037	12 Brakes	brake booster leaking,replaced	cashs

5/1/2018

VEHICLE HISTORY DOT

8

Vehicle Truck #38
Year/Make 2009 DODGE 1 TON BUCKET 4V4
Vin # 3D6WD76L59G548152

License 45A3ZU
Service Interval 3000 Miles
Location Puxico, Mo

Tire Size
front 225 70R195
rear 225 70R195

4/8/2017	144860	12 Brakes	brakes(front)guide pin kit/caliber bracket	barker noe
4/8/2017	144860	14 Regular Maintenance	oil, oil filter,air filter,grease,wiper solvent	barker noe
4/14/2017		13 Tires	4 wheel studs/lug nuts	barker noe
7/1/2017	150803	14 Regular Maintenance	oil, oil filter,air filter,grease,wiper solvent	barker noe
7/15/2017		20 miscellaneous	clean boom/floor for grease and oil	barker noe
7/27/2017		13 Tires	tire repair	barker noe
8/8/2017		20 miscellaneous	2 bags of oil dry	barker noe