



## Service Report for Workorder 0522899 Segment 06 Service Report ID 'A'

Dealer Code	E075	Customer Name:	USED GENERAL RENTAL FLEET		
Date of Repair	2016/08/04	Employee ID:	4326	Equipment Location:	Aberdeen BMC
Make	AA	Model:	420E	Serial Number:	0PRA00842
Hours:	3683	Miles:		Kilometers:	

Instructions Replace hour meter

Part#		Part Name		Qty		Desc Code	
Responsible							
Group#		Group Name		Inoperable?		Desc Comment	

**Related Serial Numbers**

Engine Model	/	Serial #	
Transmission Model		Serial #	
Torque Converter Model		Serial #	
OEM Make/Model		Vehicle Config	
		Delivery Date	0

**Customers Complaint** Hour meter was incorrect.**Cause of Failure**

Meter failed.

**Resultant Damage**

Meter needed to be replaced.

**Repair**

Removed failed meter. Checked hour meter wires on harness, connectors were tight. Installed new hour meter and put an hour sticker by new meter with correct machine hours on it.

Servicemans Name: STUDEMANN

Printed by XUPE074323 on Fri Nov 10 2017 13:13:32 GMT-0600 (Central Standard Time)

\*\*\*End of Service Report \*\*\*