

REPAIR ORDER

PWK

Repair Order Date: 9/7/2018

KS

Unit: PWK4483

Department: Division: Registered Weight: 56,000
Vehicle Model: 7400 Vehicle Make: Navistar

Date / Time (In-Out)	Status	Repair Class	Serial Number	License	Meter Reading(s)
Date In: 9/7/2018	OPEN	Scheduled	1HTWHAAT78J050405		132,912 Miles
Date Out: 9/14/2018					
Time In: 7:34 AM	Location	Repair Stage	Mechanic/Vendor		
Time Out: 1:30 PM		In Progress			

Year: 2008

Mechanic Instructions / Complaints

Parts

VMRS Code	Part Number	Description	Failure Code	Qty	Cost Per	Cost	Tax	Total Cost
013-000-000 Brakes	66864B	Brake Drum 16.5 X7.0		4.00				
013-000-000 Brakes	RK8304707Q	BRAKE SHOE KIT REAR		4.00				
013-000-000 Brakes	2589468C91	Hub		1.00				
013-000-000 Brakes	3585986C1	Exciter Ring		1.00				
013-000-000 Brakes	GC3030LCW	LONG STROKE BRAKE CHAMBER WITH WELDED CLEVIS 2.25"		4.00				
013-000-000 Brakes	2210V7536	S-Cam		2.00				
013-000-000 Brakes	2210W7537	S-Cam		2.00				
013-000-000 Brakes	40010141	HALDEX SLACK ADJUSTER		4.00				
013-000-000 Brakes	A13236Q2123	Brake Backing Plate		4.00				
013-000-000 Brakes	580	Bearing		1.00				
013-000-000 Brakes	594A	Wheel Bearing		1.00				
013-000-000 Brakes	*370003A	SEAL		4.00				
013-000-000 Brakes	KIT8042	S-Cam Bushings		2.00				
013-000-000 Brakes	Shop Supplies	Misc Shop Supplies		2.00				
032-000-000 Cranking System	Shop Supplies	Misc Shop Supplies		1.00				
032-002-000 Starter	6907N	39 mt Starter		1.00				
054-000-000 Horns & Mountings & Reverse Signal Alarms	BA-97	Backup Alarm		1.00				
054-000-000 Horns & Mountings & Reverse Signal Alarms	3791174C2	Air Horn		1.00				

\$3,734.80

REPAIR ORDER

Labor										
VMRS Code Work Accomplished	Failure Code	Mechanic / Vendor Method	Date	Time In	Time Out	Hours	Rate	Cost	Tax	Total Cost
013-000-000 Brakes		17071 (Swardstrom, Todd) STRAIGHT TIME	09/10/18	12:00 PM	02:30 PM					
013-000-000 Brakes		17071 (Swardstrom, Todd) STRAIGHT TIME	09/11/18	07:00 AM	11:00 AM					
013-000-000 Brakes		17071 (Swardstrom, Todd) STRAIGHT TIME	09/11/18	12:00 PM	02:30 PM					
013-000-000 Brakes		17071 (Swardstrom, Todd) STRAIGHT TIME	09/10/18	08:45 AM	11:03 AM					
013-000-000 Brakes		3093 (McCully, Doug) STRAIGHT TIME	09/10/18	11:30 AM	02:00 PM					
013-000-000 Brakes		3093 (McCully, Doug) STRAIGHT TIME	09/10/18	08:30 AM	11:00 AM					
013-000-000 Brakes		3093 (McCully, Doug) STRAIGHT TIME	09/11/18	06:30 AM	11:00 AM					
013-000-000 Brakes		3093 (McCully, Doug) STRAIGHT TIME	09/11/18	12:00 PM	02:30 PM					
013-000-000 Brakes		3093 (McCully, Doug) STRAIGHT TIME	09/12/18	06:30 AM	11:00 AM					
013-000-000 Brakes		3093 (McCully, Doug) STRAIGHT TIME	09/12/18	12:00 PM	02:30 PM					
013-000-000 Brakes		3093 (McCully, Doug) STRAIGHT TIME	09/13/18	07:00 AM	11:00 AM					
013-000-000 Brakes		3093 (McCully, Doug) STRAIGHT TIME	09/13/18	12:00 PM	02:30 PM					
013-000-000 Brakes		3093 (McCully, Doug) STRAIGHT TIME	09/14/18	07:00 AM	10:00 AM					
017-000-000 Tires, Tubes, Liners & Valves		3093 (McCully, Doug) STRAIGHT TIME	09/14/18	12:00 PM	01:30 PM					
032-000-000 Cranking System		3093 (McCully, Doug) STRAIGHT TIME	09/10/18	06:30 AM	08:30 AM					
032-000-000 Cranking System		3093 (McCully, Doug) STRAIGHT TIME	09/07/18	10:30 AM	11:00 AM					
054-000-000 Horns & Mountings & Reverse Signal Alarms 03 (Replace with New)		3093 (McCully, Doug) STRAIGHT TIME	09/14/18	10:00 AM	11:00 AM					
										\$3,808.00

REPAIR ORDER

Repair Order Date: 9/7/2018

Work Performed

VMRS System	Repair Reason	Work Description
032 Cranking System	Driver Report	CONCERN ; WILL NOT START CAUSE ; STARTER TESTED BAD CORRECTION ; REPLACE STARTER WITH NEW DONE 9/11/2018
013 Brakes	Inspection	CONCERN ; REAR BRAKES WORE TO LIMITS CAUSE ; NORMAL WARE CORRECTION ; REPLACED ALL REAR BRAKE S-CAMS ,SLACK ADJUSTERS, BRAKE DRUMS ,BRAKE SHOES ,HARD WARE AND BACKING PLATES.
054 Horns & Mountings & Reverse Signal Alarms	Inspection	CONCERN ; AIR HORN INOP CAUSE ; HORNE BROKE CORRECTION ; REPLACE HORNE WITH NEW DONE 09/14/2018 CONCERN ; BACK UP ALARM INOP CAUSE ; HORNE BAD CORRECTION ; REPLACED WITH NEW DONE 09/14/2018
017 Tires, Tubes, Liners & Valves	Inspection	CONCERN ; FRONT TIRES WORE TO WEARBAR CAUSE ; NORMAL WEAR CORRECTION ; REPLACE FRONT TIRES WITH NEW DONE 09/14/2018

Mechanic Signature: _____

Supervisor Signature: _____

Parts Cost

Parts Tax

Labor Cost

Labor Tax

Grand Total **\$7,542.80**