

INVOICE

OF 7139

Work Completed : 09/28/2013

Date: 03/04/2019

2010 International - 7500 -

Lic # : BJ309053

Odometer In : 47447

VIN# : BJ309053

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
KIT, EGR COOLER ASSY 330MM 7090595C91	1.00			LOOSING COOLING-EMISSIONS WARRANTY locked up „defective egr cooler ehhaust side with progressive damage #2 5 rods hit liners, replaced all rods, installed works kit replaced exhaust egr cooler emmisions warrenty. CUSTOMER:CEC	1,825.20
ROLOC DISC 05528	4.00				
CLEANER,BRAKE NON-CHLR NAL4620	4.00			AUTHORIZATION NO.:	
BOLT BEARING CAP 1883597C1	14.00			CASE FILE #	
KIT ENGINE OVERHAUL 570 1889280C97	1.00			DELIVERY DATE :5/27/2010	
SHELL ROTELLA 15W40 BULK,(PER GALLON) 15W40 ROT, BULK	8.00			DISTANCE TRAVELED:47447	
COOLANT,RED 50/50 ELC SHELLZONE ZSH9404200001B	8.00			FAILURE DATE:09/12/2013	
MEDIUM TIE 7" 81104	10.00			REPAIR COMPLETED:	
TIE,15" ZIP 81110	4.00			COMPONENT CODE:	
O RING 3543728C1	1.00			COMPONENT SERIAL NO:	
CLAMP 1040	3.00			CONDITION: COOLANT OUT EXHAUST CAUSE: DEFECTIVE EGR COOLER	
NYLON TIE, 14" MEDIUM 81108	12.00			CORRECTION: EXHAUST EGR COOLER ,#2 5 RODS REPLACED INSTALLED WORKS KIT	
ROD,CONNECTING 1873875C95	6.00			GROUP:12000	
ROD,CONNECTING <CORE> 1873875C95	1.00			NOUN:892	
PARTS WARRANTY PARTS HANDLING	1.00			CAUSE CODE:K	
PARTS WARRANTY PARTS HANDLING	-1.00			WARR:01	
WARRANTY OTHER/OUTSIDED CHARGES OTHER CHARGES	1.00			TP:P	
				PAD:100	
				OPERATION-- NUMBER:M12-1192H-20 HOURS:21.00	
				NUMBER:M12-6892H HOURS:2.1	
				NUMBER:M12-6892H-1	
				.3 HOURS:	
				WARRANTY LABOR	-132.60

INVOICE

DI-7139

2011 International - WorkStar Series - 7500 - INTERNA
Odometer In

Part Description / Number	Qty	Sale	Ext	Labor Description
ROLOC DISC 05528	4.00			DRIVESHAFT IS OUT
ABRASIVE DISC, 2" ALUM 07481	6.00			CHECK FOR BACKFIRES BAD
1" WIRE WHEEL 60002	1.00			FOUND CAMSHAFT ASSEMBLY HAD FLATTENED A LOB
FITTING,FUEL 3591094C1	1.00			REMOVED FRONT ENGINE COVER AND INTAKE TO REM
SLEEVE 3/8 1812348C1	3.00			CAMSHAFT FOR INSPECTIION.REPLACED CAM SHAFT ,
CLEANER,BRAKE NON-CHLR NAL4620	1.00			ALL LIFTERS, 1 PUSH ROD, OIL PUMP, REPLACED ALL U
CLAMP 279025R91	1.00			GASKETS & FRONT COVER GASKETS. ALSO FOUND EC
HOSE COOLANT TUBE EGR 7094705C1	3.00			VALVE LEAKING, REPLACED VALVE. CHANGED ENGINE
HOSE 7094706C1	1.00			FILTER. REFILLED COOLANT. RAN REGEN & ROAD TES
CLAMP 1873585C1	8.00			OK.
BOLT M16 X 2 X 65 MM 1820287C2	1.00			
BOLT M20 X 2.5 X 70 MM 40055R1	1.00			
KIT FRONT COVER FRONT HLF SEAL 1842663C93	1.00			
PACKAGE FRONT OIL SEAL 530/570 1833096C95	1.00			
SEAL (O-RING) 1844447C1	2.00			
GASKET 1873906C1	1.00			
EGR GASKETS 1875808C1	1.00			
KIT, CYLINDER HEAD GASKET I-32 1889247C96	1.00			
KIT,CAMSHAFT & TAPPETS I-326 1894239C92	1.00	1,		
ROD,PUSH 1854756C1	1.00			
SHIPPING AND HANDLING FREIGHT	1.00			

INVOICE

320108

INVOICE

Date: 02/23/2017

2011 International - WorkStar Series - 7500 - INTERNATIONAL

Lic # :

Odometer In : 84995

Unit # :174

VIN # :1HTWNAZTX BJ309053

Part Description / Number	Qty	Sale	Ext	Labor Description	Ex
INJECTOR 5010823R91	2.00			CHECK FOR PROLONGED CRANK TO START AFTER SITTING FOR 2 HOURS.	382.50
ADAPTER ASSY,INJ OIL INLET 1841923C97	6.00			DIAGNOSED 2 INJECTORS AND INJECTOR PUCKS LEAKING PRESSURE. REPLACED INJECTORS #1 & #6. REPLACED ALL 6 INJECTOR CUPS. RE-TESTED INJECTORS FOR LEAKS. NO LEAKS FOUND. LET SIT OVER NIGHT AND STARTED COLD. NO ISSUES FOUND. TESTED OK.	
RING,O 1841581C1 Shop Supplies	1.00				

Org. Estimate 0.00 Revisions 0.00 Current Estimate 0.00

Labor:
Parts:

SubTotal: -

Tax:

Total: 1,579.08

Bal Due:

[Payments -]