

Mower # 2
DX 9185



Date 8/11/2016 Invoice #

Invoice

jgeinc.com

Bill To:

Ship To:

Make: Hustler

Model: 928663

S/N: 10062485

Hours: 1081

P.O. #

Terms: Due on Receipt*

Account #

Contact:

Item Description	Qty	Your Cost	Total
601413X Hydro Filter element	1		
Mobil 1 Full Synthetic	7		
Inbound freight charged to customer.	1		

You've been helped by:

Subtotal
Sales Tax (0.0%)
Total
Payments/Credits

Your Balance \$6,593.59

Signature: _____

JGE
EST 1989

mower #2
DX 9185

Date
8/11/2016

Invoice #

Invoice

Bill To:

Ship To:

Make: Hustler

Model: 928663

S/N: 10062485

Hours: 1081

P.O. #

Terms: Due on Receipt*

Account #

Contact:

Item Description	Qty	Your Cost	Total
Concern: Hydro noise Trouble-shoot, checked hydrostatic system with pressure gauges and determined system was low on pressure and was not operation properly.	3.12		
Removed pumps, motors, lines, hoses, hydro tank, hydro cooler, bypass valve, flushed hydro tank, flushed cooler, flushed bypass valve, cleaned and inspected all components.	4.5		
Disassembled top tandum pump to inspect, found pump needed to be replaced, remove and replace top tandum pump assembly, check over.	5.5		
Concern: Re-install drive motors, brakes, linkage, hoses, lines, hydro filter, hydro oil, adjusted brakes, checked tire pressures, adjusted tracking, run, test machine operation.	7		
Charges for Shop Supplies.	1		
Charges for Fluid Disposal.	1		
781302 Hustler spring	1		
Drive motor Kit	1		
Tandem Hydraulic pump	1		

You've been helped by: Mark

Subtotal
Sales Tax (0.0%)
Total
Payments/Credits
Your Balance

Signature: _____