

Repairs Completed:

#	Equip Num	Repair Description	Repair Date	Miles/km on Equip	Hours on Equip	Cost
1	220	Filter	4/3/2009			
		14P Geostar G350 Lug	4/4/2009			
		Primary Wire	4/6/2009			
		Toggle Switch & Wire	8/12/2009			
		Cylinder	10/1/2009			
		Adhesive	10/6/2009			
		Light	10/28/2009			
		Bore Seal	11/18/2009			
		Controller	11/19/2009			
		Mini Lamp	12/8/2009			
		Filter	1/18/2010			
		Air Filter	1/18/2010			
		polyseal and square seals	2/23/2010			
		Hinge	2/23/2010			
		Pressure Switch	3/30/2010			
		oil filter	3/31/2010			
		Fuel Filter	4/15/2010			
		Spline Shaft and seal kit	4/27/2010			
		ball bearings	4/28/2010			
		1-1/4 in hose	4/28/2010			
		Gasket	9/29/2010			
		Cable	10/13/2010			
		Terminal	10/13/2010			
		Terminal	10/13/2010			
		Bearings	10/13/2010			
		Connector	10/13/2010			
		Fittings	10/29/2010			
		Oil Filter	11/5/2010			
		8 gal 15w/40 oil	12/29/2010			
		Interlock Tube	1/20/2011			

#	Equip Num	Repair Description	Repair Date	Miles/km on Equip	Hours on Equip	Cost
1	220					
		Lower Handle	1/20/2011			
		Under Cap	1/20/2011			
		Spring Handle	1/20/2011			
		Transmitter	1/26/2011			
		Hose	1/26/2011			
		Rubber Boot	1/26/2011			
		Sleeve and nut brass air brake	2/28/2011			
		core	4/13/2011			
		injector	4/13/2011			
		ring	4/13/2011			
		Battery	4/13/2011			
		Bearing Pad	4/27/2011			
		Bearings	4/27/2011			
		Bearing Pad	4/27/2011			
		Bearing Pad	4/27/2011			
		Bearings	4/27/2011			
		Bearing Pad	4/27/2011			
		Cap Screw	4/27/2011			
		Bearing Pad	4/27/2011			
		Control Module	6/7/2011			
		Pressure Switch	8/1/2011			
		Oil Filter	10/31/2011			
		Air Filter	10/31/2011			
		Fuel Filter	10/31/2011			
		Controller	12/9/2011			
		light	8/30/2012			
		Transmission	3/6/2013			
		Muffler	3/7/2013			
		Pipe	3/7/2013			
		Band Clamp	3/7/2013			
		Clamp	3/7/2013			

#	Equip Num	Repair Description	Repair Date	Miles/km on Equip	Hours on Equip	Cost
1	220					
		1-Fuel/Water	6/15/2017			
		1-Oil	6/15/2017			
		New trailer plug and new fuse	6/1/2018			
		Rebuilt pole claw cylinder	1/1/2019			
		Pole claws had a wire unhooked on right side of boom, reattached & works like they should	1/1/2019			
		Antifreeze	1/1/2019			
		Changed oil	1/1/2019			
		Checked trans fluid, rear and front end, & transfer case	1/1/2019			
		New radiator tank on passenger side	1/1/2019			
		New oil pan & gasket	1/1/2019			
		Rebuilt boom cylinder	1/1/2019			
		New rear main seal	1/1/2019			
		New rear main seal	6/7/2019			
Total Cost Over All						\$15,793.29

Total Cost Listed below