

INVOICE

Invoice #
Invoice Date 07/15/2019
Order #
Order Date 06/03/2019
PO #
Order Contact
Terms
Net Due Date 7/15/2019
Pick Ticket #

Customer ID: 193217

Ordered	Shipped	Remaining	Item ID Item Description
---------	---------	-----------	-----------------------------

Order Note: Haulotte 3632T
36T06-00086
Hours 5903

Repair boom operation and oil leaks. Check over
machine for other concerns.

Carrier: UPS

Tracking #:

MECH-REG

Labor-Regular

SH-25

Misc. Hardware/Shop Job

ENV-25

Environmental Charge

FRT

Shipping & Handling

HAA03644

Switch

HAA03647

Switch

SH-100

Misc. Hardware/Shop Job

SH-50

Misc. Hardware/Shop Job

INVOICE

Invoice #
Invoice Date 07/15/2019
Order #
Order Date 06/03/2019
PO #
Order Contact
Terms
Net Due Date 7/15/2019
Pick Ticket #

Ordered	Shipped	Remaining	Item ID Item Description
---------	---------	-----------	-----------------------------

PARTS SUBTOTAL:

LABOR SUBTOTAL:

SALES TAX:

CHECK: 2,253.57

AMOUNT DUE: