

INVOICE

Invoice #

SO #

Date 11/01/2019

Writer

Page 1 of 1

Sold
to:

Ship
to:

Contact	Payment terms	Ship via
Contact phone	Primary phone	

Work Order No.

Condition replace output shaft

Part number	Description	Ord	Del	B/O	List Price	Unit price	Ext. price
033_06T39143	TG-K+M+V SHAFT	1	1	0			
033_TG-GSK-A1	SEAL KIT	2	2	0			
033_28T34480	COVER CUP/PORTED END	1	1	0			
033_13MK5703	6 BOLT .010 GASKET	2	2	0			
033_13MK5704	6 BOLT .020 GASKET	2	2	0			

Labor

Shop supplies

Total merchandise

Total cores

Total labor

Tax amount

Invoice total

\$462.16

INVOICE

INVOICE	
Invoice Date	Page
11/4/2019 15:38:11	1 of 2
ORDER NUMBER	

Customer ID:

PO Number			Term Description		Net Due Date	Disc Due Date	Discount Amount	
					11/4/2019			
Order Date		Pick Ticket No		Primary Salesrep Name			Taker	
11/1/2019 08:02:47								
Quantities					Item ID Item Description	Pricing UOM	Unit Price	Extended Price
Ordered	Shipped	Remaining	UOM Unit Size	Disp.		Unit Size		

Order Note: Disassemble pump clean and inspect all parts,
installed necessary parts and new seal kit. Rebuild
pump and tested, unit has passed all testing.

Carrier:

Tracking #:

*****Service Item*****

1.00 1.00 0.00 EA PUMP GEAR
Serial Number: 68981
1.0 PUMP GEAR

Visa:
Transaction Type:
Entry Method:
Merchant ID:
Reference Number:
Retrieval Number:
Host Response:
Authorization Number:
Authorization Date: 4 Nov 2019 3:38 PM
Authorized Amount: 617.63

ORIGINAL

T300

#2481

Date: 10-3-19

Slack Farms

MAKE/MODEL Kennworth YEAR 1965 MILEAGE 396875 VIN 396875
DESCRIPTION OF WORK PERFORMED: Removed & Replaced Clutch - pilot
bearing - Flywheel - Trans Fluid

PARTS	UNIT PRICE	LINE TOTAL
1 Clutch		
1 Pilot bearing		
1 Flywheel		
3 gallons 50W Fluid		
2 4 joint Strap Kits		
LABOR 8 hrs		

Please make checks payable to WAGONER'S

Thank You for Your Business

SALES TAX
7.50%
Total

\$1,757.00

Payment due upon receipt