

Sold By:
Ship By:

PO #:

Tax #:

Date 12/06/18

INVOICE

11:23:56 PRT:

2

Tax	D	Qty	Description	Price	Amount
-----	---	-----	-------------	-------	--------

Group: 01

COUNTER PARTS

08600X 2 TAK 0881131300

ROLLER

SR1 D 2

5517 H.

Both Rear Rollers

** SUBTOTAL
** DISCOUNT
** SALES TAX

PAY THIS
AMOUNT



\$1527.99

Sold By:
Ship By:

PO #:

Tax #:

Date 11/01/18 INVOICE

15:30:33 PRT: 2

Tax	D	Qty	Description	Price	Amount
-----	---	-----	-------------	-------	--------

Group: 01

PARTS FRT & HDL

00000 FREIGHT IN UPS RED

COUNTER PARTS

08600X	1	TAK	1902023700
--------	---	-----	------------

PUMP, gear	D	2	I	2
------------	---	---	---	---

08600X	1	TAK	1420110400
--------	---	-----	------------

ORING	E	1	N	8
-------	---	---	---	---

08600X	1	TAK	1420110300
--------	---	-----	------------

OR	E	1	J	7
----	---	---	---	---

08600X	1	TAK	1420360152
--------	---	-----	------------

OR	E	1	H	6
----	---	---	---	---

08600X	2	TAK	1420010240
--------	---	-----	------------

ORING	E	1	H	3
-------	---	---	---	---

** TOTAL COUNTER PARTS

Replaced implement

gear pump 5397 hr 11/1/18

** SUBTOTAL
** DISCOUNT
** SALES TAX

PAY THIS
AMOUNT



\$832.45

Sold By:
Ship By:

PO #:
Tax #:

Date 8/30/18 INVOICE
13:23:49 PRT: 2

Tax	D	Qty	Description	Price	Amount
Group: 01					
COUNTER PARTS					
08600X	1	TAK	K1C010-73032	WATER PUMP	D 2 D 2
08600X	1	TAK	K1C010-73430	GASKET	D 5 H 2
08600X	1	TAK	K1G377-97010	BELT	D 2 F 1
08600X	1	TAK	1911509911	V-BELT	D 5 C 1
08600X	1	TAK	0569617280	IDLE PULLEY	E 4 E 3
** TOTAL COUNTER PARTS					

Returned water pump
Gasket and Belt
Replaced A/C

idler pulley and A/C

Belt 5242 hr

8/30/18

** SUBTOTAL
** DISCOUNT
** SALES TAX

PAY THIS
AMOUNT

\$324.81

Sold By:
Ship By:

PO #:

Tax #:

Date 12/14/17 INVOICE

9:26:35 PRT: 4

Tax	D	Qty	Description	Price	Amount
			GROUP : 01		
			COUNTER PARTS		
08600X	1	TAK 1100440810	BOLT	6 C 3 D	
08600X	1	TAK 1911509911	V-BELT	D 5 C 1	
08600X	1	TAK 0564634890	COLLAR		
08600X	1	TAK 0564634830	V PULLEY		
08600X	1	TAK 0564626010	SHAFT		
08600X	1	TAK 0564634895	COLLAR		
08600X	2	TAK AU0881160110	SPROCKET TL BB 4 5		
08600X	2	TAK 1914099320	TRK TL150/2 E/LOT		
			** TOTAL COUNTER PARTS		

Replaced tracks
and sprockets 4898 hr
12/14/17

** SUBTOTAL
** DISCOUNT
** SALES TAX

PAY THIS
AMOUNT



\$4541.73

Sold By: PO #: Date 12/11/17 INVOICE
 Ship By: Tax #: 11:10:22 PRT: 2

Tax	D	Qty	Description	Price	Amount
			GROUP : 01		
			COUNTER PARTS		
08600X	1	TAK	1730142090	CONTROLLER F 4 J 6	
08600X	1	TAK	0697003900	HOSE ASSY	
08600X	1	TAK	1650205500	GRIP (ROUND D 2 C 6	
08600X	8	TAK	1901710914	SEAL 6 A 4 A	
08600X	8	TAK	1420010200	O-RING D 4 G 2	
			** TOTAL COUNTER PARTS		

Replant Left
 hand Control and aux
 hy controller 4898 hr
 12/11/17

** SUBTOTAL
 ** DISCOUNT
 ** SALES TAX

PAY THIS
 AMOUNT

\$589.93

Sold By:
Ship By:

PO #:
Tax #:

Date 6/01/17 INVOICE
11:24:54 PRT: 2

Tax	D	Qty	Description	Price	Amount
			GROUP : 01		
			COUNTER PARTS		
08475X		1	TAK K1G938-52030	ASSY PUMP F E 1 D 6	

on 6/2/17 installed

Fuel lift pump for

Power Loss 4495 hr

** SUBTOTAL
** DISCOUNT
** SALES TAX

PAY THIS
AMOUNT

\$299.79

Sold By:
Ship By:

PO #: TL250-5
Tax #:

Date 1/30/17 INVOICE
8:54:30 PRT: 2

Tax	D	Qty	Description	Price	Amount
			GROUP : 01		
			COUNTER PARTS		
08350X		1	TAK AU0881131300		
			RLLR REAR L SR1 D 2		

TL250-5 1-30-17

Left Rear Idler

1-30-17

4395 H.

** SUBTOTAL
** DISCOUNT
** SALES TAX

PAY THIS
AMOUNT



\$364.59

Sold By:
Ship By:

PO #: TL250-5
Tax #:

Date 6/30/16 INVOICE
10:40:24 PRT: 2

Tax	D	Qty	Description	Price	Amount
			GROUP : 01		
			COUNTER PARTS		
08350X		2	TAK 1914099320	TRK TL150/2 E/LOT	
08350X		2	TAK AU0881160110	SPROCKET TL BB 4 5	
			** TOTAL COUNTER PARTS		

Replace Tracks & Sprockets

4157 hrs

6-30-16

** SUBTOTAL
** DISCOUNT
** SALES TAX

PAY THIS
AMOUNT



\$4515.43

Sold By: ☐
Ship By: ☐

PO #: 72250-5
Tax #:

Date 9/03/15 INVOICE
11:31:08 PRT: 2

Tax	D	Qty	Description	Price	Amount
			GROUP : 01		
			PARTS FRT & HDL		
08350X			FRT IN		
			COUNTER PARTS		
08350X		10	TAK AU0881130500	ROLLER LOWE	MM 6 4

Replace Lower Rollers

9-3-15

3795 hrs

** SUBTOTAL
** DISCOUNT
** SALES TAX

PAY THIS
AMOUNT



\$3084.59

Sold By:
Ship By:

PO #: TL250-5
Tax #:

Date 5/06/15 INVOICE
7:36:21 PRT: 2

Tax	D	Qty	Description	Price	Amount
			GROUP : 01		
			COUNTER PARTS		
08350X		2	TAK 0881160110		
08350X		2	TAK 1914099320		
			SPROCKET BB 2 5		
			TRK TL150/2 E/LOT		
			** TOTAL COUNTER PARTS		

3325 hrs

Replace Tracks & Sprockets
5-6-15

** SUBTOTAL
** DISCOUNT
** SALES TAX

PAY THIS
AMOUNT



\$4797.54

Sold By:
Ship By:

PO #: TL250-5
Tax #:

Date 5/27/15 INVOICE
16:56:20 PRT: 1

Tax	D	Qty	Description	Price	Amount
			GROUP : 01		
			COUNTER PARTS		
08350X		1	TAK K1K01263010	TL250 START	

3325 hours
5-27-2015

** SUBTOTAL
** DISCOUNT
** SALES TAX

PAY THIS
AMOUNT



\$416.11

Sold By:
Ship By:

PO #: TL250-5
Tax #:

Date 4/25/13 INVOICE
9:39:54 PRT: 2

Tax	D	Qty	Description	Price	Amount
			GROUP : 01		
			PARTS-SHOP		
08350X	2	TAK 1914099320	TRK TL150/2 E/LOT		
08350X	2	TAK AU0881160110	SPROCKET TL BB 3 5		
			** TOTAL PARTS-SHOP		

TL250-5 4-25-13

~~250~~
1701 hours

** SUBTOTAL
** DISCOUNT
** SALES TAX

PAY THIS
AMOUNT

\$4442.32

TAKEUCHI TL250C 11 SN:225001103 HR 702.0
Sold By: PO #: Date 4/30/12 WORK ORDER
Ship By: Tax #: 13:19:22 PRT: 2

Work Order Summary

01 STARTING PROBLEM
02 CHARGES ARE FOR ITEMS NOT COVERED UNDER WARRANTY

TL250-5

** TOTAL

Tax	D	Qty	Description	Price	Amount
-----	---	-----	-------------	-------	--------

GROUP : 01

01 STARTING PROBLEM

TAKE WARR LABOR

** TOTAL TAKE WARR LAB

DROVE TO CUSTOMER'S LOCATION/STARTING PROBLEM.FEMALE SPADE CONNECTOR ON STARTER SOLENOID SIGNAL WIRE LOOSES CONTACT.RAISED AND SECURED LOAD ARMS AND CAB.DISCONNECTED SIGNAL AND ADDED A 6" JUMPER WIRE WITH A NEW FEMALE SPADE CONNECTOR.HAD WORKED ON THIS PROBLEM PREVIOUSLY AND TIGHTENED TERMINAL BUT ENGINE MOVEMENT/HARNESS TIGHT CAUSED IT TO LOOSEN.

* SEGMENT SUBTOTAL

02 CHARGES ARE FOR ITEMS NOT COVERED UNDER WARRANTY

MILEAGE
00000 26 MILEAGE CHARGE
TAK INT EXP LAB

** TOTAL TAK INT EXP L

07850 **THANK YOU FOR YOUR BUSINESS**

* SEGMENT SUBTOTAL

** SUBTOTAL

PAY THIS
AMOUNT

\$122.50

TAKEUCHI TL250C 11 SN:225001103 HR 666.0
Sold By: PO #: Date 4/11/12 WORK ORDER
Ship By: Tax #: 14:28:50 PRT: 4

Work Order Summary

01 STARTING PROBLEM
02 CHARGES ARE FOR TRAVEL TIME/MILEAGE NOT COVERED UNDER WARRANTY

Tax	D	Qty	Description	Price	Amount
		GROUP :	01	TL250-5	

01 STARTING PROBLEM

TAKE WARR LABOR

** TOTAL TAKE WARR LAB

DROVE TO CUSTOMER'S LOCATION/SHORT IN CAB HARNESS.STARTED CHECKING ELECTRICAL SYSTEM AND START CIRCUIT.FOUND LOOSE SIGNAL WIRE ON STARTER SOLENOID.TIGHTENED CONNECTOR(SPADE) AND SECURED HARNESS TO PREVENT MOVEMENT PART # 0664202400

* SEGMENT SUBTOTAL

02 CHARGES ARE FOR TRAVEL TIME/MILEAGE NOT COVERED UNDER WARRANTY

MILEAGE
00000 26 MILEAGE CHARGE
TAK INT EXP LAB

N/C

** TOTAL TAK INT EXP L

* SEGMENT SUBTOTAL

PAY THIS
AMOUNT



\$.00