

Branch SIDNEY		*REPRINT*	
Date 02/07/17	Time 23:08:44 (B)	Page 01	
		Invoice No. W14879	
Ship Via		Purchase Order	
		Salesperson 667	

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
C060155		X H00924P626472		
HEAD				
924				

REPAIR# 1 C 628 JDFLEXHEAD 01/04/17 01/04/17 01/31/17
 2016/17 PRIORITY SERVICE PROGRAM - FLEX HEAD
 Perform PERFORMAX INSPECTION.
 Manufacture parts/labor ESTIMATE.
 Prioritize inspection list.
 Consult with customer on recommended repairs/service.

LABOR

10700006 REPAIR TOTAL==>

REPAIR# 2 C 628 NA 01/13/17 01/13/17 01/31/17
 REPLACE CUTTER BAR WEAR PLATES
 R&R sickle.
 R&R guards with wear plates.

H153157	WEAR PLATE	23	4.26	
H153855	KNIFE GUAR	1	22.45	
				PARTS
				LABOR

10700006 REPAIR TOTAL==>

REPAIR# 3 C 628 NA 01/13/17 01/13/17 01/31/17
 REPLACE 2 SICKLE SECTIONS

H125894	SECTION	1 S	3.21	
H207929	SECTION	1	1.97	
				PARTS
				LABOR

10700006 REPAIR TOTAL==>

REPAIR# 4 C 628 NA 01/13/17 01/18/17 01/31/17
 INSTALL POLY AUGER FLOOR LINER

CONTINUED ON PAGE 02

Branch SIDNEY		
Date 02/07/17	Time 23:08:44 (B)	Page 02
Account No.	Phone No.	Invoice No. W14879
Ship Via		Purchase Order
		Salesperson 667

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
C060155 HEAD 924		X H00924P626472		

Remove strippers.
 Raise auger.
 Install liner.
 Install stripper.
 Adjust auger.
 Install skid plates.
 Test operation.

FRT	FREIGHT CHARGE	1	
GPJRK92458G	24' POLY	1 N	

	PARTS	
	LABOR	
10700006		REPAIR TOTAL==>

REPAIR#	5 C 628 NA	01/13/17	01/13/17	01/31/17
REPLACE AUGER FINGERS AND GUIDES				
AH206160	KIT	2	N	
H162662	FINGER	2		
H86918	SCREW	4		
H87044	GUIDE	2		
H87192	CAP	2		

	PARTS	
	LABOR	
10700006		REPAIR TOTAL==>

REPAIR#	6 C 628 NA	01/13/17	01/13/17	01/31/17
REPLACE AUGER STRIPPERS				
Labor included in other repairs.				
H145024	STRIPPER	2	N	
M2353T	SNAP RING	1		
N10213	LOCK NUT	18		

CONTINUED ON PAGE 03

Branch SIDNEY		
Date 02/07/17	Time 23:08:44 (B)	Page 03
Account No.	Phone No.	Invoice No. W14879
Ship via		Purchase Order
		Salesperson 667

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
C060155	HEAD 924		X H00924P626472		
03H1540	BOLT	18	S		
10700006					
			PARTS		
			REPAIR TOTAL==>		

REPAIR# 7 C 628 NA 01/13/17 01/13/17 01/31/17
 RECONDITION RIGHT REEL LIFT CYLINDER
 R&R cylinder.
 Install seal kit.

AH222054	WASHER	1	N
AH222165	HYDRAULIC	1	S
	Hydraulic Cylinder Kit		

PARTS
LABOR

10700006 REPAIR TOTAL==>

REPAIR# 8 C 628 NA 01/13/17 01/17/17 01/31/17
 ADJUST ALIGNMENT OF THE AUGER DRIVE CHAIN
 Loosen auger drive shaft carrier bearing bracket.
 Straightened the end bracket that holds the auger drive sprocket.
 Loosen carrier bearing.
 Tighten bracket then bearing.
 Test.

LABOR

10700006 REPAIR TOTAL==>

REPAIR# 9 C 628 10005AU 01/13/17 01/17/17 01/31/17
 REEL SLAT, R&R OR REPLACE--PICKUP AND SLAT REELS
 Remove reel slat.
 Repair slats.

CONTINUED ON PAGE 04

Branch SIDNEY			
Date 02/07/17	Time 23:08:44 (B)	Page 04	
Account No.	Phone No.	Invoice No. W14879	
Ship Via		Purchase Order	
		Salesperson 667	

SERVICE INVOICE

STK#/FLEET# C060155 HEAD HRS PIN/EIN X H00924P626472 WARRANTY DATE HRS

924

Reinstall to specifications.

10700006 LABOR REPAIR TOTAL==>

REPAIR# 10 C 628 NA 01/13/17 01/13/17 01/31/17

REPLACE CUTTERBAR GEARBOX OIL

TY6296 QT80W90 1

PARTS

LABOR

10700006 REPAIR TOTAL==>

REPAIR# 11 C 628 NA 01/13/17 01/13/17 01/31/17

REPLACE LEFT SAFETY SHIELD

AH236099 SHIELD 1 N

E62951 PTO SHIELD 1 S

PTO Shield Retainer

H93439 POWERSHAFT 1 N

P50419 SNAP RING 1

PARTS

LABOR

10700006 REPAIR TOTAL==>

***** WORK ORDER TOTALS *****

PARTS

LABOR

EPA DISPOSAL FE

PRIORITY SVC DI

SHOP SUPPLIES

240837 XXXXXX3491

TOTAL

4546.77

Branch SIDNEY		
Date 02/07/17	Time 23:08:44 (B)	Page 05
Account No.	Phone No.	Invoice No. W14879
Ship Via	Purchase Order	
		Salesperson 667

SERVICE INVOICE

STK#/FLEET#

C060155

HEAD

924

HRS PIN/EIN

X H00924P626472

WARRANTY DATE

HRS

02/07/17 23:08:44 (B)