

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG
WHITE	99	KENWORTH W900A	1NKWL90X4XR814658		258320/258320	T17
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT
01JAN99 DD			17:00 01JUN18		0.00	CASH
R.O. OPENED	READY		OPTIONS: ENG: Cummins_M11			05JUN18
12:50 29MAY18	18:38 05JUN18					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A DIAGNOSE LOOSE STEERING PROBLEM WHEN LOADED

05-T1 CHECK OVER FRONT END FOR LOOSE STEERING

1613 CPTX

1993 CPTX

05-T1 REMOVE AND REPLACE TIE ROD ENDS

1613 CPTX

05-T1 REMOVE AND REPLACE BOTH STEERING SHAFT U

JOINTS

1613 CPTX

1 FLTTR3034R TIEROD, TRE MERITOR STYLE C-E 7

1 FLTTR3033L TIEROD, TRE MERITOR STYLE C-E 7

2 DS5103X U JOINT KIT

PARTS: 196.74 LABOR: 598.00 OTHER: 0.00 TOTAL LINE A:

258320 checked over the front end. both tie rod ends are loose, the upper steering shaft u-joint is loose and it has atf in the power steering system. replaced both tie rod ends. replaced both steering shaft u-joints. widened out the alignment rack and drove the truck on the rack. aired the steer tires to 120psi and set the toe. backed the truck off the alignment rack and parked it in a work bay. narrowed the alignment rack back up. -1993 Test drove and drove good

\*\*\*\*\*

B REPAIR LEFT INSIDE DOOR HANDLE/WON'T OPEN FROM INSIDE

16-T1 MISC REPAIRS TO CAB

1993 CPTX

1 K294426PAK HANDLE INSIDE LH

1 FREIGHT FREIGHT

PARTS: LABOR: OTHER: TOTAL LINE B:

inspected moving parts of door and found inner door handle didn't move any connecting rods, removed door handle and found the plastic piece that pulls the rod is broken, pushed rod against door to make sure it wasn't binding on anything to make a new door handle brake and it wasn't checked with parts to get a new one. installed new door handle and new clips, tested and worked good. 1993

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	

(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)

CUSTOMER SIGNATURE

PLEASE PAY  
THIS AMOUNT

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN 201	TAG	
WHITE	99	KENWORTH W900A	1NKWL90X4XR814658		258320/258320	T17	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN99 DD			17:00 01JUN18		0.00	CASH	05JUN18
R.O. OPENED	READY		OPTIONS: ENG:Cummins_M11				
12:50 29MAY18	18:38 05JUN18						
LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
C	COMPLEMENTARY	COURTESY	INSPECTION				
CCI	COMPLEMENTARY	COURTESY	INSPECTION				(N/C)
1613 ICCI							
PARTS:	0.00	LABOR:	0.00	OTHER: 0.00	TOTAL LINE C:		
checked over the truck and made a list of things that need attention							
*****							
CUSTOMER PAY SHOP SUPPLIES FOR REPAIR ORDER							

*Thank You For Your Business!*

	DESCRIPTION	TOTALS
	LABOR AMOUNT	
	PARTS AMOUNT	
	GAS, OIL, LUBE	
	SUBLET AMOUNT	
	MISC. CHARGES	
	TOTAL CHARGES	
	LESS INSURANCE	
	SALES TAX	
(SIGNED)	DEALER, GENERAL MANAGER OR AUTHORIZED PERSON	(DATE)
	CUSTOMER SIGNATURE	PLEASE PAY THIS AMOUNT
		1242.31

Bill To

DG 2623

L Rm

JOB	VIN	MILEAGE	MECHANIC
99' Kenworth Mixer	XR814658		Brad

Item	Description	Quantity	Rate	Amount
Labor	Labor	6		
85088	6-32 x 3/4" Metal Screw	2		
87012	6-32 MS Hex Nut	2		
95008	1/4" Flat Washer	2		
30217	16-14 #10 Hook Tongue Terminal	2		
72295	1/8" Tank Valve	1		
SP3-WG14-0	14 Gauge Black Primary Wire	30		
SP3-WG14-2	14 Gauge Primary Wire	60		
Special Order	New All Weather Toggle Switch	1		
30300	12-10 Insulated Butt Connector	6		
30217	16-14 #10 Hook Tongue Terminal	3		
5141A	3/8" Wire Protector Tubing	30		
1865PT	16-14 AWG .250 Female	3		
90008	1/4" x 1" Bolt	2		
95008	1/4" Flat Washer	2		
94306	1/4" Lock Nut	1		
Special Order	New Air Ride Seat Air Bag	1		
Freight	Freight	1		
71656	1/8" Nut	1		
71655	1/8" Split Sleeve	1		
70682	1/4" Adapter	1		

Subtotal	
Sales Tax (5.5%)	
Total	\$653.55

LCC Check  
12/17/18  
17253