

Authorization

Bill To

Plate
Description 2002 Wilson Stock Trailer
VIN
Odometer 0

Home
Bob
Email

Work Order # 25332
Service Advisor
Technician

Appointment 4/17/2020 8:34 AM
Promised 4/17/2020 5:00 PM

Inspection

Courtesy Visual Inspection

This is a Courtesy Visual Inspection not to be used as a complete vehicle inspection.

Inspection 0.3 Hour

Service

Structure Stability General Service

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Retest and verify repair as required. Perform final road test where applicable.

Remove and replace all 5th wheel sub-frame and lower channel lock.	48 Hour
TruckBed Coating	2 Unit
1/4 x 7 Flat	1 Unit
Channel	1 Unit
Metal & Metal Cutting Labor	
7" - 1/4X4 Flat	1 Unit
2" - 6" Channel	1 Unit
1/4 x 2 Flat	1 Unit
PCV Valve Grommet	1 Unit
PCV Valve Grommet	12 Unit
1/4x6 Flt	1 Unit

Sub \$7,074.72

Brake System General Service- Front Axle

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

Remove and replace brakes, wheel seal and cam kit.	2.5 Hours
Brake Shoe Kit	2 Unit
Trailer Wheel Set	1 Unit
Brake cam kit	1 Unit
Air Fittings	4 Unit

Sub \$595.82

Lighting General Service

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Retest and verify repair as required. Perform final road test where applicable.

Fixing lighting on trailer.	1 Hour
LED lights	6 Unit