

INVOICE

12812

INVOICE

Date: 09/25/2017

2009 Dodge - 5500 - 6.7L, In-Line 6 (408CI) VIN(L)

Lic # :216 - AR

Odometer In : 211496

Unit # :216

Odometer Out : 211504

VIN # :3D6WD76L4 9G566075

Part Description	Qty	Sale	Ext	Labor Description	Ext
air filter	1.00			check a/c	
EGR cooler	1.00			replaced leaking a/c hose assembly (compressor to condensor & drier , evacuate & recharge system	
crankcase filter	1.00			diagnose engine noise	
reman engine	1.00			removed engine & removed oil pan to inspect crankshaft & bearings	
a/c hose assembly	1.00			- replaced engine assembly due to #6 rod bearing damage	
R134A freon	2.00				
shop supplies					

PAID

Check # 19308Date 9-26-17

Labor:

Parts:

SubTotal:

Tax:

Total:

Bal Due:

12,112.24

\$12,112.24