CUSTOMER:

SALESMAN: EXT PHN

VEHICLE: 2000 PETE 378

LICENSE: 71036C SD MILEAGE: 92160 COLOR: RED ENGINE: 2WS31734

YN508144 VIN:

Fleet ID

DUE: 05/28/14 INVOICE DATE: 04/28/14

MECHANIC QUANTITY PRICE LABOR EXTENSION PRODUCT OIL LEAKS WASH REMOVE TRANSMISSION REMOVE CLUTCH AND FLYWHEEL REMOVE STARTER REMOVE OIL PAN RESEAL REAR HSG REPLACE MOTOR MOUNTS REASSEMBLE REPAIR EXHAUST REPLACE ELBOW REBUILD SHIFT TOWER REPLACE REVERSE SWITCH REMOVE HOOD REMOVE RADIATOR REMOVE FRONT HSG RESEAL REPLACE SPACER PLATE

RESET TIMING REPLACE LWR RADIATOR HOSES TANK ON RAD RUSTED OUT FINS BAD REPLACE RADIATOR TEST DRIVE CYL 5 MISSING REPLACE INJECTOR 5 SET TRIM CODE

REINSTALL OIL PAN CHANGE OIL REPLACE DISCHARGE HOSE REPLACE COMP OIL LINE

REPLACE FUEL LINE

FAN	DONT	LOCK	UP	LEAKS	REBUILD	FAN	

REAR	STRUCTU	JRE	E KIT C		1
BUSHIN	NG REAR	2	PIECE		4

D-83 √PAN GSK 3406

4N1151 VFRONT STRUCTURE KIT E

2336984 1.00 VEP50EL90124A PIPE

OPP 1

√IDLERGEAR BUSHING 1304698

5 BULL GEAR STUB BOLT

2J3118 10 BULL GEAR PLATE BOLT

1261756 2 STUD AIR COMP

3346832 1.00 USED SPACER PLATE

OPP 1.00

√3P1155 ORING OPP

1.00 √1918303 SENSOR OPP

1.00 √1171385 ORING

OPP

PAGE: 2

CUSTOMER:

PRODUCT	MECHANIC	QUANTITY	PRICE	LABOR	EXTENSION
RADIATOR PETE COMP		1			
, 239208		1			
*HARNESS 1325317		,			
√WELD BUMPER BRACKET		1.00			
MP √SWITCH BACK UP LIGHT PETE		1			
21-635P					
√PTO SHIFT COVER GSK		1			
35P8 √8 BOLT .010 GSK		1			
35P15-1		0.0			
√TIES		30			
PLASTIC-TIE		1			
4305294		1			
SEAL SHIFT TOWER BOOT , 10427		1			
VKIT ORING		1			
K3376		4.00			
VOIL TRANSMISSION SHC-50		4.00			
√FLEX 5 INCH SS		2.00			
P226158 CLAMP-5 IN STAINLESS		6			
X007785					
✓ORING		1			
117-1385 VEAN REBUILD KIT		1			
994305					
BOLT 1/2 X 4		2			
38-0832 VNUT 5/8		1			
86175		1			
VNUT 3/8		1			
86161 √NUT		2			
86163		1			
√NUT 3/4-10 86166		,			
✓BOLT		1			
45463		1			
√1/4 NUT 86159					
√SCREW		1			
71295 A 11 HOSE -4 3/16		1.00)		
D1017-2171					

PAGE: 3

CUSTOMER: VANDERPOL DRAGLINE INC

PRODUCT	MECHANIC	QUANTITY	PRICE	LABOR	EXTENSION
PRODUCT					
A 11 HOSE -6 5/16 D1017-2195		3.00			
3 INCH SILICONE HOSE		26			
D1030-2728 TEFLON HOSE STAINLESS (S-10T	W)	74			
H24308 ORING AIR COMP		1			
1100004 HOSE END 4 SWIVEL X 1/4 A11					
D2010-3168 HEAT SHRINK CONNECTOR		1			
NASN345LS 3406 OIL FILTER (LFP4005)		. 1			
LF691A BRAKE CLEANER		4			
ZDEM720 BELT		2			
17591DYC 1/2 TEFLON TO 10 FLARE		2			
08E-610 LOOM CLAMP		. 1			
67171 CHARGE COOLER MTG		2			
EXHAUSTMOUNT OIL-DELVAC 15W40		11.00			
DELVAC 15-40 CLAMP TBOLT 4 IN HOSE		2			
B9226-0406		1			
ORING 8 50-953		1			
AC ORING 6 50-951					
1/4T X 1/8P X 45 64801		1			
ADDITIVE COOLING SYSTEM DCA65L		1.00			
AC DYE MP		1.00			
OIL PAG 150 PER OZ 59003		. 1			
FREON		3.63			
R134A 59932 59933 CAPS		2.00			
MP GREEN ANTIFREEZE GALLON		1.00			
ANTIFREEZE SAFETY POP OFF 131081		1			

INVOICE #:

PAGE: 4

CUSTOMER:

PRODUCT	MECHANIC	QUANTITY	PRICE	LABOR	EXTENSION
COTTER PIN		2			
35063 INJECTOR		1			
10R8501 CORE INJECTOR		1			
10R8501C FUEL TREATMENT		0.25			
10013 FUEL FILTER (LFF2749)		1			
FF5319 FUEL FILTER (LFF5)		1			
FF105 CORE INJECTOR		-1			
10R8501C LABOR	1	8 60.00			
LABOR SHOP SUPPLIES SS					
~~ ~~			MERCHAN	DISE:	

LABOR:

SALES TAX:

INVOICE TOTAL: 10087.14

ON ACCOUNT A/R

10087.14

TENDERED BY

ON-SITE OIL ANALYSIS AVAILABLE NOW!!!
RESULTS IN MINUTES!!!

THANK YOU FOR YOUR BUSINESS

Customer Signature	:	
--------------------	---	--

INVOICE #:

PAGE: 1

CUSTOMER:

WORK:

SALESMAN: EXT PHN

VEHICLE: 2000 PETE 378
LICENSE: 71036C SD MILEAGE:
COLOR: RED ENGINE: 2WS31734
VIN: YN508144
Fleet ID

DUE: 05/28/14

INVOICE DATE: 04/28/14

INVOICE DAIL. 04/20/14		2021			
PRODUCT	MECHANIC	QUANTITY	PRICE	LABOR	EXTENSION
SEAL TURBO		1			
1367226 TUBE OIL SUPPLY		1			
1993212 FREIGHT FREIGHT		12.00			
SEAL TURBO PRESS WAS 1262 1986068	704	1			

MERCHANDISE:

SALES TAX:

INVOICE TOTAL:

94.77

ON ACCOUNT A/R

94.77

TENDERED BY 6

ON-SITE OIL ANALYSIS AVAILABLE NOW!!! RESULTS IN MINUTES!!!

THANK YOU FOR YOUR BUSINESS

Customer Signature	:	
--------------------	---	--

Invoice Order No. 3-172908

10/2/2018

Customer No. Sequence No.

Shipping Address:

P)# C	Ship Method ounter Sale (None)	Terms	Truck	Sale	esperson
Item		Description		Qty	Price	Extended
24704207		Rear (CRR)		1.00		
(EAT RD Lock YE	404 N/A) RD404,	1SPD,41SPL,3.90 RATIO,	LOCKER,REBUILT	,TAG#; Ratio 3.90; Spline#	41; Diff	
24704207 (ORE	Inherent core charge on F	Rear (CRR)	1.00		Marin Constitution of the State
(EAT RD Lock YES	404 N/A) RD404,	1SPD,41SPL,3.90 RATIO,1	LOCKER,REBUILT,	TAG# ; Ratio 3.90; Spline#	41; Diff	
365 DAY	PARTS & LABOR	WARRANTY- REFER TO	THE BACK OF TH	HE INVOICE FOR FULL DE	TAILS	
Received B				Subt		
Order Note	s: RS404 3.90 RA	ATIO, W/LOCKER		Т	otal	2,130.00
				Balance (Due	2130.00
A = 1 1						
ASK US N	ow to double ti	ne warranty coverage month fro	on any used or om Vander Haag	rebuilt rear ends that yeg's!	ou purcha	ase this

Invoice

Order No. 3-192054

10/25/2019

Customer No. Sequence No.

Shipping Address:

PO #	Ship Method Counter Sale (None)	Terms	Truck	Sale	esperson
Item	Description		Qty	Price	Extended
24803268	Rear (PDA)		1.00		
(EAT DS404 N/A) DS Splines 41; Diff Lock I	404,1SPD,41SPL,3.90 RATIO,REE NO	BUILT,TAG#10497,(350) ; F	Ratio 3.90; Side Gear		
24803268 CORE	Inherent core charge on R	ear (PDA)	1.00		
(EAT DS404 N/A) DS Splines 41; Diff Lock I	404,1SPD,41SPL,3.90 RATIO,REB NO	BUILT,TAG#10497,(350) ; F	Ratio 3.90; Side Gear		
24803268 CORE	Core exchange credit for F	Rear (PDA)	-1.00		
(EAT DS404 N/A) DS	404,1SPD,41SPL,3.90 RATIO,REB	BUILT,TAG#10497,(350)			
Reference Sales Orde	er: 3-192054				
	MILEAGE - 1ST YEAR PARTS & L NVOICE FOR DETAILS	ABOR - 2ND YEAR PART	S ONLY - REFER TO		
				Subtotal Tax	
Received By:					
Order Notes				Total	2,071.43

Working in the dark? Ask about our special on LED work lights to Light It Up!

2071.43

Balance Due

SOLD TO SHIP TO

STORE	CUSTOMER NUM	BER Y	OUR ORDER NUMBER	INVOICE DATE	INVOICE NUMBER	PAGE
				08-22-17		1
SHIP VIA			DOC.DATE		REFERENCE NO.	
			07-12-17	,		
UNIT NUMBER	MAKE	MODEL	SERIAL NUMBER	METER READING	MACHINE II	D NO.
	AA	3406E	02WS31734	192960.0		
QUANTITY	PART NUMBER	N/R	DESCRIPTION	UNIT PRICE	EXTENDED	PRICE

BMC HURON TROUBLESHOOT AIR CONDITIONER COMPLAINT: AC DOES NOT WORK

CAUSE: POOR WIRING, MISSING FUSE, PLUGGED EVAPORATOR AND ORIFICE TUBE

CORRECTION: INSPECTED WIRING TO COMPRESSOR, FOUND ONE WIRE IS MISSING, THE OTHER IS CHOPPED UP ALL THE WAY TO THE CAB. CHECKED POWER AT THE CAB WITH AC ON AND TRUCK RUNNING - NO POWER, INSPECTED FUSES. NO FUSE IS IN PLACE FOR CAB AC. REMOVED FUSE FROM THE SLEEPER SLOT - SINCE THERE IS NO SLEEPER - AND INSTALLED IN AC. NOW HAVE POWER AT COMPRESSOR POWER WIRE. JUMPED GROUND TO COMPRESSOR. COMPRESSOR KICKS ON. HIGH PRESSURE JUMPS AROUND. REMOVED CAB FILTER - VERY DIRTY INSPECTED EVAPORATOR - APPEARS TO BE COMPLETELY PLUGGED. NEED TO REPLACE THE ORIFICE, CLEAN EVAPORATOR - REPLACE ACCUMULATOR, VACUUM AND RECHARGE SYSTEM. ALSO NEED TO REWIRE THE COMPRESSOR.

COMPLAINT: AIR CONDITIONER IT WAS WORKING THEN STOP WORK ANYMORE.

CAUSE: A/C ROCKER SWITCH

CORRECTION: CHECKED THE MAIN CAB HARNESS, CLEAN THE CONNECTORS, THEN FOLLOWED WIRES TO THE SWITCH.

CHECKED THE SWITCH AND IT WAS ACTING WEIRD.

AND SEIEGLADOUT US, FINANCE, AND E-INVOICING

Payment Terms: Open Accounts: Parts, Service, & Rental Net 30; Machine sales Net 10; Installment contracts and leases per contract.

COD Accounts: Payment due at time of purchase. Generated as of month end. Statements:

Credit Card:

Payment via credit card is allowed at the time of purchase and only for Parts, Service, and Rentals. Credit card payment will not be accepted for machine sales, including attachments; contracts; and leases.

PLEASE NOTE THE PAYMENT TERMS CHANGE ON PARTS, SERVICE & RENTAL ACCOUNTS EFFECTIVE 11-14-16. View the legal notice at butlermachinery.com, select ABOUT U.S. FINANCE, and PAYMENT TERMS NOTICE or contact us for a written copy

Butler Machinery Company's service labor is warranted to the customer for a period of 90 days from the date of work, to include defects in workmanship performed by Butler Machinery employees. This warranty would include the replacement of parts and labor, damaged by that defect in workmanship.

Any failures caused by defect of parts, whether replaced now at the time of our work, or re-used, will be covered by the original manufacturer's applicable warranties, if any. Goods cannot be returned without our permission and are subject to restocking charge. All items marked with an asterisk (*) have been declared non-returnable by the manufacturer and are not acceptable for credit. Items not shown are backordered. Claims for shortages must be made within 5 days.

SOLD TO SHIP TO

STORE	CUSTOMER NUMB	BER YOU	IR ORDER NUMBER	INVOICE DATE	INVOICE NUMBER	PAGE
				08-22-17		2
SHIP VIA			DOC.DAT	E	THE ENERGE HO.	
			07-12-1	7		
UNIT NUMBER	MAKE	MODEL	SERIAL NUMBER	METER READING	MACHINE	ID NO.
33	AA	3406E	02WS31734	192960.0		
QUANTITY	PART NUMBER	N/R	DESCRIPTION	UNIT PRICE	EXTENDED	PRICE

REMOVED THE A/C CONSOLE, UNPLUGGED THE ROCKER A/C ON/OFF SWITCH CHECK FOR SWITCH WORK WITH A MULTI METER AND NOTICED IT IS NOT MAKING ANY DIFFERENT WHEN THE SWITCH IS ON OR OFF. LOOK FOR PART NUMBER.

THERE IS ANOTHER PETERBILT IN THE SHOP WITH THE SAME A/C CONSOLE SO I REMOVED THE SWITCH AND

SAME A/C CONSOLE SO I REMOVED THE SWITCH AND INSTALLED IN THIS TRUCK CHECK FOR OPERATION AND IT WORKS GOOD. SO ORDERED A NEW SWITCH.

TOTAL LABOR LESS 70%-LABOR SEGMENT 02 TOTAL

SEG. 02

REMOVE, CLEAN & INSTALL EVAPORATOR COIL REMOVE KICK PANEL ON PASSENGER SIDE OF CAB. REMOVED HVAC COVER. REMOVED HIGH AND LOW PRESSURE LINES FROM EVAPORATOR. REMOVED THE EVAPORATOR. WASHED OUT THE EVAPORATOR. INSTALLED BACK INTO CAB. INSTALLED COVERS.

1 9X-7381 SEAL O RING S

DISCOUNT 10.00% 1 9X-7382 SEAL O RING S

DISCOUNT 10.00%

and select ABOUT U.S, FINANCE, and E-INVOICING
Payment Terms: Open Accounts: Parts, Service, & Rental Net 30; Machine sales Net 10; Installment contracts and leases per contract.

Open Accounts: Parts, Service, & Rental Net 30; M: COD Accounts: Payment due at time of purchase. Statements: Generated as of month end.

Credit Card: Payment via credit card is allowed at the time of purchase and only for Parts, Service, and Rentals. Credit card payment

will not be accepted for machine sales, including attachments; contracts; and leases.

PLEASE NOTE THE PAYMENT TERMS CHANGE ON PARTS, SERVICE & RENTAL ACCOUNTS EFFECTIVE 11-14-16. View the legal notice at butlermachinery.com, select ABOUT US, FINANCE, and PAYMENT TERMS NOTICE or contact us for a written copy.

Butler Machinery Company's service labor is warranted to the customer for a period of 90 days from the date of work, to include defects in workmanship performed by Butler Machinery employees. This warranty would include the replacement of parts and labor, damaged by that defect in workmanship.

Any failures caused by defect of parts, whether replaced now at the time of our work, or re-used, will be covered by the original manufacturer's applicable warranties, if any. Goods cannot be returned without our permission and are subject to restocking charge. All items marked with an asterisk (*) have been declared non-returnable by the manufacturer and are not acceptable for credit. Items not shown are backgrdered. Claims for shortages must be made within 5 days.



SOLD TO SHIP TO

STORE	CUSTOMER NUMBER	YOUR OR	RDER NUMBER	INVOICE DATE	INVOICE NUMBER	PAGE		
				08-22-17		3		
SHIP VIA			DOC.DA1	TE				
07-12-17								
UNIT NUMBER	MAKE	MODEL	SERIAL NUMBER	METER READING	MACHINE	ID NO.		
	AA 3406E 02WS31734 192960.0							
QUANTITY	PART NUMBER	N/R	DE SCRIPTION	ION UNIT PRICE EXTENDED				

TOTAL PARTS SEG. 03 TOTAL LABOR SEG. 03

SEGMENT 03 TOTAL 184.46 T

REPLACE AIR CONDITIONER ACCUMULATOR

REMOVED LINES FROM THE ACCUMULATOR, LOOSENED CLAMPS, REMOVED ACCUMULATOR. REMOVED THE ORIFICE FROM THE EVAPORATOR. INSTALLED A NEW ORIFICE. INSTALLED LINES WITH NEW O-RINGS. INSTALLED A NEW ACCUMULATOR. TIGHTENED CLAMPS, INSTALLED LINES WITH NEW O-RINGS. PULLED A VACUUM FOR ONE HOUR ON

THE SYSTEM. CHARGED WITH 3 LBS OF FREON.

9X-7383 SEAL O RING DISCOUNT 10.00%

S 1899003 Orifice Tube-Red 1917004 ACCUMULATOR 134A R134A FREON PER LBS

> TOTAL PARTS SEG. 04

Parts, Service, & Rental Net 30; Machine sales Net 10; Installment contracts and leases per contract. Payment Terms: Open Accounts:

COD Accounts: Payment due at time of purchase. Statements: Generated as of month end.

Payment via credit card is allowed at the time of purchase and only for Parts, Service, and Rentals. Credit card payment

will not be accepted for machine sales, including attachments; contracts; and leases.

PLEASE NOTE THE PAYMENT TERMS CHANGE ON PARTS, SERVICE & RENTAL ACCOUNTS EFFECTIVE 11-14-16. View the legal notice at butlermachinery.com, select ABOUT US, FINANCE, and PAYMENT TERMS NOTICE or contact us for a written copy

Butler Machinery Company's service labor is warranted to the customer for a period of 90 days from the date of work, to include defects in workmanship performed by Butler Machinery employees. This warranty would include the replacement of parts and labor, damaged by that defect in workmanship.

Any failures caused by defect of parts, whether replaced now at the time of our work, or re-used, will be covered by the original manufacturer's applicable warranties, if any. Goods cannot be returned without our permission and are subject to restocking charge. All items marked with an asterisk (*) have been declared non-returnable by the manufacturer and are not acceptable for credit. Items not shown are backordered. Claims for shortages must be made within 5 days.

> Please Pay This Amount



54.24 *

SOLD TO SHIP TO CUSTOMER NUMBER YOUR ORDER NUMBER INVOICE DATE INVOICE NUMBER STORE PAGE 08-22-17 4 SHIP VIA DOC.DATE REFERENCE NO. 07-12-17 MACHINE ID NO. UNIT NUMBER MAKE MODEL SERIAL NUMBER METER READING ΔΔ 3406F 02\W\$31734 192960.0 QUANTITY PART NUMBER N/R DESCRIPTION UNIT PRICE EXTENDED PRICE TOTAL LABOR SEG. 04 SEGMENT 04 TOTAL 175.24 T TROUBLESHOOT ENGINE FAN DRIVE COMPLAINT: ENGINE FAN IS NOT WORKING PROPERLY CAUSE: LOOSE PINS IN FAN SOLENOID PLUG IN CORRECTION: INSPECTED THE FAN WIRING HARNESS. PULLED ON WIRING FOR CONNECTOR. STARTED THE TRUCK, FAN IS ON, PUSHED ON THE CONNECTOR FOR THE SOLENOID, CAN GET THE FAN TO KICK IN AND OUT BY PUSHING AND PULLING ON THE SOLENOID CONNECTOR. NEED TO REPLACE THE PLUG IN. TOTAL LABOR SEG. 05 SEGMENT 05 TOTAL 72.60 T REPLACE FAN DRIVE CONNECTOR (S) AND SEIEGLADOUT US, FINANCE, AND E-INVOICING Payment Terms: Open Accounts: Parts, Service, & Rental Net 30; Machine sales Net 10; Installment contracts and leases per contract. Payment due at time of purchase. Generated as of month end. COD Accounts: Statements: Credit Card: Payment via credit card is allowed at the time of purchase and only for Parts, Service, and Rentals. Credit card payment will not be accepted for machine sales, including attachments; contracts; and leases. PLEASE NOTE THE PAYMENT TERMS CHANGE ON PARTS, SERVICE & RENTAL ACCOUNTS EFFECTIVE 11-14-16. View the legal notice at butlermachinery.com, select ABOUT U.S. FINANCE, and PAYMENT TERMS NOTICE or contact us for a written copy Butler Machinery Company's service labor is warranted to the customer for a period of 90 days from the date of work, to include defects in workmanship performed by Butler Machinery employees. This warranty would include the replacement of parts and labor, damaged by that defect in workmanship. Any failures caused by defect of parts, whether replaced now at the time of our work, or re-used, will be covered by the original manufacturer's applicable warranties, if any.

Please Pay This Amount

Goods cannot be returned without our permission and are subject to restocking charge. All items marked with an asterisk (*) have been declared non-returnable by the

manufacturer and are not acceptable for credit. Items not shown are backordered. Claims for shortages must be made within 5 days.

SOLD TO SHIP TO

STORE	CUSTOMER NUMBER	YOU	R ORDER NUMBER		INVOICE DA	ATE	INVOICE NUMBER	PAGE
	С				08-22-1	7		5
SHIP VIA				DOC.DATE				
				07-12-17	,			
UNIT NUMBER	MAKE	MODEL	SERIAL NUMB	BER	METE	R READING	MACHINE ID	NO.
33	AA	3406E	02WS317	34	19	92960.0		
QUANTITY	PART NUMBER	N/R	DESCRI	PTION	UN	IIT PRICE	EXTENDED F	PRICE
CUT OFF OLD DEUTSCH PIN AND RECEPTA SHOULD. 1 102-88 2 126-17 2 126-17 1 155-22	S AND SOCKETS ACLE. PLUGGED 302 767	IN. FAN IS RECPTACLE PIN SOCKET PLUG KIT	DISCOUNT S DISCOUNT S DISCOUNT S DISCOUNT PARTS	10.00% 10.00% 10.00% 10.00% SEG.				
		TOTAL SEGME	NT 06 TOTAL	SEG.	0.0		85.57 T	

TROUBLESHOOT ENGINE COOLING SYSTEM

FOR LEAKS

COMPLAINT: ENGINE HAS SLOW COOLANT LEAK

CORRECTION: INSPECTED COOLANT LINES, FOUND ONE

and select ABOUT US, FINANCE, and E-INVOICING
Parts, Service, & Rental Net 30; Machine sales Net 10; Installment contracts and leases per contract. Payment Terms: Open Accounts:

COD Accounts: Payment due at time of purchase. Statements: Generated as of month end.

Credit Card: Payment via credit card is allowed at the time of purchase and only for Parts, Service, and Rentals. Credit card payment

will not be accepted for machine sales, including attachments; contracts; and leases.

PLEASE NOTE THE PAYMENT TERMS CHANGE ON PARTS, SERVICE & RENTAL ACCOUNTS EFFECTIVE 11-14-16. View the legal notice at butlermachinery.com, select

ABOUT US, FINANCE, and PAYMENT TERMS NOTICE or contact us for a written copy.

Butler Machinery Company's service labor is warranted to the customer for a period of 90 days from the date of work, to include defects in workmanship performed by Butler Machinery employees. This warranty would include the replacement of parts and labor, damaged by that defect in workmanship.

Any failures caused by defect of parts, whether replaced now at the time of our work, or re-used, will be covered by the original manufacturer's applicable warranties, if any. Goods cannot be returned without our permission and are subject to restocking charge. All items marked with an asterisk (*) have been declared non-returnable by the manufacturer and are not acceptable for credit. Items not shown are backordered. Claims for shortages must be made within 5 days.

SHIP TO SOLD TO

STORE	CUSTOMER NUMB	BER	YOUR ORDER NUMBER	INVOICE DATE	INVOICE NUMBER	PAGE
				08-22-17		6
SHIP VIA			DOC.DA	TE		
			07-12-	17		
UNIT NUMBER	MAKE	MODEL	SERIAL NUMBER	METER READING	MACHINE I	D NO.
33	AA	3406E	02WS31734	192960.0		
QUANTITY	PART NUMBER	N/R	DE SCRIPTION	UNIT PRICE	EXTENDED	PRICE
VERY SMALL OIL/COOLAN AN OIL SAM	LEAK. FOUN T FILM MIXT PLE AND SEN	D THAT THE B URE ON THE I T TO LAB FRO SEG	ING THAT HAS A LOW BY TUBE HAS NSIDE OF IT. TOOK M TESTING. MENT 08 TOTAL		.00 T	
CAUSE: BRI CORRECTION COOLANT HO AS WELL AS COMPRESSOR AND ARE CR FUTURE FAI THE BOTTOM	COOLANT LE TTLE HOSES : DURING HE SES FOR THE THE HOSE R TO THE CYL ACKING, NEE LURES. INST OF THE THE IR COMPRESS 83 73 287	AKS, WORN LI AD GASKET RE BOTTOM OF T UNNING FROM INDER HEAD H D TO REPLACE ALLED NEW CO RMOSTAT HOUS OR TO THE CY CLAMP	PAIR, I FOUND THE HERMOSTAT HOUSING THE AIR LAVE RUB SPOTS, TO PREVENT OLANT HOSES ON SING AS WELL AS LINDER HEAD. S DISCOUNT 10.00% DISCOUNT 10.00% S DISCOUNT 10.00% INCH S DISCOUNT 10.00%			

and select ABOUT US, FINANCE, and E-INVOICING

Open Accounts: COD Accounts: Statements: Payment Terms: Parts, Service, & Rental Net 30; Machine sales Net 10; Installment contracts and leases per contract.

Payment due at time of purchase. Generated as of month end.

Credit Card: Payment via credit card is allowed at the time of purchase and only for Parts, Service, and Rentals. Credit card payment

will not be accepted for machine sales, including attachments; contracts; and leases.

PLEASE NOTE THE PAYMENT TERMS CHANGE ON PARTS, SERVICE & RENTAL ACCOUNTS EFFECTIVE 11-14-16. View the legal notice at butlermachinery.com, select ABOUT US, FINANCE, and PAYMENT TERMS NOTICE or contact us for a written copy

Butler Machinery Company's service labor is warranted to the customer for a period of 90 days from the date of work, to include defects in workmanship performed by Butler Machinery employees. This warranty would include the replacement of parts and labor, damaged by that defect in workmanship.

Any failures caused by defect of parts, whether replaced now at the time of our work, or re-used, will be covered by the original manufacturer's applicable warranties, if any. Goods cannot be returned without our permission and are subject to restocking charge. All items marked with an asterisk (*) have been declared non-returnable by the manufacturer and are not acceptable for credit. Items not shown are backordered. Claims for shortages must be made within 5 days.

SOLD TO SHIP TO

\$TORE .	CUSTOMER NUME	BER	YOUR ORDE	R NUMBER		INVOICE DATE	IN/	OICE NUMBER	PAGE
						08-22-17			7
SHIP VIA				DO	C.DATE				
07-12-17									
UNIT NUMBER	MAKE	MODEL		SERIAL NUMBER		METER REA	DING	MACHINE II	D NO.
33	AA	3406E		02WS31734		192960	0.0		
QUANTITY	PART NUMBER	N/R		DESCRIPTION		UNIT PRI	CE	EXTENDED	PRICE
6 5515- 42 5526-	250 100X50	2.50 II 1.00 II							
2.00		TOTA HOSE	AL PART AL LABO LABOR AL MISO	R S TXBL	SEG. : SEG. :	11			
				.1 TOTAL	JEG.	11	1	199.00 T	

TROUBLESHOOT WIRING HARNESS

COMPLAINT: COOLANT GAUGES DO NOT WORK, AC DOES NOT WORK, ENGINE WILL INTERMITTENTLY SHUT DOWN CAUSE: OEM HARNESS WORN THROUGH, KEYSWITCH RESULTANT DAMAGE: SENSORS, COMPRESSOR, ECM LOSING CONNECTION CORRECTION: BEGAN BY INSPECTING THE HARNESS, FOUND THE HARNESS RUBBED THROUGH BY THE ECM WHERE IT BRANCHES OFF TO THE FRONT OF THE ENGINE. NEED TO CUT WIRING, INSTALL DEUTSCH CONNECTOR, BUILD HARNESS TO GO TO THE FRONT OF THE ENGINE.

and select ABOUT US, FINANCE, and E-INVOICING

Open Accounts: COD Accounts: Payment Terms: Parts, Service, & Rental Net 30; Machine sales Net 10; Installment contracts and leases per contract.

Payment due at time of purchase. Generated as of month end.

Credit Card: Payment via credit card is allowed at the time of purchase and only for Parts, Service, and Rentals. Credit card payment will not be accepted for machine sales, including attachments; contracts; and leases.

PLEASE NOTE THE PAYMENT TERMS CHANGE ON PARTS, SERVICE & RENTAL ACCOUNTS EFFECTIVE 11-14-16. View the legal notice at butlermachinery.com, select ABOUT US, FINANCE, and PAYMENT TERMS NOTICE or contact us for a written copy.

Butler Machinery Company's service labor is warranted to the customer for a period of 90 days from the date of work, to include defects in workmanship performed by Butler Machinery employees. This warranty would include the replacement of parts and labor, damaged by that defect in workmanship.

Any failures caused by defect of parts, whether replaced now at the time of our work, or re-used, will be covered by the original manufacturer's applicable warranties, if any. Goods cannot be returned without our permission and are subject to restocking charge. All items marked with an asterisk (*) have been declared non-returnable by the manufacturer and are not acceptable for credit. Items not shown are backordered. Claims for shortages must be made within 5 days.



SOLD TO SHIP TO

				08-22-17	8
SHIP VIA			DOC.DATE		
UNIT NUMBER	UNIT NUMBER MAKE MODEL		SERIAL NUMBER METER READING		MACHINE ID NO.
33	AA	3406E	02WS31734	192960.0	
QUANTITY	PART NUMBER	N/R	DESCRIPTION	UNIT PRICE	EXTENDED PRICE

YOUR ORDER NUMBER

INSPECTED THE GROUNDS AND POWER WIRES BY THE ECM, INSPECTED BATTERY CABLES, CABLES ARE VERY CORRODED AND LOOSE. AFTER ALL REPAIRS WERE COMPLETE, WENT TO START THE TRUCK, WOULD NOT START. REMOVED THE OEM 70 PIN CONNECTOR AND CHECKED POWER AND GROUNDS, - DO NOT HAVE KEYSWITCH POWER. WIGGLED THE KEYSWITCH, DASH LIT UP, I NOW HAVE POWER AT PIN 70 - PLUGGED IN - STARTED TRUCK. NEED TO INSPECT KEYSWITCH.

CUSTOMER NUMBER

TOTAL LABOR LESS SEGMEN SEG. 12

491.26 T

INVOICE NUMBER

PAGE

INVOICE DATE

REPAIR TRUCK WIRING HARNESS

STORE

REMOVED THE ENGINE SIDE OF THE OEM WIRING HARNESS, CUT THE HARNESS BY THE ECM WHERE IT WAS RUBBING AND CORRODED. LAID OUT THE HARNESS, BUILT A NEW HARNESS. INSTALLED DEUTSCH CONNECTORS. WIRED IN THE AC COMPRESSOR AND COOLANT SENSORS. REMOVED THE WIRE SOMEONE HAD INSTALLED FROM THE CAB CONNECTION TO THE AC COMPRESSOR. REPAIRED THE ORIGINAL WIRE. RAN THE TRUCK, AC IS WORKING AS WELL AS COOLANT

and select ABOUT US, FINANCE, and E-INVOICING

Payment Terms: Open Accounts: Parts, Service, & Rental Net 30; Machine sales Net 10; Installment contracts and leases per contract.
Payment due at time of purchase.

COD Accounts: Payment due at time of purchase. Statements: Generated as of month end.

Credit Card: Payment via credit card is allowed at the time of purchase and only for Parts, Service, and Rentals. Credit card payment

will not be accepted for machine sales, including attachments; contracts; and leases.

PLEASE NOTE THE PAYMENT TERMS CHANGE ON PARTS, SERVICE & RENTAL ACCOUNTS EFFECTIVE 11-14-16. View the legal notice at butlermachinery.com, select ABOUT US, FINANCE, and PAYMENT TERMS NOTICE or contact us for a written copy.

Butler Machinery Company's service labor is warranted to the customer for a period of 90 days from the date of work, to include defects in workmanship performed by Butler Machinery employees. This warranty would include the replacement of parts and labor, damaged by that defect in workmanship.

Any failures caused by defect of parts, whether replaced now at the time of our work, or re-used, will be covered by the original manufacturer's applicable warranties, if any.

Goods cannot be returned without our permission and are subject to restocking charge. All items marked with an asterisk (*) have been declared non-returnable by the manufacturer and are not acceptable for credit. Items not shown are backgrdered. Claims for shortages must be made within 5 days.

Please Pay

This Amount

SOLD TO SHIP TO

STORE	CUSTOMER NUMBER	YOU	JR ORDER NUMBER		INVOICE DATE	INVOICE NUMBER	PAGE
	O022.0				08-22-17		9
SHIP VIA				DOC.DATE			
				07-12-17	7		
UNIT NUMBER	MAKE	MODEL	SERIAL NUM	BER	METER READING	MACHINE I	D NO.
33	AA 3406E		02WS31734		192960.0		
QUANTITY	PART NUMBER	N/R	DESCRI	PTION	UNIT PRICE	EXTENDED	PRICE
SENSORS. 1 102-8 5 126-1 5 126-1 1 155-2 2 1-197 10 5-025 7 5-029	767 768 265	Wire Loom	DISCOUNT S DISCOUNT S DISCOUNT	10.00%			
		TOTAL	PARTS LABOR ENT 13 TOTAL	SEG. SEG.		493.07 T	

REPLACE BATTERY CABLE

COMPLAINT: BATTERY CABLES WERE CORRODED.

CORRECTION: REMOVED GROUND CABLES FIRST. REMOVED POSITIVE SIDE CABLES NEXT, AND REPLACED WITH ALL NEW JUMPER CABLES FROM BATTERY TO BATTERY. THEN

and select ABOUT U.S., FINANCE, and E-INVOICING
Parts, Service, & Rental Net 30; Machine sales Net 10; Installment contracts and leases per contract. Payment Terms: Open Accounts:

COD Accounts: Payment due at time of purchase. Statements: Generated as of month end. Credit Card:

Payment via credit card is allowed at the time of purchase and only for Parts, Service, and Rentals. Credit card payment

will not be accepted for machine sales, including attachments; contracts; and leases.

PLEASE NOTE THE PAYMENT TERMS CHANGE ON PARTS, SERVICE & RENTAL ACCOUNTS EFFECTIVE 11-14-16. View the legal notice at butlermachinery.com, select ABOUT US, FINANCE, and PAYMENT TERMS NOTICE or contact us for a written copy.

Butler Machinery Company's service labor is warranted to the customer for a period of 90 days from the date of work, to include defects in workmanship performed by Butler Machinery employees. This warranty would include the replacement of parts and labor, damaged by that defect in workmanship.

Any failures caused by defect of parts, whether replaced now at the time of our work, or re-used, will be covered by the original manufacturer's applicable warranties, if any. Goods cannot be returned without our permission and are subject to restocking charge. All items marked with an asterisk (*) have been declared non-returnable by the manufacturer and are not acceptable for credit. Items not shown are backordered. Claims for shortages must be made within 5 days.



SOLD TO SHIP TO

	08-22-17					
SHIP VIA	HIP VIA DOC.DATE					
UNIT NUMBER	MAKE	MODEL	SERIAL NUMBER	METER READING	MACHINE ID NO.	
33	AA	3406E	02WS31734	192960.0		
QUANTITY	PART NUMBER	N/R	DESCRIPTION	UNIT PRICE	EXTENDED PRICE	

INSTALLED GROUND CABLES.

3 9-208

STORE

Battery Cable - BaS

YOUR ORDER NUMBER

TOTAL PARTS TOTAL LABOR SEG. 14 SEG. 14

238.65 T SEGMENT 14 TOTAL

INVOICE DATE

INVOICE NUMBER PAGE

REPLACE WATER TEMPERATURE SENSOR

CUSTOMER NUMBER

TWO

REMOVED THE WATER TEMP SENSOR THEN REPLACE BOTH SENSOR. HAD TO INSTALL THE RIGHT END IN ONE OF THE WIRES. INSTALLED THE SENSOR AND INSTALLED SOME

LOOM AROUND THE WIRES.

2- 144455 SENDER - TEMP N 1 144561 TEMPERATURE SENDERN

> TOTAL PARTS SEG. 15 F/R LBR

TEMP SENDER 2.00 0121933-0000 1.00 0121933-00003 TEMP SENDER

and select ABOUT US, FINANCE, and E-INVOICING

Open Accounts: COD Accounts: Payment Terms: Parts, Service, & Rental Net 30; Machine sales Net 10; Installment contracts and leases per contract.

Payment due at time of purchase. Generated as of month end.

Credit Card:

Payment via credit card is allowed at the time of purchase and only for Parts, Service, and Rentals. Credit card payment will not be accepted for machine sales, including attachments; contracts; and leases.

PLEASE NOTE THE PAYMENT TERMS CHANGE ON PARTS, SERVICE & RENTAL ACCOUNTS EFFECTIVE 11-14-16. View the legal notice at butlermachinery com, select ABOUT US, FINANCE, and PAYMENT TERMS NOTICE or contact us for a written copy.

Butler Machinery Company's service labor is warranted to the customer for a period of 90 days from the date of work, to include defects in workmanship performed by Butler Machinery employees. This warranty would include the replacement of parts and labor, damaged by that defect in workmanship.

Any failures caused by defect of parts, whether replaced now at the time of our work, or re-used, will be covered by the original manufacturer's applicable warranties, if any. Goods cannot be returned without our permission and are subject to restocking charge. All items marked with an asterisk (*) have been declared non-returnable by the manufacturer and are not acceptable for credit. Items not shown are backordered. Claims for shortages must be made within 5 days.



SOLD TO SHIP TO

STORE	CUSTOMER NUMBE	ER YOU	JR ORDER NUMBER	INVOICE DATE	INVOICE NUMBER	PAGE
	08-22-17					
SHIP VIA	DOC.DATE		TE			
07-12-17						
UNIT NUMBER	MAKE	MODEL	SERIAL NUMBER	METER READING	MACHINE ID NO.	
33	AA	3406E	02WS31734 192960.0			
QUANTITY	PART NUMBER	N/R	DESCRIPTION	UNIT PRICE	EXTENDED	PRICE

TOTAL MISC CHGS SEG. 15 SEGMENT 15 TOTAL

267.18 T

TROUBLESHOOT ENGINE COOLANT FOR LEAKS

INSPECTED COOLANT LINES, FOUND ONE LINE GOING TO THE THERMOSTAT HOUSING THAT HAS A VERY SMALL LEAK. FOUND THAT THE BLOW BY TUBE HAS OIL/COOLANT FILM MIXTURE ON THE INSIDE OF IT. TOOK AN OIL SAMPLE AND SENT TO LAB FROM TESTING. OIL SAMPLE CAME BACK POSITIVE FOR ANTIFREEZE. INSTALLED A GAUGE ON THE RADIATOR FILL. STARTED ENGINE AND IDLE FOR 3 TO 5 MINUTES, PRESSURES WENT TO 10 TO 15PSI. THEN RAN ENGINE AT FULL IDLE FOR 3 TO 5 MINUTES AND RESSURE GOT TO 25PSI AND BLEW A HOSE. THEN FIXED PRESSURE GOT THE HOSE DROVE TRUCK IN THE SHOP, DRAINED ENGINE OIL, REMOVED BOTTOM PROTECTION BRACKET, BOLTS WERE CORRODED SO I HAD TO TORCHED AROUND THE BOLT SO THE CORROSION GET LOOSE. REMOVED THE PROTECTION BRACKET THEN REMOVED OIL PAN. PRESSURIZED THE COOLANT SYSTEM TO 20 PSI THEN CHECK ANY COOLANT LEAK IN THE ENGINE, FOUND A COOLANT LEAK CYLINDER #4. IS LEAKING BY THE PISTON. SOSBTLNP NP POST BTL SD

and select ABOUT U.S. FINANCE, and E-INVOICING

Payment Terms: Open Accounts: Parts, Service, & Rental Net 30; Machine sales Net 10; Installment contracts and leases per contract.

Open Accounts: Parts, Service, & Rental Net 30; M: COD Accounts: Payment due at time of purchase. Statements: Generated as of month end.

Credit Card: Payment via credit card is allowed at the time of purchase and only for Parts, Service, and Rentals. Credit card payment

will not be accepted for machine sales, including attachments; contracts; and leases

PLEASE NOTE THE PAYMENT TERMS CHANGE ON PARTS, SERVICE & RENTAL ACCOUNTS EFFECTIVE 11-14-16. View the legal notice at butlermachinery.com, select ABOUT U.S. FINANCE, and PAYMENT TERMS NOTICE or contact us for a written copy.

Butler Machinery Company's service labor is warranted to the customer for a period of 90 days from the date of work, to include defects in workmanship performed by Butler Machinery employees. This warranty would include the replacement of parts and labor, damaged by that defect in workmanship.

Any failures caused by defect of parts, whether replaced now at the time of our work, or re-used, will be covered by the original manufacturer's applicable warranties, if any. Goods cannot be returned without our permission and are subject to restocking charge. All items marked with an asterisk (*) have been declared non-returnable by the manufacturer and are not acceptable for credit. Items not shown are backordered. Claims for shortages must be made within 5 days.



SOLD TO SHIP TO

STORE	CUSTOMER NUMBE	R YOU	JR ORDER NUMBER	INVOICE DATE	INVOICE NUMBER	PAGE
				08-22-17		12
SHIP VIA			DOC.DAT	TE		
07-12-17						
UNIT NUMBER	MAKE	MODEL	SERIAL NUMBER	METER READING	MACHINE I	D NO.
33	AA	3406E	02WS31734	192960.0		
QUANTITY	PART NUMBER	N/R	DESCRIPTION	UNIT PRICE	EXTENDED	PRICE

TOTAL PARTS SEG. 16 TOTAL LABOR T.F.S.S.

SEGMENT 16 TOTAL 514.15 T

REPLACE CYLINDER HEAD GASKET

COMPLAINT: COOLANT IN OIL, COOLANT SIDE IS BUILDING HIGH PRESSURES

CAUSE: PREVIOUS REPAIR IN DIFFERENT SHOP DID NOT

CUT COUNTER BORE CORRECTLY
RESULTANT DAMAGE: COOLANT IS BEING PUSHED IN
ENGINE OIL SIDE`

CORRECTION: REMOVED AIR TUBES, FROM RIGHT SIDE OF THE ENGINE, TURBO COMPRESSOR HOUSING, NOTICED SOME CRACK ON THE TURBO WHEEL, THEN REMOVED PEANUT COVER AND REMOVED CAMSHAFT GEAR, AND THE GEAR RIGHT NEXT TO IT. REMOVED WATER REGULATOR ASSEMBLY, REMOVED ALTERNATOR BELTS, LOWERED THE FAN SO THE CAM GEAR IS FREE TO GO. REMOVED ENGINE COVER THEN REMOVED ROCKET ARM.
REMOVED AND MARKED INJECTORS, REMOVED FUEL LINE
THEN REMOVED THE 26 BOLTS THAT HOLD THE HEAD.

and select ABOUT US, FINANCE, and E-INVOICING

Open Accounts: COD Accounts: Parts, Service, & Rental Net 30; Machine sales Net 10; Installment contracts and leases per contract. Payment Terms:

Payment due at time of purchase. Statements: Generated as of month end.

Credit Card: Payment via credit card is allowed at the time of purchase and only for Parts, Service, and Rentals. Credit card payment

will not be accepted for machine sales, including attachments; contracts; and leases.

PLEASE NOTE THE PAYMENT TERMS CHANGE ON PARTS, SERVICE & RENTAL ACCOUNTS EFFECTIVE 11-14-16. View the legal notice at butlermachinery.com, select ABOUT US, FINANCE, and PAYMENT TERMS NOTICE or contact us for a written copy.

Butler Machinery Company's service labor is warranted to the customer for a period of 90 days from the date of work, to include defects in workmanship performed by Butler Machinery employees. This warranty would include the replacement of parts and labor, damaged by that defect in workmanship.

Any failures caused by defect of parts, whether replaced now at the time of our work, or re-used, will be covered by the original manufacturer's applicable warranties, if any. Goods cannot be returned without our permission and are subject to restocking charge. All items marked with an asterisk (*) have been declared non-returnable by the manufacturer and are not acceptable for credit. Items not shown are backordered. Claims for shortages must be made within 5 days.



SOLD TO SHIP TO

STORE	CUSTOMER NUMB	ER Y	OUR ORDER NUMBER	ORDER NUMBER INVOICE DATE		PAGE	
				08-22-17		13	
SHIP VIA DOC.DATE							
	07-12-17						
UNIT NUMBER	MAKE	MODEL	SERIAL NUMBER	METER READING	MACHINE I	D NO.	
33	AA	3406E	3406E 02WS31734 192960.0				
QUANTITY	PART NUMBER	N/R	DE SCRIPTION	UNIT PRICE	EXTENDED	PRICE	

SLOWLY LIFTED THE HEAD, REMOVED THE HEAD. INSPECTED THE GASKET AND HEAD THEN I CLEANED THE HEAD, PLATE AND DECK. PLATE AND HEAD SURFACE WERE REALLY DIRTY. LOT OF RUST FROM COOLANT BUT I WAS ABLE TO REMOVED ALL THE DEBRIS. SANDBLASTED THE PLATE THEN I ORDERED FEW MORE PARTS. FINISHED CLEANING OFF THE DECK AND THE CYLINDER HEAD INSTALLED A NEW SPACER PLATE GASKET, WITH SEALANT ON EACH SIDE. INSTALLED OIL PRESSURE SEAL AS WELL AS THE DRAIN BACK SEAL. INSTALLED A NEW SPACER PLATE, INSTALLED ALL NEW COOLANT SEALS. A NEW HEAD GASKET AND OIL PRESSURE SEAL. INSTALLED ALL NEW COOLANT SEALS. INSTALLED INSTALLED CYLINDER HEAD. INSTALLED NEW CYLINDER HEAD BOLTS. TORQUED IN SEQUENCE. INSTALLED THE CAM SHAFT SEALING PLATE WITH NEW O-RINGS. INSTALLED ADAPTER AND PLATE AND TORQUED. INSTALLED THE CAM GEAR. INSTALLED CAM GEAR BOLTS AND TORQUED. PIN TIMED THE ENGINE, SET THE CAM GEAR TO TDC 1. INSTALLED IDLER GEAR. MEASURED BACK LASH -THE .010 - BACK LASH IS OK. INSTALLED IDLER GEAR BOLTS. TORQUED TO 22 FT LBS. INSTALLED A NEW PEANUT COVER SEAL. INSTALLED COVER. INSTALLED BOLTS. TORQUED TO 22 FT LBS. HOOKED UP RADIATOR SUPPORTS. INSTALLED THE THERMOSTAT HOUSING WITH A NEW GASKET AND LOWER HOSE AND CLAMPS. ADJUSTED ENGINE BELTS. TIGHTENED FAN HUB. INSTALLED ALTERNATOR BELTS, TIGHTENED BELTS. INSTALLED FRONT CYLINDER HEAD BOLTS. CLEANED OVER HEAD PARTS. PUT NEW O-RINGS ON INJECTORS. LUBED O-RINGS AND INSTALLED INJECTORS

and select ABOUT U.S. FINANCE, and E-INVOICING

Open Accounts: COD Accounts: Parts, Service, & Rental Net 30; Machine sales Net 10; Installment contracts and leases per contract. Payment Terms:

Payment due at time of purchase. Statements: Generated as of month end.

Credit Card: Payment via credit card is allowed at the time of purchase and only for Parts, Service, and Rentals. Credit card payment

will not be accepted for machine sales, including attachments; contracts; and leases.

PLEASE NOTE THE PAYMENT TERMS CHANGE ON PARTS, SERVICE & RENTAL ACCOUNTS EFFECTIVE 11-14-16. View the legal notice at butlermachinery com, select ABOUT US, FINANCE, and PAYMENT TERMS NOTICE or contact us for a written copy

Butler Machinery Company's service labor is warranted to the customer for a period of 90 days from the date of work, to include defects in workmanship performed by Butler Machinery employees. This warranty would include the replacement of parts and labor, damaged by that defect in workmanship.

Any failures caused by defect of parts, whether replaced now at the time of our work, or re-used, will be covered by the original manufacturer's applicable warranties, if any. Goods cannot be returned without our permission and are subject to restocking charge. All items marked with an asterisk (*) have been declared non-returnable by the manufacturer and are not acceptable for credit. Items not shown are backordered. Claims for shortages must be made within 5 days



SOLD TO SHIP TO

STORE	CUSTOMER NUMBER	YOU	JR ORDER NUMBER	INVOICE DATE	INVOICE NUMBER	PAGE
						14
SHIP VIA			DOC.DA1	DOC.DATE		
07-12-17						
UNIT NUMBER	MAKE	MODEL	SERIAL NUMBER	METER READING	MACHINE I	D NO.
33	AA	3406E	02WS31734	192960.0		
QUANTITY	PART NUMBER	N/R	DESCRIPTION	UNIT PRICE	EXTENDED	PRICE

WITH NEW HOLD DOWN BOLTS. TORQUED TO 40 FT LBS. BACKED OFF AND TORQUED AGAIN TO 40 FT LBS. PUT CLEAN ENGINE OIL ON VALVES. INSTALLED BRIDGES. PUT INJECTORS, AND CAM CLEAN ENGINE OIL ON BRIDGES, SHAFT. INSTALLED ROCKER ARM ASSEMBLIES, JAKE HOUSINGS. INSTALLED BOLTS AND NUT. INSTALLED TORQUED BOLTS AND NUT ON ALL HOUSINGS TO 40 FT LBS IN SEQUENCE. TORQUED AGAIN IN SEQUENCE TO 80 FT LBS. INSTALLED ALL OIL AND COOLANT LINES. INSTALLED THE VALVE COVER BASE WITH A NEW SEAL - PUT SEALANT ON LEFT REAR CORNER. INSTALLED BOLTS. TORQUED IN SEQUENCE TO 13 FT LBS. PLUGGED IN ENGINE BRAKES AND INSTALLED INJECTOR PLUG INS. INSTALLED PLUG IN HOLD DOWNS. TORQUED TO 22" LBS. PINNED ENGINE, SET OVERHEAD, ROLLED OVER 360 DEGREES. FINISHED SETTING THE OVER HEAD. INSTALLED THE VALVE COVERS WITH NEW SEALS AND BOLTS. TORQUED ALL VALVE COVERS IN SEQUENCE TO 13 FT LBS. PLUGGED IN ALL THE ELECTRICAL CONNECTIONS. FILLED THE ENGINE WITH 15-40 AND COOLING SYSTEM WITH ELC.

6I-4421 PLATE SPACER S

85-9191 BOLT 103-6045 SEAL

10 124-1854 BOLT 12PT

and select ABOUT US, FINANCE, and E-INVOICING

Payment Terms: Open Accounts: COD Accounts: Parts, Service, & Rental Net 30; Machine sales Net 10; Installment contracts and leases per contract.

Payment due at time of purchase. Statements: Generated as of month end.

Payment via credit card is allowed at the time of purchase and only for Parts, Service, and Rentals. Credit card payment Credit Card:

will not be accepted for machine sales, including attachments; contracts; and leases.

PLEASE NOTE THE PAYMENT TERMS CHANGE ON PARTS, SERVICE & RENTAL ACCOUNTS EFFECTIVE 11-14-16. View the legal notice at butlermachinery.com, select ABOUT US, FINANCE, and PAYMENT TERMS NOTICE or contact us for a written copy

Butler Machinery Company's service labor is warranted to the customer for a period of 90 days from the date of work, to include defects in workmanship performed by Butler Machinery employees. This warranty would include the replacement of parts and labor, damaged by that defect in workmanship.

Any failures caused by defect of parts, whether replaced now at the time of our work, or re-used, will be covered by the original manufacturer's applicable warranties, if any. Goods cannot be returned without our permission and are subject to restocking charge. All items marked with an asterisk (*) have been declared non-returnable by the manufacturer and are not acceptable for credit. Items not shown are backordered. Claims for shortages must be made within 5 days.



SOLD TO SHIP TO

STORE	CUSTOMER NUM	BER Y	OUR ORDER NUMBER	INVO	CE DATE	INVOICE NUMBER	PAGE
	3			08-	22-17	5	15
SHIP VIA			DC	C.DATE			
			07	-12-17		1010071	
UNIT NUMBE	ER MAKE	MODEL	SERIAL NUMBER		METER READING	MACHINE I	D NO.
33	AA	3406E	02WS31734		192960.0		
QUANTITY	PART NUMBER	N/R	DESCRIPTION		UNIT PRICE	- FXTENDED	PRICE
16 1	24-1855	BOLT 12F	PT S DISCOUNT				
12 2	38-8648	CAT ELC-	-1 GAL S DISCOUNT				
6 2	48-1394	KIT-GASE	KET-S S DISCOUNT				
1 4	58-3875	KIT GASE	KET S DISCOUNT				
	007913BR 295	15W40DEC ADHESIVE	D-ULS BRBLKS E ROLLER S				
		TOTAL	L PARTS	SEG. 17 F/R LBR			
		SEGM	MENT 17 TOTAL	2/10 2210		4782.72 T	

REMOVE& INSTALL ENGINE OIL PAN COMPLAINT: REMOVE OIL PAN TO INSPECT COOLANT LEAK CAUSE: HEAD GASKET FAILED CORRECTION: DRAINED OIL, REMOVED BOLTS FROM OIL

PAN, THEN DROP THE PAN, PETERBILT TRUCKS HAVE A BRACKET UNDERNEATH SO I HAD TO REMOVED THIS BRACKET. THE BOLTS WERE STUCK FULL OF CORROSION IN THE ALUMINUM BLOCK. WITH THE TORCH I HEAT UP THE AREA THEN USED AN IMPACT TO REMOVED THE BOLTS AND BREAK THE CORROSION. REMOVED OIL PAN THEN REMOVED

Payment Terms: Open Accounts:

and select ABOUT US, FINANCE, and E-INVOICING
Parts, Service, & Rental Net 30; Machine sales Net 10; Installment contracts and leases per contract.

Payment due at time of purchase. COD Accounts:

Generated as of month end. Credit Card:

Payment via credit card is allowed at the time of purchase and only for Parts, Service, and Rentals. Credit card payment

will not be accepted for machine sales, including attachments; contracts; and leases.

PLEASE NOTE THE PAYMENT TERMS CHANGE ON PARTS, SERVICE & RENTAL ACCOUNTS EFFECTIVE 11-14-16. View the legal notice at butlermachinery.com, select ABOUT US, FINANCE, and PAYMENT TERMS NOTICE or contact us for a written copy

Butler Machinery Company's service labor is warranted to the customer for a period of 90 days from the date of work, to include defects in workmanship performed by Butler Machinery employees. This warranty would include the replacement of parts and labor, damaged by that defect in workmanship.

Any failures caused by defect of parts, whether replaced now at the time of our work, or re-used, will be covered by the original manufacturer's applicable warranties, if any. Goods cannot be returned without our permission and are subject to restocking charge. All items marked with an asterisk (*) have been declared non-returnable by the manufacturer and are not acceptable for credit. Items not shown are backordered. Claims for shortages must be made within 5 days.

SOLD TO SHIP TO

				08-22-17	35 16
SHIP VIA			DOC.DATE).
			07-12-17		
UNIT NUMBER	MAKE	MODEL	SERIAL NUMBER	METER READING	MACHINE ID NO.
33	AA	3406E	02WS31734	192960.0	
QUANTITY	PART NUMBER	N/R	DESCRIPTION	UNIT PRICE	EXTENDED PRICE

YOUR ORDER NUMBER

GASKET. CLEANED OIL PAN. THE SEAL SURFACE WAS CLEANED ON THE BLOCK. THE OIL TUBES AND GIRDLE WERE CLEANED. THE PAN WAS WASHED NEXT. THE GIRDLE WAS INSTALLED TORQUED, THE TUBES HAD THE NEW SEALS PUT ON THEN THE TUBES WERE INSTALLED. AFTER THE BLOCK SURFACE WAS COTED IN RTV ON THE SEAMS TO PREVENT LEAKS THE PAN GASKET WAS INSTALLED AND THE PAN WAS PUT UP AND TORQUED. ALL TORQUES WERE FOR A 3/8 BOLT AT 37FTLBS.

CUSTOMER NUMBER

1R-1808 FILTER AS-LU DISCOUNT 4N-1151 GASKET DISCOUNT 109-0072 SEAL O RING DISCOUNT SEAL O RING 1 109-0078 DISCOUNT

> SEG. 18 TOTAL PARTS F/R LBR

SEGMENT 18 TOTAL 540.08 T

INVOICE DATE

INVOICE NUMBER

PAGE

REPLACE CYLINDER PACK

STORE

COMPLAINT: COOLANT IN THE ENGINE OIL

CAUSE: IMPROPER LINER PROTRUSION LED TO HEAD

and select ABOUT US, FINANCE, and E-INVOICING

Parts, Service, & Rental Net 30; Machine sales Net 10; Installment contracts and leases per contract. Payment Terms: Open Accounts:

COD Accounts: Payment due at time of purchase.

Generated as of month end. Credit Card:

Payment via credit card is allowed at the time of purchase and only for Parts, Service, and Rentals. Credit card payment

will not be accepted for machine sales, including attachments; contracts; and leases.

PLEASE NOTE THE PAYMENT TERMS CHANGE ON PARTS, SERVICE & RENTAL ACCOUNTS EFFECTIVE 11-14-16. View the legal notice at butlermachinery.com, select ABOUT US, FINANCE, and PAYMENT TERMS NOTICE or contact us for a written copy

Butler Machinery Company's service labor is warranted to the customer for a period of 90 days from the date of work, to include defects in workmanship performed by Butler Machinery employees. This warranty would include the replacement of parts and labor, damaged by that defect in workmanship.

Any failures caused by defect of parts, whether replaced now at the time of our work, or re-used, will be covered by the original manufacturer's applicable warranties, if any. Goods cannot be returned without our permission and are subject to restocking charge. All items marked with an asterisk (*) have been declared non-returnable by the manufacturer and are not acceptable for credit. Items not shown are backordered. Claims for shortages must be made within 5 days.

SOLD TO SHIP TO

STORE	COSTOMER NOME	LIX I IO	ON ONDER NOMBER	INVOICE DATE	INVOICE NUMBER	FAGE
				08-22-17		17
SHIP VIA			DOC.DAT	TE		
			07-12-1	7		
UNIT NUMBER	MAKE	MODEL	SERIAL NUMBER	METER READING	MACHINE	E ID NO.
33	AA	3406E	02WS31734	192960.0		
QUANTITY	PART NUMBER	N/R	DESCRIPTION	UNIT PRICE	EXTENDE	D PRICE
GASKET FAIL	TITER					

VALIB ARRED NUMBER

CORRECTION: REMOVED THE LINER. AFTER INSTALLING THE SHIM, CLEANED UP THE O-RING SEAT. LUBRICATED THE LINER O-RINGS AND INSTALLED IN CORRECT POSITIONS. PUT A CLEAN FILM OF ENGINE OIL ON THE O-RINGS. SOAKED THE TOP SEALING RING IN OIL THEN INSTALLED ON TO LINER. INSTALLED THE LINER, MAKING SURE TAB SIDE IS TOWARD THE PISTON COOLING JET. USED TOOLING TO PRESS IN THE LINER. INSTALLED NEW ROD BEARINGS. LUBRICATED BEARINGS, INSTALLED CAP, INSTALLED NEW BOLTS LUBRICATED WITH ENGINE OIL. OR-8915 CYL. PACK DISCOUNT

STORE CHSTOMER NUMBER

CORE CHARGE 1 N Ν 328-5573 BEARING-ROD DISCOUNT

> TOTAL PARTS SEG. 19 TOTAL LABOR SEG. 19 SEGMENT 19 TOTAL

877.38 T

CHECK ENGINE

and select ABOUT US, FINANCE, and E-INVOICING

Payment Terms: Open Accounts: COD Accounts: Parts, Service, & Rental Net 30; Machine sales Net 10; Installment contracts and leases per contract.

Payment due at time of purchase. Statements: Generated as of month end.

Credit Card: Payment via credit card is allowed at the time of purchase and only for Parts, Service, and Rentals. Credit card payment

will not be accepted for machine sales, including attachments; contracts; and leases.

PLEASE NOTE THE PAYMENT TERMS CHANGE ON PARTS, SERVICE & RENTAL ACCOUNTS EFFECTIVE 11-14-16. View the legal notice at butlermachinery.com, select ABOUT US, FINANCE, and PAYMENT TERMS NOTICE or contact us for a written copy.

Butler Machinery Company's service labor is warranted to the customer for a period of 90 days from the date of work, to include defects in workmanship performed by Butler Machinery employees. This warranty would include the replacement of parts and labor, damaged by that defect in workmanship.

Any failures caused by defect of parts, whether replaced now at the time of our work, or re-used, will be covered by the original manufacturer's applicable warranties, if any. Goods cannot be returned without our permission and are subject to restocking charge. All items marked with an asterisk (*) have been declared non-returnable by the manufacturer and are not acceptable for credit. Items not shown are backordered. Claims for shortages must be made within 5 days.

> Please Pav This Amount



INVOICE DATE INVOICE NUMBER DACE

SOLD TO SHIP TO

310	NL.	COSTOMER NOME	DER TO	OK OKDEK NOMBEK	INVOICE DATE	INVOICE NUMBER	PAGE
					08-22-17		18
SHIP VIA				DOC.DATE	E		
				07-12-1	7		
UNIT NU	IMBER	MAKE	MODEL	SERIAL NUMBER	METER READING	MACHINE	ID NO.
3	3	AA	3406E	02WS31734	192960.0		
QUANTIT	Y	PART NUMBER	N/R	DE SCRIPTION	UNIT PRICE	EXTENDE	D PRICE

LINER PROJECTION

AFTER CUTTING COUNTER BORE, INSTALLED A SHIM, INSTALLED THE LINER. INSTALLED THE SPACER PLATE GASKET AND SPACER PLATE, FOUND THAT #3 AND #5 HAVE MEASUREMENTS OF .005 - .006. INSTALLED A THICKER SHIM - MEASURED AGAIN - NOW SITTING AT .004 ON CYLINDER #4.

F/R LBR

SEGMENT 20 TOTAL

VALID ADDED MILMOED

151.25 T

INVOICE DATE INVOICE NUMBER DACE

INSTALL LINER SEAT/INSERT

STORE CUSTOMER NUMBER

FIRST ONE

COMPLAINT: CYLINDER #4 - LINER PROTRUSION WAS .007 TOO HIGH CAUSE: PREVIOUS SHOP THAT CUT COUNTER BORE DID NOT CUT DEEP ENOUGH RESULTANT DAMAGE: CRACKED HEAD GASKET CORRECTION: INSTALLED TOOLING ONTO CYLINDER #4 CUT FIRST LAYER OF COUNTER BORE. MEASURED DEPTH. CONTINUED CUTTING UNTIL I REACHED A SMOOTH
SURFACE, MEASURED AND CUT TO A DEPTH OF .063.
AFTER MEASURING LINER PROTRUSION, I FOUND THAT I
WAS AT .0025. CYLINDERS #3 AND #5 ARE BETWEEN .003

.006. INSTALLED A THICKER SHIM - MEASURED LINER PROTRUSION AGAIN - MEASUREMENTS ARE NOW AT .004.



Payment Terms: Open Accounts: COD Accounts:

Credit Card:

and select ABOUT US, FINANCE, and E-INVOICING

Parts, Service, & Rental Net 30; Machine sales Net 10; Installment contracts and leases per contract.

Payment due at time of purchase. Generated as of month end.

Payment via credit card is allowed at the time of purchase and only for Parts, Service, and Rentals. Credit card payment

will not be accepted for machine sales, including attachments; contracts; and leases.

PLEASE NOTE THE PAYMENT TERMS CHANGE ON PARTS, SERVICE & RENTAL ACCOUNTS EFFECTIVE 11-14-16. View the legal notice at butlermachinery.com, select ABOUT US, FINANCE, and PAYMENT TERMS NOTICE or contact us for a written copy

Butler Machinery Company's service labor is warranted to the customer for a period of 90 days from the date of work, to include defects in workmanship performed by Butler Machinery employees. This warranty would include the replacement of parts and labor, damaged by that defect in workmanship.

Any failures caused by defect of parts, whether replaced now at the time of our work, or re-used, will be covered by the original manufacturer's applicable warranties, if any. Goods cannot be returned without our permission and are subject to restocking charge. All items marked with an asterisk (*) have been declared non-returnable by the manufacturer and are not acceptable for credit. Items not shown are backordered. Claims for shortages must be made within 5 days.

SHIP TO SOLD TO

	CUSTOMER NUMB	ER	YOUR ORDER NUMBER	INVOICE DATE	INVOICE NUMBER PAG
				08-22-17	19
VIA			DOC.DA	ATE	
			07-12-		
UNIT NUMBER	MAKE	MODEL	SERIAL NUMBER	METER READING	MACHINE ID NO.
33	AA	3406E	02WS31734	192960.0	
QUANTITY	PART NUMBER	N/R	DESCRIPTION	UNIT PRICE	EXTENDED PRICE
1 6I-43 1 9Y-33		INSERT INSERT			
		TOTA LESS		6. 21 F/R LBR	
		SEG	MENT 21 TOTAL		250.94 T
COMPLAINT: LINE BEGIN CORRECTION THE REAR OF FUEL FILTE	NNING TO CRAC N: INSTALLED OF THE CYLINI CR HOUSING.	EMBLY I FOUN CK AND IS VE A NEW FUEL DER HEAD TO	ID THE FUEL RETURN RY BRITTLE RETURN LINE FROM THE SECONDARY		
COMPLAINT: LINE BEGIN CORRECTION THE REAR OF FUEL FILTE 30 9X-23	DURING ASSI NNING TO CRAC N: INSTALLED OF THE CYLINI ER HOUSING. 374	EMBLY I FOUN CK AND IS VE A NEW FUEL DER HEAD TO 1130 HO	RY BRITTLE RETURN LINE FROM THE SECONDARY OSE .406-8 S DISCOUNT		
COMPLAINT: LINE BEGIN CORRECTION THE REAR OF FUEL FILTE	DURING ASSI NNING TO CRAC N: INSTALLED OF THE CYLINI ER HOUSING. 374	EMBLY I FOUN CK AND IS VE A NEW FUEL DER HEAD TO	RY BRITTLE RETURN LINE FROM THE SECONDARY OSE .406-8 S DISCOUNT		

and select ABOUT US, FINANCE, and E-INVOICING

Open Accounts: COD Accounts: Payment Terms: Parts, Service, & Rental Net 30; Machine sales Net 10; Installment contracts and leases per contract.

Payment due at time of purchase. Generated as of month end. Statements:

Payment via credit card is allowed at the time of purchase and only for Parts, Service, and Rentals. Credit card payment will not be accepted for machine sales, including attachments; contracts; and leases. Credit Card:

PLEASE NOTE THE PAYMENT TERMS CHANGE ON PARTS, SERVICE & RENTAL ACCOUNTS EFFECTIVE 11-14-16. View the legal notice at butlermachinery.com, select ABOUT US, FINANCE, and PAYMENT TERMS NOTICE or contact us for a written copy.

Butler Machinery Company's service labor is warranted to the customer for a period of 90 days from the date of work, to include defects in workmanship performed by Butler Machinery employees. This warranty would include the replacement of parts and labor, damaged by that defect in workmanship.

Any failures caused by defect of parts, whether replaced now at the time of our work, or re-used, will be covered by the original manufacturer's applicable warranties, if any. Goods cannot be returned without our permission and are subject to restocking charge. All items marked with an asterisk (*) have been declared non-returnable by the manufacturer and are not acceptable for credit. Items not shown are backordered. Claims for shortages must be made within 5 days.



SOLD TO SHIP TO

STORE	CUSTOMER NUMB	ER YOU	R ORDER NUMBER	INVOICE DATE	INVOICE NUMBER	PAGE
15				08-22-17		20
SHIP VIA			DOC.DAT	E		
			07-12-1	7		
UNIT NUMBER	MAKE	MODEL	SERIAL NUMBER	METER READING	MACHINE I	D NO.
33	AA	3406E	02WS31734	192960.0		
QUANTITY	PART NUMBER	N/R	DE SCRIPTION	UNIT PRICE	EXTENDED	PRICE

SEGMENT 22 TOTAL 77.20 T

REPLACE TURBOCHARGER

COMPLAINT: EXHAUST WHEEL FINS AS WELL AS INTAKE

FINS WERE CHIPPED AND BENT

CAUSE: DEBRIS WENT THROUGH INTAKE AS WELL AS THE

EXHAUST

CORRECTION: REMOVED THE TURBO MOUNTING BOLTS, REMOVED THE TURBO. REMOVED THE INTAKE ELBOW. INSTALLED A NEW TURBO WITH NEW GASKETS, NUTS AND BOLTS. INSTALLED OIL DRAIN LINE WITH A NEW SEAL. PRE LUBED THE TURBO, INSTALLED PRESSURE LINE WITH A NEW SEAL. INSTALLED INTAKE ELBOW WITH NEW SEALS.

INSTALLED EXHAUST.

1 OR-7923

TURBO GP

DISCOUNT 10.00%

Ν

1 CORE CHARGE 1- CORE CREDIT

TOTAL DARTS SE

TOTAL PARTS SEG. 23 TOTAL LABOR SEG. 23

and select ABOUT US, FINANCE, and E-INVOICING

Payment Terms: Open Accounts: Parts, Service, & Rental Net 30; Machine sales Net 10; Installment contracts and leases per contract.

COD Accounts: Payment due at time of purchase. Statements: Generated as of month end.

Credit Card: Payment via credit card is allowed at the time of purchase and only for Parts, Service, and Rentals. Credit card payment

will not be accepted for machine sales, including attachments; contracts; and leases.

PLEASE NOTE THE PAYMENT TERMS CHANGE ON PARTS, SERVICE & RENTAL ACCOUNTS EFFECTIVE 11-14-16. View the legal notice at butlermachinery.com, select ABOUT U.S. FINANCE, and PAYMENT TERMS NOTICE or contact us for a written copy.

Butler Machinery Company's service labor is warranted to the customer for a period of 90 days from the date of work, to include defects in workmanship performed by Butler Machinery employees. This warranty would include the replacement of parts and labor, damaged by that defect in workmanship.

Any failures caused by defect of parts, whether replaced now at the time of our work, or re-used, will be covered by the original manufacturer's applicable warranties, if any. Goods cannot be returned without our permission and are subject to restocking charge. All items marked with an asterisk (*) have been declared non-returnable by the manufacturer and are not acceptable for credit. Items not shown are backgrdered. Claims for shortages must be made within 5 days.

Please Pay This Amount



2239.04

SOLD TO SHIP TO

STORE	CUSTOMER NUM	DER TO	JR ORDER NUMBER	INVOICE DATE	INVOICE NUMBER	PAGE
				08-22-17	i	21
SHIP VIA			DOC.DAT	E		
			07-12-1	7		
UNIT NUMBER	R MAKE	MODEL	SERIAL NUMBER	METER READING	MACHINE I	D NO.
33	AA	3406E	02WS31734	192960.0		
QUANTITY	PART NUMBER	N/R	DESCRIPTION	UNIT PRICE	EXTENDED	PRICE

SEGMENT 23 TOTAL 2432.64 T

REPLACE AIR CONDITIONER

CLUTCH SWITCH

COMPLAINT: A/C WORKS INTERMITTENT

CAUSE: SWITCH IS BAD

CORRECTION: REMOVED PANELS AROUND THE A/C SWITCH, REMOVED A/C SWITCH. WE HAD ANOTHER PETERBILT TRUCK IN THE SHOP SO I REMOVED THE SWITCH FROM THE TRUCK AND INSTALLED IN THIS ONE, PROBLEM GOT SOLVED SO I ORDERED A NEW SWITCH AND INSTALLED THE "TEST "
SWITCH BACK IN THE OTHER PETERBILT TRUCK. CUSTOMER
DECIDED HE WAS GOING TO INSTALL THE SWITCH. 1 51360 LOCTITE SILICONE LN

1.00 0123979-00001

TOTAL PARTS SEG. 24 TOTAL LABOR SEG. 24 ROCKER SWITCH TOTAL MISC CHGS SEG. 24 SEGMENT 24 TOTAL

199.48 T

and select ABOUT US, FINANCE, and E-INVOICING

Open Accounts: COD Accounts: Payment Terms: Parts, Service, & Rental Net 30; Machine sales Net 10; Installment contracts and leases per contract.

Payment due at time of purchase. Generated as of month end.

Credit Card: Payment via credit card is allowed at the time of purchase and only for Parts, Service, and Rentals. Credit card payment will not be accepted for machine sales, including attachments; contracts; and leases.

PLEASE NOTE THE PAYMENT TERMS CHANGE ON PARTS, SERVICE & RENTAL ACCOUNTS EFFECTIVE 11-14-16. View the legal notice at butlermachinery.com, select ABOUT US, FINANCE, and PAYMENT TERMS NOTICE or contact us for a written copy.

Butler Machinery Company's service labor is warranted to the customer for a period of 90 days from the date of work, to include defects in workmanship performed by Butler Machinery employees. This warranty would include the replacement of parts and labor, damaged by that defect in workmanship.

Any failures caused by defect of parts, whether replaced now at the time of our work, or re-used, will be covered by the original manufacturer's applicable warranties, if any. Goods cannot be returned without our permission and are subject to restocking charge. All items marked with an asterisk (*) have been declared non-returnable by the manufacturer and are not acceptable for credit. Items not shown are backordered. Claims for shortages must be made within 5 days.

Please Pav

This Amount

SOLD TO SHIP TO PAGE STORE CUSTOMER NUMBER YOUR ORDER NUMBER INVOICE DATE INVOICE NUMBER 08-22-17 22 SHIP VIA DOC.DATE 07-12-17 UNIT NUMBER MAKE MODEL SERIAL NUMBER METER READING MACHINE ID NO. 33 ΔΔ 3406E 02WS31734 192960.0 QUANTITY PART NUMBER N/R DESCRIPTION UNIT PRICE EXTENDED PRICE and select ABOUT US, FINANCE, and E-INVOICING
Parts, Service, & Rental Net 30; Machine sales Net 10; Installment contracts and leases per contract. Payment Terms: Open Accounts: COD Accounts: Payment due at time of purchase. Statements: Credit Card: Payment via credit card is allowed at the time of purchase and only for Parts, Service, and Rentals. Credit card payment will not be accepted for machine sales, including attachments; contracts; and leases. PLEASE NOTE THE PAYMENT TERMS CHANGE ON PARTS, SERVICE & RENTAL ACCOUNTS EFFECTIVE 11-14-16. View the legal notice at butlermachinery.com, select ABOUT US, FINANCE, and PAYMENT TERMS NOTICE or contact us for a written copy Butler Machinery Company's service labor is warranted to the customer for a period of 90 days from the date of work, to include defects in workmanship performed by Butler Machinery employees. This warranty would include the replacement of parts and labor, damaged by that defect in workmanship. Any failures caused by defect of parts, whether replaced now at the time of our work, or re-used, will be covered by the original manufacturer's applicable warranties, if any. Goods cannot be returned without our permission and are subject to restocking charge. All items marked with an asterisk (*) have been declared non-returnable by the manufacturer and are not acceptable for credit. Items not shown are backordered. Claims for shortages must be made within 5 days.

Please Pav

This Amount

\$13.217.07

INVOICE

INVOIC	
Invoice Date	Page
3/15/2018 14:31:14	1 of 1
ORDER NUM	MBER

Bill To:

Ship To:

Ordered By Customer ID: Ship to ID: PO Number Term Description Net Due Date Net 30 4/14/2018 Order Date Pick Ticket No Primary Salesrep Name Taker 3/15/2018 14:24:14 Quantities Pricing Item ID **UOM** Unit Extended UOM Unit Siz Item Description Price Price Ordered Shipped Remaining Unit Size Carrier: Will Call Tracking #: 1.00 1.00 0.00 EA 3139610768 EA 1.0 1.0000 PGP051A346***AL*20-65* 2.00 2.00 0.00 EA 6400-20-20 EA 1.0 1 1/4 MJ-1 1/4 ORB 1.0000 Total Lines: 2 SUB-TOTAL: SOUTH DAKOTA: SIOUX FALLS (SD): AMOUNT DUE: 746.20 U.S. Dollar

INVOICE DATE 01/27/2020 08:26AM PAGE 1 CUSTOMER NO

ALL CORES MUST BE RETURNED WITHIN 60 DAYS FOR CREDIT
ALL APPROVED NON-STOCKING PRODUCT RETURNS ARE SUBJECT TO A 20% RESTOCKING FEE PLUS ALL FREIGHT CHARGES 000/927 002216 NONE TERMS: (00) NET 10TH PROX COMPLETION DATE: 01/27/2020 MAKE/MODEL: PETE 379 UNIT: 33 YEAR: 1999 MILEAGE: 260781 SERIAL: 1XPFDB9XXYN508144 JOB#01 00 000 01 MISC REPAIR 43 (Y) - TRUCK REPAIR INSTALL POWERSTEERING SEAL ON INPUT SEAL IS NOT OUT IN INPUT, REAR OUTPUT SHAFT IS LOOSE ON SECTOR AND SEAL IS LEAKING BAD. REPLACE STEERING GEAR, DRAIN AND FLUSH SYSTEM. FILL SYSTEM, MAKE NEW PRESSURE LINE, HAS STEEL SHOWING WHERE LAYS ON FRAME, WRAP HOSES. RUN AND CHECK, ADJUST STOPS BACK UP ON SECTOR REMAN STEERING \$1096.11 EXC 1 PS RTAS65024R STEERING GEAR C \$1500.00 CHG 1 PS RTAS65024R-C1 STEERING GEAR CORE RTAS65024R-C1 SAE 45 FEMALE SWIVEL \$15.12 1 GYH FG-SFFX-0808 SAE FEMALE SWV-90 ELB \$53.61 1 PA 27920-8-8 #8 100R5 BRAIDED HOSE \$10.60 2 GYH DR5-08X250 \$1.23 SILICONE HOSE CLAMP BRE 9210 POWER STEERING FLU \$6.78 4 CRP 501959 PARTS SUBTOTAL LABOR SUBTOTAL SHOP SUPPLIES - EPA 1150.63 ** JOB SUBTOTAL JOB#02 01 000 00 BRAKE INSPECTION AND OR REPAIR 43 (Y) - TRUCK REPAIR REMOVE RIGHT REAR WHEELS, DRUM ETC. INSTALL BRAKE SHOES AND HARDWARE 685 EATON BRAKE S EXC 2 WH RSEXP4311E CHG 4311 EATON CORE 2 WH CLASS02-C1 4311 EATON CORE RET 2-WH CLASS02-C1 BRAKE KIT(4311) \$16.29 1 EU E4311EHDN PARTS SUBTOTAL LABOR SUBTOTAL SHOP SUPPLIES - EPA 170.95 ** JOB SUBTOTAL JOB#03 00 000 01 MISC REPAIR Buyer agrees to pay 1 1/2% service charge per month (18% per annum), on accounts paid after due date, with a minimum service charge of \$1.00. Errors subject to correction TAX STATUS/STATE SALES TAX *CONTINUED* I hereby authorize the repair work hereinafter set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of sire, theft or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby

SIVUA FALLS

CUSTOMER'S SIGNATURE

acknowledged on above vehicle to secure the amount of repairs thereto.

INVOICE DATE 01/27/2020 08:26AM PAGE 2 CHICTOMED NO. BRANCH

ALL CORES MUST BE RETURNED WITHIN 60 DAYS FOR CREDIT
ALL APPROVED NON-STOCKING PRODUCT RETURNS ARE SUBJECT TO A 20% RESTOCKING FEE PLUS ALL FREIGHT CHARGES NONE 002216 000/927

39 (Y) - PREVENTIVE MAINT TRUCK HAS COLD LEAK, CHECK AND REPAIR AS NEEDED. BYPASS HOSE TO THERMOSTAT HAS COLD LEAK AT BYPASS HOSE, TIGHTENED CLAMPS CHECK AND FILL COOLANT 4 PST AFC12100-55 (SHOP)

> ANTIFREEZE 50/50 NO NI \$6.47 PARTS SUBTOTAL LABOR SUBTOTAL ** JOB SUBTOTAL

> > *TOTAL PARTS: *TOTAL LABOR:

*TOTAL SHOP SUPPLIES - EPA:

WE NOW HAVE A FULL SERVICE DRIVELINE SHOP!!!

Buyer agrees to pay 1 1/2% service charge per month (18% per annum), on accounts paid after due date, with a minimum service charge of \$1.00. Errors subject to correction

SUBTOTAL TAX STATUS/STATE

1396.68

I hereby authorize the repair work hereinafter set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsowhere for the purpose of testing ancion inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereby.

CUSTOMER'S SIGNATURE

127 INVOICE DATE 07/27/2020 03:26PM 127 INVOICE NO. PAGE 1 135 CUSTOMER NO. BRANCH \$ 1

Phone (952) 373-8130

SHIP TO:

ALL CORES MUST BE RETURNED WITHIN 60 DAYS FOR CREDIT ALL APPROVED NON-STOCKING PRODUCT RETURNS ARE SUBJECT TO A 20% RESTOCKING FEE PLUS ALL FREIGHT CHARGES (605) 999-6302 JASON J 977739 47 002/47 TRK 33 000 TERMS: (00) NET 10TH PROX 1 TA 03-1001C SANDEN COMPRESSOR/03- 539.85 ORDER PICKED BY E. Buyer agrees to pay 1 1/2% service charge per month (18% per annum), on accounts paid after due date, with a minimum service charge of \$1.00. Errors subject to correction TAX STATUS/STATE 2 299.45 I hereby authorize the repair work hereinafter set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto.

CUSTOMER'S SIGNATURE