



Work Order

Date

11/14/2020

Name / Address

Year/Make	Mechanic In...	Vin	Odometer	Plate #
2012 F-450	KR	1FDTF4GT1CEA71116	128705	

Quantity	Description	Price	Total
1	Turbo - Ford # BC3Z-6K682-B		
1	Refurbished Exhaust Particulate filter		
10.1	Labor- Diagnose and replace turbo and exhaust particulate filter due to turbo failure.		
  <i>OK # 13814</i>			
		Sales Tax (7.375%)	
<p>All Cars after 200 miles of a tire rotation, tire repair or tire installation Should have lug nuts re-torqued to proper specs</p>		Total	\$4,142.23

Signature _____

Phone #