

Page 2 of 2 Invoice 5170 Estimate Ref #0 Date Printed: 02/11/2021 Printed Time: 10:22 am CELL 660 909 6000 Hat/Ref: Time Promised: 2007 GMC YUKON XL 1500 DENALI 6.2 VIN: 1GKFK66877J354370 License: BE9H9F Mileage In: 243,193 02/09/2021 Date Written: Unit #: Mileage Out: 243,193 Written By: DONE DOM: Save Old Parts: No Part 61323 EXHAUST PIPE GASKET Part A104531CK ROTOR KIT 6L50/80/90 Part 195752A 6L80 FRICTION MODULE COMPLETE Part D104750B BELL/HSG/PUMP BODY, 6L80 Part 25999420 COOLER LINE SET OF Part 15779543 COOLER HOSE Part SI2KIT CABLE REPAIR BUSHING .414 HOLE IF YOU WERE HAPPY WITH OUR SERVICE, SEND SOME KIND WORDS TO KITLINDSAY@CENTURYLINK.NET AND WE WILL POST YOUR TESTIMONY TO OUR WEB PAGE AND FACEBOOK, ALSO PLEASE CONSIDER POSTING A FAVORABLE REVIEW ON GOOGLE! OUR BUSINESS GROWS FROM REFERRALS FROM OUR HAPPY CUSTOMERS. WE APPRECIATE YOU SENDING YOUR FRIENDS AND LOVED ONES SO WE CAN SOLVE THEIR TRANSPORTATION NEEDS! WARRANTY: 36 MONTH/100,000 MILES. VEHICLE MUST BE INSPECTED ANNUALLY OR EVERY 12,000 MILES. WARRANTY VOID IF THE TRANSMISSION IS SERVICED BY ANY FACILITY NOT APPROVED BY LINDSAY TRANSMISSION SERVICE IN ADVANCE. FIRST SERVICE DUE AT 50,000 MILES POST OVERHAUL FOR WARRANTY TO REMAIN IN EFFECT. WE WANT YOUR TRANSMISSION TO LAST FOREVER! Parts: Payment Date Type Method Amount Labor: Sublet: 2/11/2021 Check #1159 Misc: Payment Totals: Discount: Hazmat: Supplies: Tax Total: Invoice Total: \$4,749.68 Less Paid: Balance Due: