

Purchase order
UNIT #506

Ship Via: SHOP REPAIR

Date
10-06-20

Job Number

Job Contact
NATE

Vermeer Parts Manual Page Reference, 6-3

REMOVED AND REPLACED ATTACHMENT PUMP ASSY
REASSEMBLED AND TESTED

HAD TO DRAIN AND CLEAN OUT TANK MULT TIMES
TANK FULL OF BRASS DEBRIS
FLUSHED SYSTEM MULT TIMES

3	08880	BRAKE CLEAN
1	10643-8-8	1/2 IN FEMALE JI
1	13943-8-8	JIC 1/2 IN 90 DE
2	HOSE-8	1/2 HOSE 3000 PS
1	220075001	FLANGE - 65 FLE-
1	224297001	HUB - FLE65 SERI
1	265981001	PUMP-SAUER 90 SE
1	268966001	NEUTRAL START SW
1	FREIGHT	
2	COTTER PIN	
14	ZIPTIES	

Total Labor

Total for segment

Seg# 008 Mfr:VER Model:RTX1250

S/N:308

Meter: 2663

Equip ID:RTX1250-0308

Equipment Wash

4.00 Hours

SHOP LABOR

Total for segment

Amount

Continued

CAP-RUBBER TIRE

Ship Via: SHOP REPAIR

Purchase order
UNIT #506Date
10-06-20

Job Number

Job Contact
NATE

Seg# 009 Mfr:VER Model:RTX1250

S/N:308

Meter: 2663

Equip ID:RTX1250-0308

Hydraulic Oil Filter (All) R&R CMP
Remove hydraulic filter(s) including o-ring/gasket
Label new filter(s) with machine hours, date, and install
Test run machine and inspect for leaks
Top off hydraulic fluid as needed

2	52F1561	HOSE CLAMP
1	LUB 1025	POWER SERVICE FU
2	296387478	FILTER ELEMENT -
2	64101001	STRAINER SUCTION
4	81902001	FILTER OIL
1	FREIGHT	

Total

Total for segment

0
Total partsSub Total 9,477.00
0.00

EXEMPT03

EXEMPT IOWA INTERNAL/WARRANTY
Sales Tax Number -