

Repair Order #6335

Day Phone

Vehicle : 2006 GMC Truck C5500 2 Ton Truck 6.6 L 403 CID V8

VIN : 1GDE5C1286F407154

Last Mileage : 187435

Created : 4/18/2018 10:25:14 AM

Odometer In : 193420

Complete : 5/4/2018 10:10:06 AM

Odometer Out : 193461

Labor/Notes

Qty	Code/Tech*	Description	Unit Price	Price
12	LH*	LABOR		
TRUCK BROUGHT IN FOR CODE P0087. TRUCK WOULD GO INTO LIMP MODE WHEN TOWING. REMOVED ALL 8 INJECTORS AND HAD THEM TESTED AT M&D. ALL 8 INJECTORS FAILED THE RETURN RATE TESTS. INSTALLED 8 NEW INJECTORS. REPLACED THE FUEL FILTER. REPLACED INJECTOR RETURN LINE ASSEMBLY ON PASSENGER SIDE, IT BROKE WHEN DISSASSEMBLING THE INJECTORS.				

Parts

Qty	Code/Tech*	Description	Condition	Unit Price	Price
1	LH*	AC DELCO FUEL FILTER			
8	LH*	BOSCH INJECTOR			
0	LH*	CORE CHARGE			
1	LH*	INJECTOR RETURN HOSE			

Sublet/Misc.

Qty	Code/Tech*	Description	Unit Price	Price
8	LH*	TEST INJECTORS		
INJECTOR TESTING				

Labor

Parts

Sublet/Misc.

Shop Supplies

Charges

Sales Tax

Repair Total

\$4,938.19

Tech

Certification #

LH

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that _____ is not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond our control. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express garage keeper's lien is hereby acknowledged on above vehicle to secure the amount or repairs thereto.

Customer Signature _____