

Part ID	Description	Qty	Unit Price	Total
2219392	Gasket - Cylinder Head, Engine	1.00		
242-1811	Cap - Bolt Cat	2.00		
242-1811	Cap - Bolt Cat	24.00		
256-2209	Seal - O-Ring	1.00		
5P5678	Gasket - Rocker Arm Cover (Valve Cover	1.00		
283-2238	Gasket - Exhaust Manifold	6.00		
248-0840X	Mounting Gasket - Turbocharger	1.00		
210-4460	Cap - Bolt CAT Head	8.00		
EC50PLA	Clamp - Exhaust System	1.00		
9X-6620	Nut - Stud,	12.00		
9X-6620	Nut - Stud,	4.00		
10R-2602	Cylinder Head	1.00		
230-3518	Seal - Intake Manifold	1.00		
1056004	Engine Oil - 10w 30	6.00		
197-8418	Gasket - Oil Line, Turbocharger	2.00		
197-8419	Gasket - Drain, Turbochager	2.00		
8T-0644	Bolt - Injector holddown	3.00		
8T-0644	Bolt - Injector holddown	3.00		

Priority: 0 Rep Reason: INSPECTION
 Complaint: WORN OUT Comments:
 Conditioning Assembly - Complete AIR CONDITIONING ASSEMBLY - COMPLETE

Comment Text

a/c lines into a/c comp wore out.

Invoice No: IN-000000084

Opies Transport, Inc

Part Charges

Customer: GOTELD

PO No:

Unit: GO120

Part ID	Description	Qty	Unit Price	Total
2219392	Gasket - Cylinder Head, Engine	1.00		
242-1811	Cap - Bolt Cat	2.00		
242-1811	Cap - Bolt Cat	24.00		
256-2209	Seal - O-Ring	1.00		
5P5678	Gasket - Rocker Arm Cover (Valve Cover	1.00		
283-2238	Gasket - Exhaust Manifold	6.00		
248-0840X	Mounting Gasket - Turbocharger	1.00		
210-4460	Cap - Bolt CAT Head	8.00		
EC50PLA	Clamp - Exhaust System	1.00		
9X-6620	Nut - Stud,	12.00		
9X-6620	Nut - Stud,	4.00		
10R-2602	Cylinder Head	1.00		
230-3518	Seal - Intake Manifold	1.00		
1056004	Engine Oil - 10w 30	6.00		
197-8418	Gasket - Oil Line, Turbocharger	2.00		
197-8419	Gasket - Drain, Turbochager	2.00		
8T-0644	Bolt - Injector holddown	3.00		
8T-0644	Bolt - Injector holddown	3.00		

: 31

Priority: 0

Rep Reason: INSPECTION

ent: 001-001

Complaint: WORN OUT

Comments:

Desc: Air Conditioning Assembly - Complete

AIR CONDITIONING ASSEMBLY - COMPLETE

n:

:

ts Comment Text

a/c lines into a/c comp wore out.

replaced expansion valve and a/c drier

rges

Description	Hours	Rate	Total
-------------	-------	------	-------

Shop Labor	2.48		
------------	------	--	--

es

Part ID	Description	Qty	U
---------	-------------	-----	---

LF0111	Compressor - Air Conditioning	1.00	
--------	-------------------------------	------	--

HE3929	Hose Assembly - A/C	1.00	
--------	---------------------	------	--

RF737750715	Hose Assembly - A/C	1.00	
-------------	---------------------	------	--

EA10660	Expansion Valve Assembly - HVAC System	1.00	
---------	--	------	--

R134A	Refrigerant - Air Conditioner	3.00	
-------	-------------------------------	------	--

RF41800651	Receiver - Dehydrator Assembly	1.00	
------------	--------------------------------	------	--

Invoice No: IN-000000666

PO No:

Unit: GO120

install new driver seat.

Labor Charges

Description

Hours

Rate

Total

Shop Labor

1.28

Part Charges

Part ID

Description

Qty U

715-1500

Line - Coiled, Air for cab blow gun

1.00

90-488

Air Gun Blower Nozzle

1.00

5300001-905

Seat Assembly-GO

1.00

Total Parts Issued:

Total Labor Hours:

Total Part Charges: \$

Total Labor Charges:

Total Service Charges:

Repair Total: \$

Taxes:

Fees:

Discount:

Invoice Total: \$

Amt Paid:

Balance Due: \$ 1,699.61

