2/5/2021 Work Orders

Ship To

IN STORE PICKUP Date Time Page 02/05/21 15:49:35 (o) 01 **Phone Number** Invoice Number **Customer Number** Sold To **CUST CELL PHONE #** Purchase Order Farm/Sales Tax Exemption # Tax ID Ex Date Salesperson 066 Description STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS 5600 TOOLCAT 520512230 E011785 3333 5600 \*\*\*\*\* UNIT DESCRIPTION \* \* MISCBASE 5600 TOOLCAT SEGMENT# 1 5 067 12/03/20 12/03/20 2.00 REPAIR COMPLAINT: HYD LEAK PIN ON FRONT LOADER NEEDS REPLACED CAUSE: HYDRAULIC LEAK CAUSED BY WORN STEERING HOSES RUBBING FRAME RAIL AND PACKED WITH DIRT/MUD UNDER CAB, ALSO FOUND BOOM CYLINDER AND TILT CYLINDER LEAKING, SEALS HAVE FAILED INTERNALLY ON CYLINDERS. PIN ON WORKGROUP HAS ALSO BROKEN. CORRECTION: VERIFIED COMPLAINT. LEAKS WERE FOUND BY OTHER TECHS: SHAWN, JOSH AND HOOPER. NOT FOR SURE WHAT ALL THEY REPLACED AND OR DID BUT I PUT THE MACHINE BACK TOGETHER INCLUDING INSTALLING THE GATEWAY, TIGHTENING UP SEVERAL HOSES, INSTALLING A FEW PLUGS IN THE CYLINDERS, REINSTALLING THE SEATS AND FIXING THE WIRING FOR THE SEAT BAR DETENT. ADDITIONAL DESCRIPTION: **HAT 147** MACHINE IS UNLOCKED MACHINE CAME WITH FORKS MACHINE HAS NO ACTIVE FIELD MODS MACHINE HAS NO ACTIVE WARRANIES FREIGHT 1CM1070 1 N BOLT CONTINUED ON PAGE 02 Ship To Location IN STORE PICKUP Date Time Page 02/05/21 15:49:35 (o) 02 Phone Number **Customer Number** Invoice Number W24370 Sold To **CUST CELL PHONE #** Purchase Order Farm/Sales Tax Exemption # Tax ID Ex Date Salesperson

Location

	Description			
STK#/FLEET#	HRS PIN/FIN	WARRANTY DATE	HRS	

2/5/2021		We	ork Orders	
E011785	5600 TOOLCAT 5600	3333 520512230		
53DM10 59CM1240 6806124 6813408 6814053 6814055 6983128 7135559	52120201	NUT BOLT HEAD PIN LINKAGE HOSE HOSE ANTI-FREEZE PG KIT	2 1 1 N 1 N 1 N 1 N 3 2 PARTS LABOR SEGMENT TOTAL==>	
			PARTS LABOR PICK UP AND DEL OK CITY TAX OK STATE TAX TOTAL CREDIT CARD	WORK ORDER TOTALS ****** 2560.47

Print E-mail

Close

## Invoice Reprint

INVOICE #	02088531
LOCATION	02
DATE	10/21/20
PAGE	1 OF 2

### 

ORDER NUMBER ORDER DATE JOB NUMBER	CUSTOMER P/O NUMBER	FREIGHT TERMS
02113132   07/21/20		Allow
WRITTEN BY	CUNTACT	SHIP VIA Customer Pickup
PAYMENT TERMS Charge Net/30		F.O.B.

PRODUCT/DESCRIPTION QUANTITY QUANTITY QUANTITY PRICE U/M EXTENSI
--

Model : 5600-U

TURBO TOOLCAT WORK MACHINE F-SERIES

Ein: 0707584 Serial#: 520512230 Meter: 3318

-----> Description Of Repair Job A <-----

REPAIRS PER LIST

-----> Solution Of Repair Job A <-----

CUSTOMER WOULD LIKE COMPLETE SERVICE DONE AS WELL AS HYDRAULIC LEAKS REPAIRED. UPON INSPECTION FOUND ONE STEERING HOSE LEAKING, ONE HOSE TO THE JOYSTICK, AND ONE WORK VALVE LEAKING. REPLACED BOTH HYDRAULIC HOSES, SERVICED AND GREASED COMPLETELY. ALSO REPLACED ALL FOUR TIRES, AND TEST RAN MACHINE. EVERYTHING LOOKS AND WORKS GREAT NOW.

THANK YOU AND WE APPRECIATE YOUR	BUSINESS!		
6988685	1	1	0
KIT, SEAL JACK			
6815737	1	1	0
HOSE			
6815740	1	1	0
HOSE			
6675517	1	1	0
OIL FILTER-12			
6667352	1	1	0
FILTER-12			
6666334	1	1	0
AIR FILTER INNER			

# Invoice Reprint

INVOICE #	02088531
LOCATION	02
DATE	10/21/20
PAGE	2 OF 2

ORDER NUMBER	ORDER DATE	JOB NUMBER	CUSTOMER P/O NUME	BER	FREIGHT TERMS
02113132	07/21/20				Allow
					SHIP VIA Customer Pickup
PAYMENT TERMS Charge Net/3	-		_		F.O.B.

PRODUCT/DESCRIPTION	QUANTITY OPEN	QUANTITY SHIPPED	QUANTITY BACKORDERED	PRICE	U/M	EXTENSION
6666333	1	1	0			
AIR FILTER OUTER						
6668819	1	1	0			
HYDRAULIC FILTER HI-FLOW						
6516722	1	1	0			
HYDRAULIC FILTER						
7023289	4	4	0			
TIRE - 27X10.5X						
6686872	2	2	0			
WHEEL, RIM 15X8						
PTS-FREIGHT	1	1	0			
Freight						
1614765	4	4	0			
VALVE STEM						
SVC-ES-BT	1	1	0			
Service - Expendable Supplies						
SVC-EC-BT	1	1	0			
Service - Environmental Charge						
LABOR						
Signature		Print Na	me			

Signature \_\_\_\_\_ Print Name \_\_\_\_\_

### 0815

MERCHANDISE TOTAL	FREIGHT & MISC	TAX	TOTAL CHARGES	DEPOSIT BALANCE	DEPOSIT APPLIED	DEPOSIT AMOUNT	INVOICE TOTAL
	'		5,658.40				5,658.40

Ship To: IN STORE PICKUP

Invoice To:

Branch		
	*REPR	INT
Date	Time	Page
02/08/21	23:30:20	(B) 01
Account No.	Phone No.	Invoice No.
	'	W24370
Ship Via	Purchase	
		Salesperson

#### SERVICE INVOICE

STK#/FLEET#

HRS PIN/EIN

WARRANTY DATE

HRS

E011785

5600 TOOLCAT

3333 520512230

5600

Storage Fee of \$100 per month after 30 days upon completion of service

SEGMENT# 1 C 067 NA

12/03/20 12/03/20

REPAIR

13.27 HRS

COMPLAINT:

HYD LEAK

PIN ON FRONT LOADER NEEDS REPLACED

CAUSE:

HYDRAULIC LEAK CAUSED BY WORN STEERING HOSES RUBBING FRAME RAIL AND PACKED WITH DIRT/MUD UNDER CAB, ALSO FOUND BOOM CYLINDER AND TILT CYLINDER LEAKING, SEALS HAVE FAILED INTERNALLY ON CYLINDERS. PIN ON WORKGROUP HAS ALSO BROKEN. CORRECTION:

VERIFIED COMPLAINT. LEAKS WERE FOUND BY OTHER TECHS: SHAWN, JOSH AND HOOPER. NOT FOR SURE WHAT ALL THEY REPLACED AND OR DID BUT I PUT THE MACHINE BACK TOGETHER INCLUDING INSTALLING THE GATEWAY, TIGHTENING UP SEVERAL HOSES, INSTALLING A FEW PLUGS IN THE CYLINDERS, REINSTALLING THE SEATS AND FIXING THE WIRING FOR THE SEAT BAR DETENT.

ADDITIONAL DESCRIPTION:

HAT 147

MACHINE IS UNLOCKED

MACHINE CAME WITH FORKS

MACHINE HAS NO ACTIVE FIELD MODS

MACHINE HAS NO ACTIVE WARRANIES

FRT FREIGHT 2
1CM1070 BOLT 1 N
53DM10 NUT 2
59CM1240 BOLT 1

CONTINUED ON PAGE 02

X

Ship To: IN STORE PICKUP		Branch				
		Date	Time		_,	Page
		02/08/21 Account No.	Phone No	30:20 (	Invo	02 lice No.
Invoice To:		Ship Via	l	Purchase O		4370
					Salespers	on
					066	
	SERVICE INVO	ICE				

			_				
STK#/FLEET#	<u> </u>	HRS	PIN/EIN	WARR	ANTY DATE	HRS	
E011785	5600 TOOLCAT	3333	520512230				
	5600						
6806124		HEAD		1 N			
6813408		PIN LINKAGE		1 N			
6814053		HOSE		1 N			
6814055		HOSE		1 N			
6983128		ANTI-FREEZE PG		3			
7135559		KIT		2			
11400001	52120201			SEGMENT	TOTAL==>		

\*\*\*\*\* WORK ORDER TOTALS \*\*\*\*\*

PARTS

LABOR

PICK UP AND DEL

OK CITY TAX

OK STATE TAX

SERVICE A/R DUE 2560.47

DUE ON RECIEPT

Remit to:

JR66