



Estimate

Date:

5/10/2021

Bill To

Ship To

Remit Payment To

Service Order

Purchase Order

Authorizer

SO-76

RC361

Trent Richardson

Item	Description	Quantity	Rate	Amount
Drive to unit				
Labor	Drive to unit (Service Call) 15800 W 5th Ave, Golden, CO - 003	0.50000		
Service Call		1.0000		
			Subtotal	

Complaint: Complete inspection of unit- check all hyd leaks, engine, all electrical components.

Cause: Customer Request

Labor	Correction: Aerial / General / PERFORM INSPECTION BUT CAN NOT DECAL UNIT BECAUSE CUSTOMER DID NOT WANT TO REIAP SOME ITEMS UNTILL A FUTURE DATE - 003	3.00000
-------	---	---------

Subtotal

Complaint: Power Wash Unit

Cause: Customer request (Inspection)

Labor	Correction: Equipment / / WASH UNIT - 004	2.00000
-------	---	---------

Subtotal

Complaint: Replace all hydraulic lines, filters, flush fluid, test system for leaks.

Cause: All hydraulic lines are failing. Suggest replacing all lines. Flushing system, change filters and flush system. Pressure tested pumps and they all produce 3000psi when deadheaded. (Inspection)

Labor	Correction: Aerial / / REPLACE HYDRAULIC LINES, REPAIR RADIATOR, PAINT BASKET, REPLACE ALL DECALS, FULL SERVICE, GET UNIT RUNNING PROPERLY, RUN UNIT TO BE SURE IT IS OPERATING NORMALY. - 003,004	55.00000
Parts	Hyd filter element - 2120158 - A	1
Parts	Hyd filter element - 2120150 - A	1
Parts	AW 32 Hydraulic Fluid - AW32 - A	28
Parts	AW 32 Hydraulic Fluid - AW32 - A	3
Parts	Indicator clogged - 7020021 - A	1

Item	Description	Quantity	Rate	Amount
Parts	O Ring - 7023206 - A	1		
Parts	O Ring backup - 70323207 - A	1		
Parts	Misc Hydraulic Hose - Misc - A	1		
Parts	Oil - 15W40 Oil - A	3		
Parts	Large Cylinder Rebuild - LCR - A	2		
Parts	Freight - Freight - A	1		
Parts	Hydraulic Hose - H212Mx35 - A	2		
Parts	Hydraulic Hose - U205MX35 - A	2		
Parts	Hydraulic Hose - U205M-08 - A	1		
Parts	Hydraulic Hose - U205-08-70 - A	1		
Parts	Hydraulic Hose - H212M-04x20 - A	2		
Parts	Hydraulic Hose - U205-06x19 - A	1		
Parts	Hydraulic Hose - U205-06X17 - A	1		
Parts	Hydraulic Hose - M542-16x91 - A	2		
Parts	HYDRAULIC HOSE - H203EM-8X20 - A	3		
Parts	Hydraulic Hose - H203EM x79.75 - A	1		
Parts	HYDRAULIC CAP - 0304-C-06 - A	2		
Parts	HYDRAULIC HOSE - U205M-06 - A	1		
Parts	HYDRAULIC HOSE - H203EM-04 - A	1		
Parts	HYDRAULIC HOSE - H203EM-04X8 - A	1		
Parts	HYDRAULIC HOSE - H203EM-04108.5" - A	1		
Parts	HYDRAULIC HOSE - U203M-06X18.5" - A	1		
Parts	HYDRAULIC HOSE - H212M-04X10" - A	2		
Parts	HYDRAULIC HOSE - H203EM-08X7" - A	1		
Parts	HYDRAULIC HOSE - H205M-06X34" - A	1		
Parts	RADIATOR - 1234-5 - A	1		
Parts	MISC - 3456-7 - A	1		
Subtotal				

Complaint: Replace tank side hinges.

Cause: Customer request (inspection)

Labor	Correction: Aerial / General / INSTALL HINGES - 003	1.00000		
Parts	Hinge - 2600246 - A	2		
Subtotal				

Complaint: Repair damaged platform.

Cause: Customer request (inspection)

Labor	Correction: Aerial / Bucket/Platform / The platform damaged and needs to be welded. Weld and repair damaged platform. Replace damaged decal. Operators manual missing from unit. Replaced missing manual. Fire extinguisher missing. Replaced fire extinguisher. - 004	14.00000		
Parts	Decal platform display - 1703084 - A	1		

Item	Description	Quantity	Rate	Amount
Parts	Operations Manual - 3120748 - A	1		
Parts	JLG Orange Paint - 3360017S - A	8		
Parts	Fire Extinguisher 2.9lbs - 440161MTL - A	1		
Parts	Freight Zuma - Freight - A	1		
Subtotal				

Complaint: Engine PM Service

Cause: Customer request

Labor	Correction: Equipment / Auxiliary Engine / PM UNIT - 004	1.00000		
Parts	Fuel Filter - 23100 - A	1		
Parts	Oil Filter - 1452 - A	1		
Parts	Air Filter - 1340060 - A	1		
Parts	Freight - Freight - A	1		
Subtotal				

Complaint: DECALS ARE WORN AND NOT LEDGABLE

Cause: Customer request (Inspection)

Labor	Correction: Aerial / General / INSTALL DECAL KIT - 001	2.00000		
Parts	DECAL KIT - JG1703804 - A	1		
Subtotal				

Return from unit

Labor	Return from unit 15800 West 5th Avenue, Golden, CO - 003	0.50000		
Subtotal				

Tow/Roll Bac

Shop Supplies

Unit: 5 VIN: 0300058239

2001 JLG 450A

Equipment: 0 Hours

Labor

Parts

Subtotal

Local (6.6500% of \$6,778.47)

Total \$17,929.24

