

Invoice

1985 Ottawa

DATE	INVOICE #
10/10/2012	17421

BILL TO

P.O. NO.	TERMS
	Due on receipt

QUANTITY	UNIT#	DESCRIPTION	RATE	AMOUNT
10	Peachies	Emergency Road Service/Travel Time Labor to Remove & Replace Engine & Accessories. Trouble Shoot Runability. Remove & Replace Starter. Remove & Replace Carburetor. Remove & Replace Ign., Dist. & Module. Replace Power Wire to Coil. Test Voltage Regulator & Replace.		
35	Peachies			
1	CP4037	Water Pump		
2	90026587	Motor Mount/Isolator		
1	32-290	Smog Pump		
1	91-02-5827	Starter		
1	30-2893	Distributor		
1	CBE7	Ignition Control Module		
1	FIT50322	Muffler		
1	HLY018505	Holley Carburetor		
1	42287	Air Filter		
1	51773	Oil Filter		
30	valv/oil	Qt 10W30		
1	47397	Vac Cap		
1	194A	Dist. Cap Adaptor		
1	PCV294	PCV Valve		
1	703-1427	Radiator Cap		
1	60390	Base Plate to Intake Gasket		
1	60003	Carb to Plate Gasket		
It's been a pleasure working with you!			Total	

DATE	INVOICE #
10/10/2012	17421

BILL TO

P.O. NO.	TERMS
	Due on receipt

QUANTITY	UNIT#	DESCRIPTION	RATE	AMOUNT
1	R400	BWD/Regulator		
1	Shop Supplies	Truck Supplies/Fuel Surcharge Kansas Sales Tax		
<i>Order 10/15/12</i> <i>10/17/12</i>				
It's been a pleasure working with you!			Total	\$4,393.93

Invoice

Date	Invoice #
1/24/2012	34349

Ship To

P.O. Number	Terms	Rep	Ship	Via	Mileage
			1/24/2012		

Quantity	Description	Price Each	Amount
1	Shop supplies Sales Tax		

O. Hawa 1985

*Del
012312
1/30/12*

Total

\$800.14

Invoice

Date	Invoice #
1/24/2012	34349

Ship To

P.O. Number	Terms	Rep	Ship	Via	Mileage
			1/24/2012		

Quantity	Description	Price Each	Amount
0.5	Segment 1 Unit Ottawa, model 30 VIN# 60944 Check oil leak and advise. Diagnose oil leaks: failing gaskets. Advised customer. Pan gasket leaking Rear main seal leaking Oil filter housing leaking Oil filter leaking Possible PCV valve failure		
3	Segment 2 Tune up (plugs, wires, cap and rotor). Remove and replace air filter, spark plugs, spark plug wires, distributor cap and rotor, engine oil. Reseal oil filter housing, grease chasis and valve sleeves.		
8	Spark plugs		
1	Distributor rotor		
1	Distributor cap		
1	Spark plug wire set		
1	Oil filter bas o'ring		
1	Spark plug wire seperator		
1	Segment 3 Full service performed. NOTE: King pin is bad No head lamps No park lamps		
1	Oil filter		
1	Air filter		
10	Quarts oil		
3	Quarts ATF tranny oil		
2	Gallon 50/50 extended life coolant		
0.5	Segment 4 Shift cable is hard to shift. Check up found working fine at this time. NOTE: Inform customer need to push and hold brake to shift.		

Total

Invoice

DATE	INVOICE #
9/6/2012	17353

P.O. NO.	TERMS
	Due on receipt

QUANTITY	UNIT#	DESCRIPTION	RATE	AMOUNT
1	Peachies	Shipping/Transportation From MWBS To Engine Reman. From Reman. To MWBS		
1	Parts	Remand Engine Ford Gas 6.1L 370, Complete Parts And Labor (SUBLET CHARGE)		
1	Truck Supplies	Truck Supplies/Fuel Surcharge Kansas Sales Tax		
Total				\$5,538.80