

Invoice

Date	Invoice #
9/29/2018	

PAID
10/27/2018

PO #	Unit / License #	Make & Model	Serial / VIN	Mileage / Hours
		95 IH 4700	TH359218	257689
Qty	Description			Amount
	Labor-- truck was towed in - Head gasket bad - pulled cyl head found scored cyl , talked to cust - overhaul engine - after market parts, new injectors, cyl kits, rod and main brgs and thrust, cyl head , air filter , oil and fuel filters, water pump, new belts and tensioner, removed hood and install Shop supplies: spray, tape, floor dry, towels, etc.			
	towing			
1	thermostat ih1830256c93			
1	waterpump dt466 flt1830606			
1	water filter fgwf2071			
1	oil filter fglf3883			
1	fuel filter fgff5019			
1	cyl. head 31823914r			
1	in-frame OH kit 311005			
1	thrust brg 31822379			
6	injector 31824930			
1	belt 25-060470hd			
1	belt 25-080730hd			
1	air filter fgaf979m			
1	tensioner 1830033c2			
	EPA Charge			
1	gasket ih1816722c2			
2	o-ring ih1818402c2			
			Subtotal	
			Sales Tax (7.0%)	
Phone #				Total
Fax #				
E-mail				

Invoice

Date	Invoice #
9/29/2018	

PAID
10/27/2018

PO #	Unit / License #	Make & Model	Serial / VIN	Mileage / Hours
		95 IH 4700	TH359218	257689
Qty	Description			Amount
1	gasket ih1820936c1			
1	grommet - 3/8 ih1812348c1			
1	gasket ih253660r2			
2	paint de1610			
3	dca			
1	radiator cap ih3578833c3			
8	15-40 shell rotella oil bulk			
3	antifreeze bulk			
1	gr.8hxcapscrew1/2-13x3-1/2 bdt d39114			
0.75	transmission fluid - allison per gal transynd			
			Subtotal	
			Sales Tax (7.0%)	
			Total	\$11,842.14
Phone #	Fax #	E-mail		