

Invoice

Date	Invoice #
12/31/2020	201599

P.O. No.	Terms	Project
	Due on receipt	

Quantity	Description	Rate	Amount
1	R&I ENGINE, DISSAY, FOUND CYLINDER #1 OVERSIZE, SEND BLOCK, HEAD, CRANK AND CAM FOR REPAIR, SLEEVE CYLINDER #1, PISTONS RING GLAND WORN EXCESSIVELY CAUSED BY OVERFUELING, ASSY ENGINE WITH NEW PISTON KITS, NEW ROD AND MAIN BEARINGS, REPLACE INJECTORS, TORBO AND FUEL PUMP, ASSY HEAD, INSTALL TORQUE TO SPECS, ADJUST OVERHEAD, INSTALL ENGINE, REPLACE FILTERS, RAD HOSES, TURBO LUBE LINES, FILL COOLING SYSTEM, BLEED FUEL SYSTEM, START ENGINE, HAD CODES FOR LOW RPMS, AND FUEL SYSTEL PRESSURE, REPLACE FUEL SENSORS, AND ENGONE SPEED SENSORS, RESTART ENGINE, STILL HAD CODES, HAD YANCEY COME INSTALL COMPUTER, TRY CLEAR CODES, WAS TOLD WIRE HARNESS BAD, ORDER NEW HARNESS, INSTALL, RECALIBRATE FUEL AND ELECT SYSTEM, INSTALL BELLY PANS AND SHEET METEL, OPERATE MACH FOR 2EA HRS, CHECK OK-CAT D5K-YYY0397		
1	Sub-Contracted-SERVICE CALL YANCEY CALOBRATE MACHINE		
2	REPLACE 2EA MISSING SIDE PANEL DOORS		
	Shipping & Handling for wire harness		
	Fulton County Outside Atlanta City Limits		
Total			\$23,346.52

Invoice

Date	Invoice #
12/31/2020	201599

P.O. No.	Terms	Project
	Due on receipt	

Quantity	Description	Rate	Amount
4	3200577 INJECTOR		
4	3109269 PISTON KIT		
1	5185437 BEARING KIT		
1	3532205 MAIN BEARING KIT		
2	2380120 SPEED SENSOR		
1	3196481 SENSOR		
1	1166680 SENSOR		
1	2556940 WIRE HARNESS		
1	2934053 AIR FILTER		
1	2277449 AIR FILTER		
1	7W2326 OIL FILTER		
1	3087298 FUEL FILTER		
1	2998229 FUEL FILTER		
1	2551342 HOSE		
1	2551344 HOSE		
1	3035787 FUEL TUBE		
1	3035793 TUBE		
1	3838543 HOSE		
1	10R7659 REMAN FUEL PUMP		
5	15/40 OIL		
5	ABTIFREEZE		
1	Sub-Contracted-VAT,CLEAN,RESURFACE CYLINDER BLOCK,SLEEVE ONE CYLINDER		
1	Sub-Contracted-VAT,CLEAN,REBUILD CYLINDER HEAD		
1	10R9586 REMAN TURBO		
1	1W8545 ENGINE GASKET KIT		
1	Sub-Contracted-INSPECT AND POLISH CRANKSHAFT AND CAM SHAFT		

Total