

INVOICE

Invoice # [REDACTED]
 SO # [REDACTED]
 Date 10/31/2022
 Writer [REDACTED]
 Page 2 of 2

Invt:Cust [REDACTED] Cust acct# [REDACTED] Cust PO# [REDACTED]
 Date 10/31/2022
 Writer [REDACTED]
 Page 1 of 2

Sold to: [REDACTED] Ship to: [REDACTED]

Contact [REDACTED] Payment terms [REDACTED] Due on the 10th [REDACTED] Ship via [REDACTED] None Specified
 Contact phone [REDACTED] Primary phone [REDACTED] Prepay and Add [REDACTED]

Vehicle info: Year/Make/Model 2004 / FORD / F650 Cust Unit # RED 6
 VIN/Short VIN 3FRNF65N54V667578 / 4V667578 Miles/Hours 111473 / 0

Repair Order no. RO - RO 0219268 Operation # 1

Condition REPAIR ENGINE MISS

Correction UNIT CAME IN FOR ENGINE MISS, CHECKED OUT FOUND THERMOSTAT STUCK, ALSO FOUND ALL 6 INJECTORS BAD, TOOK FUEL SAMPLE FOUND AN ABUNDANCE OF WATER IN FUEL, AFTER REMOVING INJECTORS FOUND INJECTOR CUPS LEAKING, AND HAD PUT COOLANT IN FUEL TANK, FLUSHED FUEL TANK.

Part number	Description	Ord	Del	B/O	List Price	Unit price	Ext. price
CQX_PART_NC	PART - NO CORE	1	1				
86806 FUEL FILTER							
CQX_PART_NC	PART - NO CORE	1	1				
86377 FUEL FILTER							
329_115-4223	THERMOSTAT - 190	2	2				
GRX_DIESEL	DIESEL FUEL	1	1				
329_310-7255	SEAL O RING	6	6				
329_310-7257	O-RING SEAL	6	6				
329_227-1200	SLEEVE	6	6				
NAP_PART_NC	MISC PART - NO CORE	1	1				
7651146 BEARING LOCK							
329_208-8057	Injector	6	6				
Core exchange							
329_222-5915	THERMOSTAT HOUSING GASKET	1	1				
210_24115	NO. 20 WORM GEAR HOSE CLAMP	2	2				
210_24116	NO. 24 WORM GEAR HOSE CLAMP	2	2				
OAP_28445	COOLANT HOSE	6	6				
263_PART_NC	MISC PART - NO CORE	1	1				

Invt:Cust [REDACTED] Cust acct# [REDACTED] Cust PO# [REDACTED]

1141PCPII FITTING

210_24114 NO. 16 WORM GEAR HOSE CLAMP 2 2 0

GRX_802 ANTIFREEZE-BULK 9 9 0

Labor

Freight in DELIVERY CHARGE

Shop supplies

Received by [REDACTED]

See warranties on reverse side

Total merchandise [REDACTED]
 Total cores [REDACTED]
 Total labor [REDACTED]
 Tax amount [REDACTED]
 Invoice total \$11,299.97