

Program Invoice Date	Dealer Invoice Date
12/13/2021	12/13/2021
PO No.	PO Date
OVT1027199	N/A
Settlement Date	Term of Sale
12/13/2021	NET 15 EOM STMT SAT
Statement Date	Due Date
12/17/2021	01/15/2022

Invoice Header

Bill To:

Ship To:

Vehicle Information:

Unit: W8392M

Mileage: 774435

Vin: 1FUJGLDV2ELFT5839

Invoice Line Items

Section 1

Complaint MIL-DERATED

Correction FOUND UNIT HAS MULTIPLE CODES FOR AFTERTREATMENT. FOUND UNIT HAS A VERY LARGE EXHAUST LEAK AT THE ONEBOX INLET CLAMP. MADE ESTIMATE FOR REPAIRS. REMOVED EXHAUST PIPE FROM INLET OF ONEBOX AND INSPECTED FOR DAMAGE. FOUND MULTIPLE LARGE GROOVES IN THE SEALING SURFACE OF THE PIPE DUE TO BEING LOOSE. INSTALLED NEW EXHAUST PIPE FROM BELLOWS PIPE TO ONEBOX WITH NEW CLAMPS AND GASKETS. SPRAYED WITH SOAPY WATER AND STARTED UNIT, NO LEAKS FOUND AFTER REPAIRS. INSTALLED NEW DOSER INJECTOR IN EXHAUST PIPING.

PLACED UNIT INTO REGEN AND FOUND IT WAS ONLY CONVERTING AT 50%. DISCONNECTED DEF DOSER AND RAN FOR 20 MINUTES IN REGEN. RECONNECTED DEF DOSER AND FOUND UNIT IS NOW CONVERTING AROUND 70%. FIRST REGEN COMPLETED AND CLEARED FAULT CODES. PLACED INTO SECOND REGEN TO SEE IF CONVERSION WOULD COME UP EVEN MORE. UNIT COMPLETED SECOND REGEN AT 91% CONVERSION, GOOD TEMPS AND PRESSURES. ALL FAULTS REMAINED INACTIVE AND CLEARED. REINSTALLED SIDE FAIRING.

Type	Item	Description	PO Line#	Qty	Unit Price	Ext. Price
P	04-30676-000	PIPE-EXHAUST,ATS IN		1.00		
	VMRS: 043-003-025					
P	TCX AMS014AM	CLAMP KIT-SLIP,4IN		1.00		
	VMRS: 043-003-013					
P	TCX T130158342AB2	CLAMP-EXHAUST 5 INCH		1.00		
	VMRS: 043-003-013					
M	d	DIAGNOSE		2.00		
P	DDE A4720700746	INJ VALVE		1.00		
	VMRS: 043-006-026					
P	TCX AMS013	GASKET-5 INCH SPHERI		1.00		
	VMRS: 043-003-038					
L	r	REPAIR		6.00		
M	NC	PARTS REMINDER: ADD PFP		0.00		
P	04-30676-000	PIPE-EXHAUST,ATS IN		0.00		
	VMRS: 043-003-025					

TOTAL 14.00

Section 2

Complaint C/A CITY HORN INOP

Correction FOUND CITY HORN IS MISSING AND CONNECTOR IS DAMAGED. FOUND HORN PLUG HAS GOOD POWER AND GROUND TO IT. MADE ESTIMATE FOR REPAIRS. INSTALLED NEW CITY HORN. REPLACED CONNECTOR BODY. NO ISSUES AFTER REPLACEMENT.

Type	Item	Description	PO Line#	Qty	Unit Price	Ext. Price
P	86-01788-001	HORN-ELECTRIC HORN,S		1.00		
	VMRS: 054-001-042					
P	23-13142-204	PLUG 2CAV MP150S PAC		1.00		
	VMRS: 034-004-107					
P	PAC 12048074	TERMINAL-FEMALE,METR		2.00		
	VMRS: 034-004-107					
P	PAC 12052634 B	LOCK-SECONDARY,2 POS		1.00		
	VMRS: 034-004-107					
P	PAC 15324973 B	SEAL-CABLE,FMALE,MET		2.00		
	VMRS: 034-004-277					
L	5300000	GENERAL ACCESSORIES REPAIR		1.20		


Type	Item	Description	PO Line#	Qty	Unit Price	Ext. Price
P	23-12069-001	TIE STRAP-BUTTON HEA		2.00		
	VMRS: 014-008-005					

Section 3

Type	Item	Description	PO Line#	Qty	Unit Price	Ext. Price
S	Shop Supplies	Shop Supplies		1.00		
M	Diagnostic Supplies	Diagnostic Supplies		1.00		

References

Invoice Totals

Line Types	Type Totals	Orig Totals	Totals
F - Freight		1,695.09	Line Item Total (Excl. Taxes)
L - Labor		0.00	Taxes
M - Miscellaneous		\$1,695.09	Total : USD  \$1,695.09
P - Parts			
S - Shop			
U - Sublet			
Line Item Total			

*The dates displayed on the invoice are based on U.S. Eastern Time Zone.