



INVOICE

BILL TO

SHIP TO

INVOICE # 1049

DATE 09/27/2018

DUE DATE 10/12/2018

TERMS Net 15

TRACKING NO.	MODEL	SERIAL NUMBER	HOURLY METER
.	PC300LC-7EO	A88107	8,674

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
08/27/2018	REGULAR FIELD RATE	REPLACE BOTH TRAVEL MOTORS DIAGNOSED ON RO# 1044	24.50		
08/27/2018	EXTENDED FIELD RATE	REPLACE BOTH TRAVEL MOTORS DIAGNOSED ON RO# 1044	9.50		
08/27/2018	MILEAGE	TO AND FROM SHOP 8/27/18, 9/26/18, PICK UP PARTS 8/28/18	180		
09/27/2018	PARTS	TRAVEL MOTOR, KOMATSU REMAN LEFT SIDE	1		
09/27/2018	PARTS	TRAVEL MOTOR, AFTERMARKET REMAN RIGHT SIDE	1		
09/27/2018	PARTS	ROTARY SEAL	2		
09/27/2018	PARTS	COVER, LEFT FINAL DRIVE	1		
09/27/2018	PARTS	UPPER CARRIER, LEFT FINAL DRIVE	1		
09/27/2018	PARTS	MAIN BEARINGS, LEFT FINAL DRIVE	2		
09/27/2018	PARTS	SPACER, LEFT FINAL DRIVE	1		
09/27/2018	PARTS	WASHER, LEFT FINAL DRIVE	1		
09/27/2018	PARTS	BEARING, LEFT FINAL DRIVE	3		
09/27/2018	PARTS	THRUST WASHER, LEFT FINAL DRIVE	6		
09/27/2018	PARTS	BEARING, LEFT FINAL DRIVE	4		
09/27/2018	PARTS	THRUST WASHER, LEFT FINAL DRIVE	8		
09/27/2018	PARTS	BUTTON, LEFT FINAL DRIVE	1		
09/27/2018	PARTS	PIN	6		
09/27/2018	PARTS	PIN	8		
09/27/2018	PARTS	PAD BOLT	1		
09/27/2018	PARTS	PAD NUT	1		
09/27/2018	PARTS	BOLT	8		

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
09/27/2018	PARTS	WASHER	8		
09/27/2018	PARTS	FLANGE	4		
09/27/2018	PARTS	ORING	2		
09/27/2018	PARTS	ORING	10		
09/27/2018	PARTS	ORING	4		
09/27/2018	PARTS	ORING	4		
09/27/2018	PARTS	ORING	4		
09/27/2018	PARTS	ORING	8		
09/27/2018	PARTS	VALVE	2		
09/27/2018	PARTS	SILICONE	1		
09/27/2018	PARTS	TO30, 5 GALLON BUCKET	1		
09/27/2018	PARTS	GREASE, TUBE	4		
09/27/2018	PARTS	MASTER PIN	2		
09/27/2018	PARTS	MASTER SEAL	4		
09/27/2018	FREIGHT		1		
09/27/2018	MISC. SHOP SUPPLIES		1		

PLEASE SEE ATTACHED EXCEL DOCUMENT IN EMAIL FOR JOB
DESCRIPTION

SUBTOTAL
TAX
TOTAL
BALANCE DUE

\$25,080.55



PO NUMBER

ADDRESS

SHIP TO

PO NUMBER # 1003

DATE 03/20/2019

EXPIRATION DATE 04/20/2019

TRACKING NO.	MODEL	SERIAL NUMBER	HOOR METER
.	PC300LC-7EO	A88107	9,119

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
03/20/2019	PARTS	REMAN ENGINE	1		
03/20/2019	PARTS	REMAN HYDRAULIC PUMP	1		

TOTAL

\$34,446.05

Accepted By

Accepted Date



Invoice

BILL TO

SHIP TO

INVOICE # 1128

DATE 04/04/2019

DUE DATE 04/19/2019

TERMS Net 15

TRACKING NO.

MODEL

PC300LC-7EO

SERIAL NUMBER

A88107

HOURLY METER

9,120

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
04/01/2019	REGULAR	ENGINE KNOCK, REPLACE ENGINE AND	60.50		
	FIELD RATE	HYDRAULIC PUMPS			
04/01/2019	MILEAGE		295		
04/01/2019	PARTS	KOMATSU REMAN ENGINE	1		
04/01/2019	PARTS	KOMATSU REMAN HYDRAULIC PUMP	1		
04/01/2019	PARTS	KOMATSU REMAN STARTER	1		
04/04/2019	PARTS	FLUSH, CLEAN, AND REPAIR RADIATOR (LABOR)	1		
04/04/2019	PARTS	15W40 OIL	10		
04/04/2019	PARTS	HO56 OIL	5		
04/04/2019	PARTS	TO30 OIL	1		
04/04/2019	PARTS	COOLANT	9		
04/04/2019	PARTS	ORING	1		
04/04/2019	PARTS	SEAL	1		
04/04/2019	PARTS	CLAMP	1		
04/04/2019	PARTS	BOLT	2		
04/04/2019	PARTS	WASHER	4		
04/04/2019	PARTS	PLATE	1		
04/04/2019	PARTS	TUBE	1		
04/04/2019	PARTS	RING	1		
04/04/2019	PARTS	TUBE	1		
04/04/2019	PARTS	CLIP	1		
04/04/2019	PARTS	LOCK NUT	2		
04/04/2019	PARTS	BOLT	2		
04/04/2019	PARTS	COVER GASKET	1		

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
04/04/2019	PARTS	BELT	1		
04/04/2019	PARTS	BELT	1		
04/04/2019	PARTS	GASKET	1		
04/04/2019	PARTS	ORING	1		
04/04/2019	PARTS	ELEMENT ASS.	1		
04/04/2019	PARTS	CAP	1		
04/04/2019	PARTS	HOSE	1		
04/04/2019	PARTS	HOSE	1		
04/04/2019	PARTS	HOSE	1		
04/04/2019	PARTS	HOSE	1		
04/04/2019	PARTS	FUEL PRE FILTER	1		
04/04/2019	PARTS	WIF SENSOR	1		
04/04/2019	PARTS	ELEMENT	1		
04/04/2019	PARTS	ORING	1		
04/04/2019	PARTS	ORING	1		
04/04/2019	PARTS	SEAL	2		
04/04/2019	PARTS	ORING	10		
04/04/2019	PARTS	ORING	1		
04/04/2019	PARTS	HOSE	1		
04/04/2019	PARTS	ORING	2		
04/04/2019	PARTS	ORING	2		
04/04/2019	PARTS	ORING	1		
04/04/2019	PARTS	ORING	1		
04/04/2019	PARTS	ORING	8		
04/04/2019	PARTS	ORING	8		
04/04/2019	PARTS	SEAL	1		
04/04/2019	PARTS	TANK	1		
04/04/2019	PARTS	SEAL	1		
04/04/2019	PARTS	HEATER HOSE	2		
04/04/2019	PARTS	FITTING	2		
04/04/2019	PARTS	TUBE	2		
04/04/2019	PARTS	COVER	2		
04/04/2019	PARTS	GROUND WIRE	1		
04/04/2019	PARTS	GASKET	1		
04/04/2019	PARTS	BOLT	2		

THE ENGINE HAD A BAD RATTLE AND LOST POWER. REMOVED VALVE COVER. FOUND #1 EXHAUST CROSS OVER HAD COME OUT OF PLACE. THE #1 INTAKE PUSH ROD WAS BENT. MEASURED THE CAM LIFT. FOUND #1 EXHAUST WAS .060" LOW. REMOVED ENGINE AND PUMPS. REMOVED HEAD AND FRONT COVER. REMOVED CAM. FOUND THE LOBE AND LIFTER WERE BOTH WORN DOWN. THE OTHER LOBES WERE PITTED. THE PISTONS WERE ROUNDED AND WORN. IT WAS DECIDED TO INSTALL A REMAN ENGINE. REASSEMBLED THE

SUBTOTAL
TAX
SHIPPING
TOTAL
PAYMENT
BALANCE DUE

\$13,914.66