

Branch		
Date	Time	Page
01/04/22	22:31:36 (B)	01
Account No	Phone No	Inv No
Ship Via		Purchase Order
Tax ID No		
		Salesperson

## SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
A008346 TRACTOR	922	V0855D181873		
855				

SEGMENT# 1 C 828 NA 12/02/21 12/02/21 12/31/21

STEERING WHEEL

CORRECTION:

REMOVED AND REPLACED STEERING WHEEL, INSTALLED STEERING WHEEL CENTER CAP.

ADDITIONAL DESCRIPTION:

REPLACE STEERING WHEEL DAMAGED WHEN ROOF COLLAPSED.

AM103066

M71094

CAP

STEERING WHEEL

10100006

SEGMENT# 2 C 828 NA 12/02/21 12/02/21 12/31/21

SEAT

CORRECTION:

REMOVED AND REPLACED SEAT AS WELL AS DAMAGED SEAT FRAME.

ADDITIONAL DESCRIPTION:

REPLACE SET AND SEAT SUSPENSION FRAME.

AM105089

SUSPENSION, SEAT

1

AM107759

SEAT

1

7703440

5/16-18X5/8 FLG

1

5/16"-18 X5/8" FLANGE SCREW

10100006

SEGMENT# 3 C 799 NA 12/02/21 12/02/21 12/31/21

REAR FENDER LIGHTS

CONTINUED ON PAGE 02

Branch		
Date	Time	Page
01/04/22	22:31:36 (B)	02
Account No	Phone No	Inv No
Ship Via		Purchase Order
Tax ID No		--
		Salesperson

## SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
A008346	TRACTOR	922	V0855D181873	
	855			

CORRECTION:

REMOVED AND REPLACED RIGHT HAND FENDER LIGHTS AND BEZEL.  
 CHECKED LIGHT OPERATION, FOUND THE RIGHT SIDE FENDER LIGHTS  
 NOT WORKING, AS WELL AND FRONT RIGHT LIGHT. INSPECTED AND  
 FOUND DAMAGED WIRING. REMOVED AND REPLACED LIGHT HARNESS.

ADDITIONAL DESCRIPTION:

REPLACE RIGHT REAR FENDER TAIL LAMP/TRIM (SOLD AS A UNIT)  
 AND BEZEL ON RIGHT REAR FENDER FRONT LIGHT TRIM. REPLACE  
 RIGHT REAR FENDER HANDLE.

AM102142	TAIL LAMP	1	
AM103664	BEZEL	1	
AM105093	WIRING HARNESS	1 N	
AM108167	WIRING HARNESS	1 N	
AM118928	HANDLE	1	
AM876786	SWITCH	1	

10100006

---

SEGMENT# 4 C 828	NA	12/02/21	12/02/21	12/31/21
------------------	----	----------	----------	----------

REPLACE LOADER OPERATION HANDLE KNOB

CORRECTION:

REMOVED AND REPLACED KNOB ON LOADER CONTROL HANDLE.

ADDITIONAL DESCRIPTION:

REPLACE KNOB ON LOADER OPERATION HANDLE.

M90303	KNOB	1	
--------	------	---	--

10100006

---

CONTINUED ON PAGE 03

Branch		
Date	Time	Page
01/04/22	22:31:36 (B)	03
Account No	Phone No	Inv No
Ship Via		Purchase Order
Tax ID No		
		Salesperson

## SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
-------------	-----	---------	---------------	-----

A008346	TRACTOR	922	V0855D181873	
---------	---------	-----	--------------	--

855

SEGMENT# 5 C 799	NA	12/02/21	12/02/21	12/31/21
------------------	----	----------	----------	----------

ROPS

CORRECTION:

REMOVED AND REPLACED ROPS, INSTALLED NEW SAFETY DECAL.

ADDITIONAL DESCRIPTION:

REPLACE ROLL OVER PROTECTION ASSEMBLY.

AM119856	ROPS	1
----------	------	---

M159662	SAFETY SIGN	1 N
---------	-------------	-----

10100006

SEGMENT# 6 C INTER NA	12/02/21	12/02/21	12/31/21
-----------------------	----------	----------	----------

FREIGHT

FRT	FREIGHT	1
-----	---------	---

10100006

SEGMENT# 7 C 823	N/A	12/02/21	12/02/21	12/31/21
------------------	-----	----------	----------	----------

RIGHT FRONT TIRE REPAIR

CORRECTION:

RIGHT FRONT TIRE NOT HOLDING AIR. REMOVED AND TOOK FOR REPAIR. INSTALLED TIRE.

SUBLETL	FLAT REPAIR	1
---------	-------------	---

10100006

Branch		
Date	Time	Page
01/04/22	22:31:36 (B)	04
Account No	Phone No	Inv No
Ship Via		Purchase Order
Tax ID No		
		Salesperson

## SERVICE INVOICE

STK#/FLEET#

A008346 TRACTOR  
855

HRS PIN/EIN  
922 V0855D181873

WARRANTY DATE

HRS

PARTS

LABOR

SUBLET

SHOP SUPPLIES

SUB TOTAL==>

KANSAS STATE TAX 6.5

SALINA COUNTY 1.50%

CUSTOMER TOTAL

5348.46