

INVOICE #: 9120037926

PAGE: 1

TIME CLOSED: 15:26:29

CUSTOMER:

1

PRIMARY:  
SALESMAN:

0

VEHICLE: 2015 INTERNATIONAL PROSTAR

LICENSE: FH0046 IA MILEAGE: 1

COLOR: WHITE ENGINE: CUM ISX

VIN: FN715799

Fleet ID 02

INVOICE DATE: 11/17/22

DUE: 11/17/22

PRODUCT	MECHANIC	QUANTITY	PRICE	LABOR	EXTENSION
SERVICE COMMENTS LISTED BELOW MESSAGE		1			
We understand your truck is your livelihood our procedures assure that your vehicle has been serviced properly, our policy requires that you witness the torqueing of all drain plugs, fill plugs, check plugs and lug nuts if applicable, please verify and initial all required lines below as it pertains to the service you were provided.					
I have witnessed the torqueing of all oil drain plugs.					
I have witnessed the torqueing of all transmission drain & fill plugs.					
I have witnessed the torqueing of all front & rear diff, drain/fill plugs					
I have witnessed the torqueing of all Tire/Wheel assembly lug nuts.					
I understand as part of the tire service provided I will stop at a Loves/Speedco location within 50-100 miles for a re-torque verification					
Customer Signature X					
R&R BATTERIES	91295	1.00			
S-8997					
INTERSTATE 31-MHD 950 CCA		4			
31-MHD					
SHOP SUPPLIES					
SS					
				MERCHANDISE:	
				LABOR:	
				OTHER:	
				SALES TAX:	
				INVOICE TOTAL:	
FUEL DESK					830.80
TENDERED BY 91225					



INVOICE #: 9120038305

PAGE: 1

TIME CLOSED: 11:21:48

CUSTOMER:

1

PRIMARY:  
SALESMAN0 VEHICLE: 2015 INTERNATIONAL PROSTAR  
LICENSE: FH0046 IA MILEAGE: 123456  
COLOR: WHITE ENGINE: CUM ISX  
VIN: FN715799  
Fleet ID 02

INVOICE DATE: 12/10/22

DUE: 12/10/22

PRODUCT	MECHANIC	QUANTITY	PRICE	LABOR	EXTENSION
SERVICE COMMENTS LISTED BELOW		1			
MESSAGE					
We understand your truck is your livelihood our procedures assure that your vehicle has been serviced properly, our policy requires that you witness the torqueing of all drain plugs, fill plugs, check plugs and lug nuts if applicable, please verify and initial all required lines below as it pertains to the service you were provided.					
I have witnessed the torqueing of all oil drain plugs.					
I have witnessed the torqueing of all transmission drain & fill plugs.					
I have witnessed the torqueing of all front & rear diff, drain/fill plugs					
I have witnessed the torqueing of all Tire/Wheel assembly lug nuts.					
I understand as part of the tire service provided I will stop at a Loves/Speedco location within 50-100 miles for a re-torque verification					
Customer Signature X					
R&R AIR DRYER		91286	1.00		
S-8997					
FLTAD4050 AIR DRYER		1			
OUTSIDE REPAIR					
DRIVER CAME IN FOR PURGE VALVE NEEDING REPLACED, ENDED UP BEING THE AIR DRYER CARTRIDGE WAS LEAKING. ATTEMPTED TO REMOVE CARTRIDGE BUT IT WAS RUSTED TO AIR DRYER, DRIVER APPROVED R&R ON AIR DRYER					
SHOP SUPPLIES					
SS					
MERCHANDISE:					
LABOR:					
OTHER:					
SALES TAX:					
INVOICE TOTAL:					
FUEL DESK					
605.17					