

Invoice

Date	Invoice #
11/8/2022	849908

Bill To

Due Upon Receipt

Make and Model	Serial Number	Hour Meter/Odometer
CAT 953C	22N1508	
Description		Amount
Labor Left side case Use OEM gear OEM Pinion gear Bearings and seals Brake discs and plates Sensor Shop Supplies		
Left final drive was failed. Disassembled and found component had been run dry. The pinion gear, the gear driven by the pinion, the main housing, and the brake discs were damaged. Acquired a good, used housing, a new OEM pinion gear and a good, used gear that is driven by the pinion. Acquired and installed all new brake disc, brake plates, OEM bearings, seals and wheel bearing bolts. Replaced all bearings and seals in the right final drive using OEM parts. Replaced damaged speed sensor. Unit are being sent with no oil.		
Thank you for your business.		
Subtotal		
Sales Tax (7.5%)		
Total		\$15,677.80

11-10-22
pd