

2004 Peterbilt 357
MW9646

INVOICE

Date 02/12/19

Date Open 01/02/18

Page: 1 of 5

Sold To :

Ship To :

--	--

Written By		Terms		Time 13:46:53		Customer Po #		Promised		Phone		Ship Via			
Unit # RT-4093		Plate # 40B2WZ		Year 2003		Make PETERBILT		Model 357		Mileage/Hrs 805500/0.0		VIN 1NPAXUEX340821565		Engine	

Qty	Description	Price	Amount
	Work Requested : ENGINE ASSEMBLY COOLANT IN OIL Work Completed :CHECK FOR COOLANT IN OIL. DRAIN OIL AND PULL PAN. PRESSURIZE COOLING SYSTEM. FOUND LEAK AROUND #2 CYLINDER FROM CAM AREA, HEAD GASKET ISSUE. REMOVE HEAD, CAM AND FRONT COVER. STRIPPED HEAD TO BE WORKED OVER. REMOVE AND REPLACE CAM BEARINGS, CAMSHAFT, FRONT COVER, FRONT SEAL, OIL PAN GASKET, 3 DIP STICK HOLE PLUGS, CROSS HATCHES, ROCKERS, CAM FOLLOWERS, 2 FUEL RETURN HOSES, VARIOUS SEALS AND ORINGS, HEAD GASKET, FUEL FILTERS, OIL FILTER AND OIL. REMOVE AND REPLACE LOWER RADIATOR HOSE AT RADIATOR, TOP RADIATOR HOSES, AND FILL COOLANT. TEST DRIVE UNIT, AND RECHECK, ALL OK.		
5.000	TCIL10R1797 ROCKER ARM		
4.000	TCIL10R1707 ROCKER ARM		
6.000	TCIL1764168 VALVE BRIDGE		
6.000	TCIL1764172 VALVE BRIDGE		
1.000	TCIL2627131 TIMING COVER ASSEMBLY		
1.000	TCIL1742475 SEAL INEGRA CAT		
1.000	TCIL2264755 SEAL GAP		
1.000	TCIL1095309 GASKET		
6.000	TCIL1095313 GASKET		
12.00	TCIL6V5839 WASHER HARD		

Parts.....
Labor.....

Shop Supplies

Sub Total
Sales Tax....**TOTAL**
PAID

Continued

INVOICE

Date 02/12/19

Date Open 01/02/18

Page: 2 of 5

Sold To :

Ship To :

--	--	--	--

Written By		Terms		Time 13:46:53		Customer Po #		Promised		Phone		Ship Via			
Unit # RT-4093		Plate # 40B2WZ		Year 2003		Make PETERBILT		Model 357		Mileage/Hrs 805500/0.0		VIN 1NPAXUEX340821565		Engine	

Qty	Description	Price	Amount
12.00	TCIL3E8017 LOCK NUT		
1.000	TCIL1S4295 GASKET		
1.000	TCIL1978418 GASKET		
1.000	TCIL1978419 GASKET		
1.000	TCIL1316645 HOSE		
1.000	TCIL7E5555 GASKET		
1.000	TCIL10R0705 WATER PUMP		
1.000	TCIL1095308 SEAL		
14.00	TCIL7C8296 ISOLATOR		
1.000	TCIL1873307 GASKET AS-CY		
7.000	TCIL6V9607 BOLT		
6.000	TCIL9X7317 SEAL ORING		
6.000	TCIL2153198 SEAL		
6.000	TCIL1523001 BOLT HEX HEAD		
12.00	TCIL2511005 LIFTER ASSEMBLY		
6.000	TCIL2027475 LIFTER ASSEMBLY		
	7		
12.00	TCIL1163715 STUD		

Parts.....
Labor.....

Shop Supplies

Sub Total
Sales Tax....**TOTAL**
PAID

Continued

INVOICE

Date 02/12/19

Date Open 01/02/18

Page: 3 of 5

Sold To :

Ship To :

--	--

Written By		Terms		Time 13:46:54	Customer Po #		Promised		Phone		Ship Via	
Unit # RT-4093		Plate # 40B2WZ	Year 2003	Make PETERBILT		Model 357	Mileage/Hrs 805500/0.0		VIN 1NPAXUEX340821565			Engine

Qty	Description	Price	Amount
3.000	TCIL7W164 GASKET		
6.000	TCIL1198784 ORING		
1.000	TCIL1314164 GASKET		
2.000	TCIL3S9643 SEAL		
4.000	TCIL1182797 GASKET		
2.000	TCIL2477133 TSTAT CAT C12		
3.000	TCIL5P5678 M SEAL STK		
1.000	TCIL2165585 CAM BEARING		
3.000	TCIL2165583 BEARING CAM		
1.000	TCIL2165584 BEARING CAM		
3.000	TCIL2097309 PLUG		
1.000	TCIL1137068 GASKET COVER		
6.000	TCIL4G4972 SEAL		
1.000	JHFH06908 CUSTOM MADE FUEL LINE		
23.00	TCIL1750454 BOLT HEAD CAT STANDARD		
4.000	JHF06U056 SWIVEL CRIMP END		
3.000	TCIL1787508 HEAD BOLT WITH STUD		
1.000	ERIREBUILD CYL HEAD REBUILD CYL HEAD, RESURFACE, MAGNAFLUX REPALCE VALVES AND SPRINGS, KEEPERS AND GUIDS		

Parts.....
Labor.....

Shop Supplies

Sub Total
Sales Tax....TOTAL
PAID

Continued

INVOICE

Date 02/12/19

Date Open 01/02/18

Page: 4 of 5

Sold To :

Ship To :

--	--	--	--

Written By	Terms	Time 13:46:54	Customer Po #	Promised	Phone	Ship Via	
Unit # RT-4093	Plate # 40B2WZ	Year 2003	Make PETERBILT	Model 357	Mileage/Hrs 805500/0.0	VIN 1NPAXUEX340821565	Engine

Qty	Description	Price	Amount
6.000	TCIL3618205 SEAL		
3.000	TCILGT41753 RADIATOR HOSE 4175-0030		
2.000	TCIL4988280 GASKET, HYDRAULIC PUMP		
1.000	PTBJC12000 ACCUMULATOR		
2.000	PTBAC11150 O RING #12		
1.000	TCIL10R3356 CAM SHAFT CAT C12		
2.000	PTBHW06601 NUT-HEX FLG		
.5000	HAIVAL799222 P/S FLUID		
36.00	EPCSHL15W40 15W40 SHELL ROTELLA ENGINE OIL		
1.000	DONP551712 FUEL FILTER SPIN ON		
1.000	DONP550105 FUEL FILTER		
1.000	DONP554005 OIL FILTER		
13.00	EPCEXTENDED LIFE EXTENDED LIFE COOLANT RED SHELL		
3.000	TCILR134A FREON R134A		
1.000	MISCHARDWARE		
	BOLTS, NUTS, WASHERS, PENETRATING OIL, BRAKE CLEAN, ECT.		
1.000	PTB4988280CUM P/S PUMP GASKET		

Parts.....

Labor.....

Shop Supplies

Sub Total
Sales Tax....TOTAL
PAID Continued

Date	02/12/19
Date Open	01/02/18

Page: 5 of 5

Ship To :

Written By		Terms		Time 13:46:55		Customer Po #		Promised		Phone		Ship Via			
Unit # RT-4093		Plate # 40B2WZ		Year 2003		Make PETERBILT		Model 357		Mileage/Hrs 805500/0.0		VIN 1NPAXUEX340821565		Engine	

Qty	Description	Price	Amount
2.000	HAI24040 2 1/2 INCH HOSE		
1.000	TCILCT300LSS HOSE CLAMP 3" CONSTANT TORQUE CLAMP		
1.000	TCILCT250LSS CONSTANT TORQUE CLAMP 2 1/2 INCH		

Parts.....	
Labor.....	

Shop Supplies

Sub Total
Sales Tax....

TOTAL	14011.64
PAID	

INVOICE

Date 04/30/19

Date Open 04/04/19

Page: 1 of 3

Sold To :

Ship To :

--	--	--	--	--	--	--	--	--	--

Written By		Terms		Time 14:36:30	Customer Po #		Promised		Phone		Ship Via	
Unit # RT-4093		Plate # 40B2WZ	Year 2003	Make PETERBILT		Model 357	Mileage/Hrs 811681/0.0		VIN 1NPAXUEX340821565			Engine

Qty	Description	Price	Amount
1.000	Work Requested : ENGINE ASSEMBLY TURBO WONT BOOST OVER 15 PSI Work Completed : CHECK TURBO FOR NOT BOOSTING OVER 15 PSI. FOUND WASTE GATE SOLENOID STUCK HOLDING WASTE GATE OPEN. REPLACED SOLENOID, TEST DRIVE, ALL SEEMS OK.		
1.000	CAT2280267 VAVLE GP-MDL		
1.000	CATFREIGHTCHARGE FREIGHT CHARGE		
1.000	Work Requested : ENGINE ASSEMBLY OIL PAN BOLT MISSING Work Completed : INSTALLED OIL PAN BOLT, RECHECKED OTHERS. CHECKED LEAK AT LF CORNER, POWER STEERING PUMP MOUNT GASKET LEAKING.		
1.000	PTB6V5230 BOLT		
1.000	PTB7C8296 ISOLATOR		
1.000	PTB7E3369 SLEEVE		
	Work Requested : BRAKE SYSTEMS LEFT SIDE DRIVE AXLE BRAKES BACK OFF AND RIGHT SIDE DRIVE AXLE BRAKES TIGHTEN DOWN BY THEMSELVES WHILE DRIVING Work Completed : CHECK OUT BRAKES. FOUND LR CLEVIS PIN WRONG SIZE, LF SLACK STRIPPED, ALL S-CAM BUSHINGS VERY WORN CAUSINGS SLACK ADJUSTERS TO NOT KEEP PROPER ADJUSTMENT. RF AND RR SHOES BELOW DOT SPECS.		

Parts.....
Labor.....

Shop Supplies

Sub Total
Sales Tax....

TOTAL

Continued

INVOICE

Date 04/30/19

Date Open 04/04/19

Page: 2 of 3

Sold To :

Ship To :

--	--	--	--

Written By		Terms		Time 14:36:31	Customer Po #		Promised	Phone	Ship Via	
Unit # RT-4093	Plate # 40B2WZ	Year 2003	Make PETERBILT	Model 357		Mileage/Hrs 811681/0.0		VIN 1NPAXUEX340821565		Engine

Qty	Description	Price	Amount
1.000	Work Requested : COOLING SYSTEM FAN WONT SHUT OFF Work Completed : CHECK FAN FOR NOT SHUTTING OFF. CHECK CODES, NONE PRESENT. CHECK WIRING AND SWITCHES. FOUND RUBBED THRU WIRE FOR HIGH PRESSURE SWITCH AT CONDENSER. Mileage In... 442612 Mileage Out 8116810 MISCELECTRICALSUPPL ELECTRICAL SUPPLIES, TERMINALS, BUTT CONNECTORS, BLACK TAPE, ECT.		
	Work Requested : BRAKE SYSTEMS ABS LIGHT ON Work Completed : CHECK FOR ABS LIGHT BEING ON. CHECK CODES AND FOUND LR SENSOR GAP LARGE.		
1.000	Work Requested : STEERING ASSEMBLY AND SYSTEMS POWER STEERING PUMP LEAK Work Completed : REPLACED POWER STEERING PUMP GASKET-WAS LEAKING OIL. TCIL4988280 POWER STEERING GASKET		
	Work Requested : STARTING SYSTEMS Work Completed : MAKE UP 12 FOOT BATTERY CABLE AND FURNISH TO JOHN R.		

Parts.....
Labor.....

Shop Supplies

Sub Total
Sales Tax....

TOTAL

Continued

Date Open 04/04/19

Page: 3 of 3

Ship To :

Written By		Terms		Time 14:36:31		Customer Po #		Promised		Phone		Ship Via			
Unit # RT-4093		Plate # 40B2WZ		Year 2003		Make PETERBILT		Model 357		Mileage/Hrs 811681/0.0		VIN 1NPAXUEX340821565		Engine	

Qty	Description	Price	Amount
1.000	HA13/0BATTERYCABLE BATTERY CABLE WITH ENDS 3/0		

Parts.....	
Labor.....	

Shop Supplies

Sub Total
Sales Tax....

TOTAL	1105.88
--------------	----------------