

# Invoice

Date	Invoice #
7/18/2022	

Bill To

P.O. No.

Item	Quantity	Description	Rate	Amount
Shop Labor	8	Complaint: Brake drum cracked Released brakes and backed off slack adjusters Jacked up axles individually Removed wheels Removed old cracked brake drums Installed new centrifuge brake drums on all 4 drives and both sides of pusher axle Replaced brake shoes on right front drive axle Adjusted all brakes-checked all brakes for hanging up causing overheating		
DB123537	6	Brake drum		
4709	1	Brake Kit		
		2014 KW ODO 148720 VIN# 454771 Lic# 38KS2J Unit# 724		
			<b>Total</b>	\$3,938.60

# Invoice

Date	Invoice #
6/24/2022	9562

Bill To

P.O. No.

Item	Quantity	Description	Rate	Amount
Shop Labor	6	Complaint : PTO coming apart. Removed HD pump from PTO. Removed oil lines to transmission from PTO. R&R PTO We had to rewire the PTO. Clocked the flange on the PTO and installed the HD pump to PTO. Refilled the transmission with 6 gallons of transmission fluid.		
Transmission Fluid	6	Syn Trans Fluid 50 (gallon)		
Misc Parts	1	bolts and washers		
280GDFP-B5RK-R	1	PTO		
Misc Shop Supplies		Misc Shop Supplies		
		KW 2015 T880 VIN 454771 UNIT 7-24		
			<b>Total</b>	\$4,456.63

# Invoice

Date	Invoice #
5/17/2022	9442

Bill To

P.O. No.

Item	Quantity	Description	Rate	Amount
Shop Labor	9	Complaint : Check out all of the brakes. Checked out all the brakes and found the brakes on the back of the truck falling off. This was the noise that the driver was hearing. R&R all rear brakes including the tag axle.		
3600AX	2	Brake Drum		
4707RFLOE	2	Brake Kit		
4709	4	Brake Kit		
Misc Shop Supplies		Misc Shop Supplies		
		2014 KW VIN 454771 MILES 140217		
Total				\$2,048.36