				0.00
	SE MOSE			
	The second second			
	A SHALL DE LA LINE OF THE PARTY OF			- 8
	The state of the state of			
	No. of Concession, Name of Street, or other Persons, Name of Street, Name of S			- 8
	Make:	CASE IH	and state as the	
ust PO:	Model:	3330		
ust Fleet#:				
ob Desc: 3330 REPAIR ENGIN	E NOISE Hours:	6802.0		
	NOISE Hours: Service Order Summ	6802.0		
WO # 2245983 SV 3330 REPAIR ENGINE	Service Order Sumn	6802.0 nary		Amount
WO#	Service Order Sumn	6802.0 nary		Account.
WO#	Service Order Sumn	6802.0 nary		Amount.
WO#	Service Order Sumn	6802.0 nary		America
WO#	Service Order Sumn	6802.0 nary	Price Sales	Annual State of the State of th
WO#	Service Order Sumn	6802.0 nary	Price to the state of the state	Account.
WO#	Service Order Sumn	6802.0 nary	Price Division Section Section	America A America A America America A America A America A A America A A A A America A A A A A A A A A A A A A A A A A A A
WO#	Service Order Sumn	6802.0 nary	Price 13146 50.65	A 100 M
WO#	Service Order Sumn	6802.0 nary	Price 101 to 101	Account of the last of the las
WO#	Service Order Sumn	6802.0 nary	Price 151.60 55.60	American de la companya de la compan
WO#	Service Order Sumn	nary	Price 101.00 101	Account of the last of the las
WO#	Service Order Sumn	6802.0 nary	Price 11 (10 (10 (10 (10 (10 (10 (10 (10 (10	Account of the last of the las
WO#	Service Order Sumn	nary	Price 1016 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	Arrent Ar

3330 REPAIR ENGINE NOISE

Comments:

check fluidscheck codes

run engine and do a injector cut out test. #4 cylinder is dead.

look up parts and help coy

washed off the sprayer, then pulled the sprayer in to the shop and unbolted the valve cover, then found that the brigegs were off of the valves

looked up the valve lash on the exhust and intake valve, started to rotate the engine and check the valve lash on each cycindar

installed the rocker arms and turned turned the engine over and set the valve lash, after that I drained the engine oil and removed the engine oil filter and installed the new filter then filled the engine up with oil and started the sprayer, found that the engine still had a miss and hooked est up to the engine and used eassy tool to check each injector, then found that number 4 injector was bad unbolted the injector and rmeovedit from the engine, started to hook up the compresstion tester.

help coy with diagnosing fuel issues with #4 cylinder, capped off fuel to see if it still smoked.

Labor:

Description Labor				Amount
TRUCK IN		Total Labor		_
endor Part Number	Description	Bin	Price	Ext. Price

Parts	_			Din		Price	Ext. Price
0ty 1.00 1.00 1.00 1.00 2.00 1.00 1.00 1.00	CAS CAS CAS CAS CAS	Part Number 504070040 504344540 FREIGHT FREIGHT 73344233 84228488 504128307R FREIGHT 504100835	Description GASKET ROCKER ARM FREIGHT FREIGHT OIL ENGINE ENGINE OIL FILTER REMAN-FUEL I FREIGHT FITTING	2221 2522		Price	EAL PHOE
-1.00 1.00	CAS	504106633 504128307C BN69860	CORE INJECTOR, FUEL SYSTEM CIRCUIT BREAKER	CORE			
					Total Parts		*******

Total Faits	
Tax	
Total WO	\$5,000.22

Make: Model: CASE IH 3330 Cust PO: Cust Fleet#: Job Desc: 3330 REPAIR ENGINE NOISE Hours: 6802.0 Service Order Summary WO# 3330REPAIR ENGINE FAULT \$2,510.73

	TOTAL INVOICE	\$2,510.73
	Payment Information Client ID: Store ID:	
X Customer Signature		

3330REPAIR ENGINE FAULT


Comments:

look at fault codes and started to dignous engine fault tested the engine harness and order and new one installed the engine harness reloaded software started to digunous the fault codes for the ecu fixed the wiring

found the harness which was a ground for the engine ecu had been rubbing on negative battery cable

Labor:

Description Labor				Amount
Cust PO:		Total Labor		
Parts:				
Qty Vendor Part Number	Description HARNESS, WIRE	Bin	Price	Ext. Price
1.00 CAS 504122747 1.00 MIS PICB1103PT	WIRE			
1.00 MIS PIC4239KT	KT-PACK KT PACK			
1.00 MIS 4238KT 1.00 MIS 4009KT	KT PACK			
		Total Parts		
		Tax		
		Total WO		\$2,510.73



3330 REPLACE ENGINE

surface head, valve job, install 4 seats in cyl 4, crack check, clean head,

Labor:

Description Labor

valve job, crack ck, surface

Amount

Total Labor

Parts	:					10000
		Part Number	Daniel de la constante de la c			
1.00	CAS	504384423ER	Description	Bin	Price	Ext. Price
1.00	CAS	5801645677	REMAN-SHORT ENGINE			
1.00	CAS	87478869	GASKET			
1.00	CAS	2830704	KIT, GASKET			
1.00	CAS	504070040	THICKNESS 1,25 MM			
1.00	CAS	504070038	GASKET			
1.00		5801483558	GASKET			
1.00		5801483583	SEAL, OIL			
1.00		2859342	SEAL, OIL			
5.00		HDWE5	TURBOCHARGER	1400		
1.00		5802497075R	HARDWARE REMAN-WATER PUMP	1400		
1.00		504065877				
1.00			TENSIONER, B BELT TENSIONER	0925		
		504315785	ROLLER, SHIF	0920		
1.00		504065878 504065879	PULLEY	0935		
1.00			SCREW	0000		
12.00		4891024 4891025	SCREW			
14.00		4892867	SCREW			
6.00		73341723	2.5G / 9.46L HYTRAN			
1.00		CC2825	ANTIFREEZE	2433		
2.00		73344233	OIL ENGINE	2221		
1.00		87682984	FILTER, AIR	5031		
		87682985	FILTER, AIR	5050		
1.00		84228488	ENGINE OIL FILTER	2522		
1.00			PKG-FILTER, Evel CITY	2641		
1.00		84412164 504384423EPAC	CORE-EPA ENGINE	CORE		
-1.00			SEAL, SPECIA	2110		
2.00	CAS	ZPX18572	FREIGHT			
1.00	040	FREIGHT	STD EXHAUST	0642		
4.00		4895051	VALVE.ENGINE			
4.00		4895052	PUMP ENGINE OIL			
1.00		5802274911	GASKET	0447		
1.00		4898301	GASKET			
1.00		2830559	GASKET			
1.00	CAS	4896409	REMAN INJECTORS / INNER TUBE			
1.00		MISC	SEAL			
24.00		2831287	15W40 1QT / .95L ENGINE OIL	2310		
1.00		73341699				
1.00		504114491	GASKET			
1.00		4899921	GASKET	0423		
1.00		504380075	THERMOSTAT			
2.00		504062710	PKG-O-RING	0443		
1.00	CAS	5802123628	GASKET	DR22-21		
1.00	CAS	217408	O-RING	Direct.		
1.00		MISC	EXPANSION PLUG			
2.00	CAS	4895406	PLUG	DR41-03		
4.00	CAS	5183780	WASHER, SEALING	Diviso		
1.00		FREIGHT	FREIGHT	0137		
1.00	CAS	87645567R	REMAN, ALTERNATOR	CORE		
-1.00		87645567C	CORE, ALTERNATOR			
3.00		87299775	75W90 GEAR OIL 1QT	2320	9111	
		87341550	BOLT			
1.00	CHO	01011000				

1.00	CAS			
1.00		86980518	NUT	0007
2.00	CAS	J883284	O-RING	0327
1.00	CAS	ZX001	LOW SILICATE CONCENTRATE EG-	3050
	CAS	87341998	BOLT BOLT	4312
3.00	CAS	CC2825	ANTIFREEZE	
5.00	MIS	HDWE5	HARDWARE	2433
1.00	CAS	73344328	OIL HYDRAULIC	1400
2.00	CAS	BMF31GSW		4030
-2.00	CAS	SCRP3	BATTERY, WET	4413
1.00	CAS	73344328	CORE	CORE
1.00	CAS	5801960832	OIL HYDRAULIC	4030
2.00	CAS	84412164	SENSOR, TEMPERATURE	
1.00	CAS		PKG-FILTER, for Gilter	2641
1.00	CAS	73344232	OIL ENGINE	2322
1.00		87272534	FUEL, FILTER TO ENGINE	
	CAS	84204186	ENGINE TO TANK	
1.00	NHL	10261060	GASKET	
1.00	CAS	84412164	PKG-FILTER, ful Cilfer	2641
7.00	NHL	10261060	GASKET THE HITE	

Total Parts

Tax Total WO

\$28,493.88