

Invoice

Date	Invoice #
12/20/2022	

Bill To

P.O. No.	Terms	Project

Quantity	Description	U/M	Rate	Amount
40	T/S cel on, test fuel system with gauges, determined injectors are dumping fuel psi, block test engine, psi test cooling system and found radiator leaking, also air was slow to build, t/s discharge line full of carbon and needs dryer and purge valve, R&R all 6 injectors, R&R fuel filters, R&R discharge line, R&R dryer and purge valve kit, R&R radiator assembly and replace radiator and install assembly, fill with coolant, add 4 gallons of oil, R&R high psi relief valve, run truck, program engine, repair exhaust, found left rear brake chamber leaking, R&R brake chamber and clevis pin			
1	Shop supplies			
	Parts: Injector kit, hp relief valve, high psi lines fuel filter kit, discharge line, fittings, radiator, software, 30/30 brake chamber, clevis and pins, exhaust clamps, gaskets, bellows			
4	10w30 Oil	gal		
	2015 Freightliner Coronado VIN: 3AKJGND60GDHK9365 Mileage: 487,064			
			Total	\$14,416.64

296