

Repair Order Invoice

Page 1 / 1

Invoice Date	Invoice	A/C	Customer PO	Payment Term	Customer Tax #
Mar 24, 2023					

Repair Mar 15, 2023

Unit 1095	VIN 1XP4D49X8GD351686	License DF4571	Last Cert.()
Peterbilt, 687, maroon, high roof sleeper			
Make PETERBILT	Model 687 CONVENTIONAL	Year 2016	Engine

Activity Description	Part Number	Part Description	Quantity	Charge	Unit
----------------------	-------------	------------------	----------	--------	------

1. Sublet Repairs, en route

03-15-23 Peterbilt, Waco, TX

No invoice on file. Billing from Chris email and Tehek record. "the Peterbilt in Waco Invoice is for a turbo on 1096 use the i check sheet, TCT installed it and ive asked for invoice a couple of times and still have not received it. Should be a credit for \$1,021 coming in mail from Peterbilt for the core to our physical address i confirmed this morning."

Replace turbo

Tehek 1578079

SUBLET T_NM

SUBLET REPAIR T_NM **20**

Technician

Authorized

Invoice Total: \$ 8,197.67

Signature: _____

Repair Order Invoice

Page 1/3

Invoice Date	Invoice	A/C	Customer PO	Payment Term	Customer Tax #
Jan 12, 2023					
					Repair Dec 29, 2022
Unit 1096	VIN 1XP4D49X8GD351886	License DF4571	Last Cert.()		
Peterbilt, 587, maroon, high roof sleeper					
Make PETERBILT	Model 587 CONVENTIONAL	Year 2016	Engine		
ODOMETER 625262 MI					
As/Inv Description Part Number / Qty Part Description Amount Charges Total					
1. PM A: Full Service, Chassis Lube, Fluids, Lights, Brakes, Tires, & Body Inspection.					
Ongoing labor exceeding multiple work weeks As of: 01-11-2023 Shop work week: 12-29-22 to 01-11-23 Parts and labor to date. P557004 FUEL FILTER K37-1004 Re Sealed Front Gear Case Replaced Rear Main Seal Re Sealed Bellhousing Replaced Water Pump Replaced Pan Gasket					
2. PM A: Full Service, Chassis Lube, Fluids, Lights, Brakes, Tires, & Body Inspection.					
P556776	FF/WS SPIN FUEL FILTER				
P560949	LUBE SPIN				
FILTERW	OIL FILTER WASTE				
55655-E	15W-40 HP EXPRESS OIL				
3. PM AIR: Replace Engine Air Filter					
P549644	AIR FILTER PRMYRS				
4. PM DRY: System Air Dryer (Filter Replacement)					
P961413	SPIN ON AIR FILTER DRIER				

Repair Order Invoice

Page 2 / 3

Invoice Date	Invoice	A/C	Customer PO	Payment Term	Customer Tax #
Jan 12, 2023					
Part Number (O) Part Description Quantity Change Total					
5. PM INS: Repair, Inspect, or Brief Assessment					
Ongoing labor exceeding multiple work weeks As of: 01-11-2023 Shop work weeks: 12-29-22 to 01-11-23 Parts and labor to date.					
Reassemble front, rear, and oil pan.					
4393089CUM	GASKET-GEAR HOUSING				
6440813CUM	Gasket, Acc Drive Support				
6414049CUM	Gasket, Fuel Pump				
5658175	Gasket, Gear Housing				
3685556CUM	GASKET ADAPTER				
4289124CUM	SEAL-O RING				
4289125CUM	SEAL-REAR O RING				
5718778	Gasket, Camshaft Cover				
3685173CUM	SEAL, OIL				
3887007CUM	Seal, Rectangular Strip				
5594275NX	Sensor, Position				
5594275NX-C	Core, Sensor, Position				
5594275NX-C	Core, Sensor, Position				
6306090RXCUM	Kit, Water Pump				
6306090RXCUM-CORE	Core, Kit, Water Pump				
6306090RXCUM-CORE	Core, Kit, Water Pump				
4393176	Gasket, Flywheel Housing				
4965668CUM	Kit, Seal, Rear Main				
N14A	1/4" CABLE TIE 120 LB				
3675724CUM	SEAL- O RING WATER PUMP ISX				
6712L	# 12 HOSE CLAMP LINED				
4026884CUM	Gasket Oil Pan				

Repair Order Invoice

Page 3/3

Invoice Date	Invoice	A/C	Customer PO	Payment Term	Customer Tax #
Jan 12, 2023					
Part Number	Part Description	Quantity	Unit Price	Total	
b22353	3/8 X 1/4 Hex BUSHING				
108-4	EXTERNAL SEAT DRAIN				
6,5-70-18X	U JOINT STRAP KIT				
3687932	CAP, FILLER				
0716858301FTG	FITTING ELBOW 90 DEG 3/8"				
100216	FUEL BIOCID				

Authorized

Invoice Total: \$ 12,774.98

Signature: _____