

Repair Order Invoice

Page 1 / 1

Invoice Date	Invoice	A/C	Customer PO	Payment Term	Customer Tax #
Jan 27, 2020					

Repair Jan 24, 2020

Unit 1031	VIN 1XP7D49X87D740634	License	Last Cert.()
387 PET			
Make	Model	Year 2007	Engine
ODOMETER 1490182 MI			

Activity Description	Part Number	Part Description	Quantity	Charge	Total
1. Sublet Repairs, en route					
01-24-20 JX Truck Center, Elmhurst, IL Replace rusted out primary air tank and repair system wide air leaks Replace #6 fuel injector and valve-pressure regulator Repair coolant leak Replace idler pulley and belt Replace EGR valve Replace drive line U-joint Check SUBLET T_NM SUBLET REPAIR T_NM **20**					

Technician

Authorized

Invoice Total: \$ 7,354.17

Signature: _____

Repair Order Invoice

Page 1 / 3

Invoice Date	Invoice	A/C	Customer PO	Payment Term	Customer Tax #
Oct 24, 2019					

Repair Oct 21, 2019

Unit 1031	VIN 1XP7D49X87D740634	License	Last Cert. ()
387 PET			
Make	Model	Year 2007	Engine
ODOMETER 1468553 MI			

Activity Description	Part Number	Part Description	Quantity	Charge	Total
----------------------	-------------	------------------	----------	--------	-------

1. Inspection & Repairs

R/R WIPER BLADES AND TEE FOR SPRAYER
R/R AC LINE COMPRESSOR TO CONDENSER
R/R WASHER TEE
R/R MIRROR SWITCH
R/R CAB EXPANSION VALVE.
R/R CAB EVAP
R/R NON PRESSURE P/S LINE
R/R AXLE 2 SLACK ADJUSTERS
R/R AXLE 2 RH BRAKE CHAMBER
R/R AXLE 3 LH BRAKE CHAMBER
R/R AXLE 3 RH TORSION BAR
R/R AXLE 2 TRACK BAR
R/R YOKE AT TRANS
R/R UJOINT AT TRANS
R/R ALL 40 DRIVE WHEEL STUDS
R/R AXLE 2 L AND R WHEEL SEAL
R/R DRIVER LOWER STEP
R/R TUBES IN RH TANK FARING
R/R BACK GARING BRACKET WITH USED
R/R AXLE #3 BRAKES AND DRUMS
R/R AXLE 2 LH BRAKES
GREASED DRIVE LINE AND 5TH WHEEL
R/R DOWN PIPE AND FLEX PIPE

31-200	WIPER BLADE
W58-1	387 WASHER TEE
0015	A/C O-RING # 10 HOSE
D9027-9877	LINE-A/C CONDENSOR TO COMPRESSOR
AUV10602	5/8 TUBE CLAMP 13/32 EYE
P27-1037-2	SWITCH-MIRROR
151338BSM	COIL ASSY-EVAP HVAC ALUM/COPPER
SR2000020	SWITCH-FREEZE CONTROL
F90-6001	VALVE-EXPANSION
CD12340	BOLT-STEEL, CAB EXP. VALVE BOLT
SR2000057	FILTER-FRESH AIR HVAC W/O META
0015	A/C O-RING # 10 HOSE

Repair Order Invoice

Page 2/3

Invoice Date	Invoice	A/C	Customer PO	Payment Term	Customer Tax #
Oct 24, 2019					
Activity Description					
Part Number	Part Description	Quantity	Charge	Total	
0011	A/C O-RING # 6 HOSE				
0013	A/C O-RINGS				
5706L	# 6 HOSE CLAMP LINED				
HE2277	1/2" OIL RESISTANT HOSE #8				
WK4709ES2-20W	EAT ES2 STYLE VALUE WHEEL KIT				
40010143	ADJUSTER-BRAKE 10 SPL, 5.5" DR				
3030SB	COMBO SPRING BRAKE				
PRLCF3	CLEVIS FORGED				
Q347367FLG	CAP-FILL VENTED, P/S RESERVOIR				
M66-6026	PIPE-EXHAUST MBEND 4" STL ALMZ				
10028-6	CLAMP-STEEL, EXHAUST 4"				
X007784	SEAL CLAMP 4" BAND				
46917	4IN STAINLESS FLEX TUBE				
C85-6023-002	ROD-RADIUS FLEX AIR/AG380				
M8CS16C140	16M-2.0 X 140M 10.9 HHCS				
G8US062	5/8 SAE GD 8 WASHER				
M8NY16C	M16-2.0 METRIC NYLOCK NUT				
6,5-4-4631-1	YOKE				
CM10001331	WHEEL STUD LONG				
309-0973	GUARDIAN HP SEAL				
3566966C1	GASKET AXLE SHAFT FLG R T U				
41055555-4	75-90 SYN. GEAR OIL				
G8US050	1/2 SAE GD 8 WASHER				
C65-6020	ROD TRACKING, FLEX AIR				
6,5-70-18X	U JOINT STRAP KIT				
SDD15-676X	U JOINT KIT ALT OEM # 5-676X				
11-04006-0775	STEP-FUEL TANK ALUM 775MM				
47972	TRACTOR SIDE SKIRT TUBE				

Repair Order Invoice

Page 3 / 3

Invoice Date	Invoice #	A/C	Customer PO	Payment Term	Customer Tax #
Oct 24, 2019					

Activity Description		Quantity	Charge	Total
Part Number	Part Description			
15-06844	SPACER-FAIRING			
FLT4400B	BRAKE DRUMS REAR / TRAILER			
2. PM B Half Service				
55555-6	PRIDE SERIES EP1 GREASE			

Authorized

Invoice Total: \$ 6,678.95

Signature: _____

Repair Order Invoice

Page 1 / 3

Invoice Date	Invoice	A/C	Customer PO	Payment Term	Customer Tax #
May 22, 2019					

Repair May 21, 2019

Unit 1031	VIN 1XP7D49X8/D740634	License	Last Cert. ()
387 PET			
Make	Model	Year 2007	Engine
ODOMETER 1423454 MI			

Activity Description	Part Number	Part Description	Quantity	Charge	Total
1. PM A Full Service					
	P550949	LUBE SPIN			
	P562200	FUEL FILTER			
	P562203	FUEL FILTER			
	FILTERW	OIL FILTER WASTE			
	CTS	2-WAY H.D. COOLANT TEST STRIP			
	55555-E	15W-40 HP EXPRESS OIL			
	55555-6	PRIDE SERIES EP1 GREASE			
2. PM AIR Replace air filter					
	P549644	AIR FILTER PRMYRS			

Repair Order Invoice

Page 2 / 3

Invoice Date	Invoice	A/C	Customer PO	Payment Term	Customer Tax #
May 22, 2019					

Activity Description	Part Number	Part Description	Quantity	Charge	Total
----------------------	-------------	------------------	----------	--------	-------

3. Inspection & Repairs

R/R FRONT BANK TIMING AND METERING ACTUATORS
R/R FUEL SHUT OFF
R/R CLAMP ON DP AT TURBO
R/R BOTTOM CLAMP FRONT FLEX PIPE
R/R INJECTORS #3, #4, #5, #6
R/R REAR BANK TIMING ACTUATOR
RAN OVERHEAD
R/R RH TURN SIGNAL REAR

4024808CUM	KIT, FUEL SOLENOID
4088863CUM	HOUSING-ACTUATOR
129839CUM	COVER-SHUTOFF VALVE
129768CUM	SPRING, VALVE
196057CUM	DISC, VALVE
4088274CUM	DISC, ACTUATOR
4089986RXCUM	ACTUATOR-TIMING KIT
4089986RXCUM-CORE	CORE-ACTUATOR-TIMING KIT
4089986RXCUM-CORE	CORE-ACTUATOR-TIMING KIT
4089985RXCUM	ACTUATOR-METERING KIT
4089985RXCUM-CORE	CORE-ACTUATOR-METERING KIT
4089985RXCUM-CORE	CORE-ACTUATOR-METERING KIT
10028-6	CLAMP-STEEL, EXHAUST 4"
X007784	SEAL CLAMP 4" BAND
4088665PXCUM	INJECTOR-HD HPI
4088665PXCUM-CORE	CORE-INJECTOR-HD HPI
4088665PXCUM-CORE	CORE-INJECTOR-HD HPI
1157	BULB, m/nl
3347937	SEAL,O RING
3330537	SEAL O RING CUMMINS
3347937	SEAL,O RING

Repair Order Invoice

Page 3 / 3

Invoice Date	Invoice	A/C	Customer PO	Payment Term	Customer Tax #
May 22, 2019					

Activity Description					
Part Number	Part Description	Quantity	Charge	Total	
DIAG.COMP	DIAGNOSTIC COMPUTER HOOK UP				
OVERHEAD	OVERHEAD PROCEDURE				

Authorized

Invoice Total: \$ 7,522.52

Signature: _____

Repair Order Invoice

Page 1 / 6

Invoice Date	Invoice	A/C	Customer PO	Payment Term	Customer Tax #
Aug 20, 2018					

Repair Aug 9, 2018

Unit 1031	VIN 1XP7D49X87D740634	License	Last Cert. ()
387 PET			
Make	Model	Year 2007	Engine
ODOMETER 1357097 MI			

Activity Description		Quantity	Charge	Total
Part Number	Part Description			
1. PM A Full Service				
P550949	LUBE SPIN			
P552200	FUEL FILTER			
P552203	FUEL FILTER			
FILTERW	OIL FILTER WASTE			
55555-E	15W-40 HP EXPRESS OIL			
CTS	2-WAY H.D. COOLANT TEST STRIP			
55555-6	PRIDE SERIES EP1 GREASE			

Repair Order Invoice

Page 2 /6

Invoice Date	Invoice	A/C	Customer PO	Payment Term	Customer Tax #
Aug 20, 2018					
Activity Description	Part Number	Part Description	Quantity	Charge	Total
2. Inspection & Repairs					
R/R VALVE CAM AND VALVE TRAIN.					
R/R UPPER GEAR COVER					
R/R INJECTORS					
R/R EGR VALVE					
R/R BOTH BELTS					
R/R LARGE TENSIONER					
R/R JAKE HARNESS					
R/R ALL BRAKES AND DRIVE DRUMS.					
R/R LFD, RRD, RFD WHEEL SEAL					
NEW BEARINGS TL/R/F					
	3685690CUM	ISX CAM BEARING			
	4298626CUM	CAMSHAFT			
	4299124CUM	SEAL-O RING			
	3679931CUM	SEAL-O RING			
	3679932CUM	Gasket, Camshaft Cover			
	4299125CUM	SEAL-REAR O RING			
	4962721CUM	SEAL-RECTANGULAR STRIP			
	3684273CUM	COVER-GEAR			
	3347939	SEAL, O RING CUMMINS			
	3330537	SEAL O RING CUMMINS			
	3347937	SEAL,O RING			
	3330538	SEAL O RING CUMMINS			
	3682826CUM	SEAL GROMMET SMALL BLUE PACKING			
	904-5001	EGR VALVE 4956422RX, 3683 305, 3682974			
	PA1042029	CLAMP V BAND CUM3683144			
	3683145CUM	CLAMP-V-BAND			
	K060637HD	387 ALT BELT GREEN FLEETRANNER			
	K120872HD	387 FAN BELT GREEN FLEETRANNER			
	38587	TENSIONER			
	HE2291	5/8 OIL RESISTANT HOSE # 10			

Repair Order Invoice

Page 3 / 6

Invoice Date	Invoice	A/C	Customer PO	Payment Term	Customer Tax #
Aug 20, 2018	1				
Activity Description	Part Number	Part Description	Quantity	Charge	Total
	4331263CUM	HARNESS-WIRING (COMPRESSION BRAKE)			
	3902662CUM	NUT, HEXAGON FLANGE			
	4336706CUM	SCREW-STUDDER FLANGE CAP			
	449-4973	PRO-TORO SPINDLE NUT			
	ASET594A-92A	STEMCO 594A/592A			
	ASET580-72	STEMCO BEARING 580/572			
	3566966C1	GASKET AXLE SHAFT FLG R T U			
	XKEG4709E2	SHOE BRAKE W/LINING			
	DB1657B	DRUM-BRAKE 16.5 BAL TRP			
	41055555-4	75-90 SYN. GEAR OIL			

Repair Order Invoice

Page 4 / 6

Invoice Date	Invoice	A/C	Customer PO	Payment Term	Customer Tax #
Aug 20, 2018					

Activity Description	Part Number	Part Description	Quantity	Charge	Total
3. Inspection & Repairs					
R/R CAB FILTER R/R REAR FILTER CHARGED AC SYSTEM					
	HE9625	HOSE-CHARGE AIR COLD			
	5-46164	RUBBER COVERED CLAMP 1"			
	82194	PERMATEX ULTRA GRAY			
	4059329CUM	VALVE-CROSSHEAD			
	4059342CUM	VALVE - CROSS HEAD			
	5484231CUM	LEVER-ROCKER			
	5484230CUM	LEVEL-ROCKER			
	5484229CUM	LEVER, ROCKER			
	5484228CUM	LEVER ROCKER			
	4393087CUM	LEVER, ENGINE BRAKE			
	525525BSM	GRILLE-RECIRCULATION			
	SR2000057	FILTER-FRESH AIR HVAC W/O META			
	0011	A/C O-RING # 6 HOSE			
	0013	A/C O-RINGS			
	0015	A/C O-RING # 10 HOSE			
	5-46301	CLAMP - RUBBER CUSHION, 3/8"			
	309-0973	GUARDIAN HP SEAL			
	GUNM705	PRO-SERIES NON CHLORINATED BRAKE CLEAN			

Repair Order Invoice

Page 5 /6

Invoice Date	Invoice	A/C	Customer PO	Payment Term	Customer Tax #
Aug 20, 2018					

Activity Description	Part Number	Part Description	Quantity	Charge	Total
4. Inspection & Repairs					
INSURANCE PARTS					
	G8CS062750	5/8-11 X 7-1/2 NC GRADE 8 HEX			
	G8US062	5/8 SAE GD 8 WASHER			
	G8NY062	5/8-11 GD 8 NYLOCK			
	TU28R2215-16NS	PB 125SS-ALUM, LMP/STEP/2LCPTL			
5. Tractor Repair Memo-Tractor General					
06-22-18 Accident, Great West Claim Hit deer, center front bumper, dented, minor.					
6. Tractor Repair Memo-Tractor General					
05-22-18 Accident Claim Great West Reported a minor scratches, TS fender and bumper. Please inspect and take pictures as necessary.					

Authorized

Repair Order Invoice

Page 6 / 6

Invoice Date	Invoice	A/C	Customer PO	Payment Term	Customer Tax #
Aug 20, 2018					

Invoice Total: \$ 10,485.02

Signature: _____

Repair Order Invoice

Page 1 / 1

Invoice Date	Invoice	A/C	Customer PO	Payment Term	Customer Tax #
Jun 5, 2017					

Repair Mar 29, 2017

Unit 1031	VIN 1XP7D49X87D740634	License	Last Cert. ()
387 PET			
Make	Model	Year 2007	Engine
ODOMETER 1270776 MI			

Activity Description	Part Number	Part Description	Quantity	Charge	Total
1. Sublet Repairs, en route				HR	
03-29-17 Performance Truck, Baytown, TX Loud engine knock, # 4 cylinder dropped a valve. Replace head, camshaft. Complete overhead. Tchek					
	SUBLET T_NM	SUBLET REPAIR T_NM **20**	1.00	EA	

Technician _____ Authorized _____

\$

Invoice Total: \$ 17,585.09

Signature: _____

Repair Order Invoice

Page 1 / 1

Invoice Date	Invoice	A/C	Customer PO	Payment Term	Customer Tax #
Apr 28, 2016					

Repair Apr 25, 2016

Unit 1031	VIN 1XP7D49X87D740634	License	Last Cert. ()
387 PET			
Make	Model	Year 2007	Engine
ODOMETER 1169903 MI			

Activity Description				
Part Number	Part Description	Quantity	Charge	Total
1. Sublet Repairs, en route				
04-25-16 MHC Kenworth, Memphis, TN				
Fan hub assembly came apart allowing fan to go through radiator. Replace with new radiator, fan hub, blade. AC line failed, replaced and recharged system.				
SUBLET T_NM	SUBLET REPAIR T_NM **20**			

Technician

Authorized

Invoice Total: \$ 6,424.81

Signature: _____

Repair Order Invoice

Page 1 / 4

Invoice Date	Invoice	A/C	Customer PO	Payment Term	CustomerTax#
Feb 9, 2015					

Repair Jan 26, 2015

Unit 1031	VIN 1XP7D49X87D740634	License	Last Cert. ()
387 PET			
Make	Model	Year 2007	Engine
ODOMETER 1062394 MI			

Activity Description	Part Number	Part Description	Quantity	Charge	Total
----------------------	-------------	------------------	----------	--------	-------

1. Repairs

Includes maintenance sheet 028554, 028650, 028653, 028660

4985562CUM	GASKET-COVER FRONT ISX
4059393CUM	HOUSING, GEAR
4965690CUM	GASKET-SUPPORT ACCESSORY DRIVE
3682867CUM	TUBE, VENT
4309500NXCUM	KIT-LUBE PUMP
4309500NXCUM-CORE	CORE-KIT-LUBE PUMP
4309500NXCUM-CORE	CORE-KIT-LUBE PUMP
4955383CUM	SEAL-OIL
4973081CUM	COVER-GEAR
3878838CUM	ISX INTAKE HEAD PLUG
4331387RXCUM	HEAD-CYLINDER PREMIUM VALVE
4331387RXCUM-CORE	CORE-HEAD-CYLINDER PREMIUM VALVE
4331387RXCUM-CORE	CORE-HEAD-CYLINDER PREMIUM VALVE
4962722CUM	SEAL-RECTANGULAR STRIP
3678506CUM	SCREW, HEX FLANGE HEAD CAP
4088665PXCUM	INJECTOR-HD HPI
4088665PXCUM-CORE	CORE-INJECTOR-HD HPI
4088665PXCUM-CORE	CORE-INJECTOR-HD HPI
3688114CUM	PLUG-GEAR COVER
2864399CUM	387 ISX JAKE BRAKE WIRE HARNESS
4965698CUM	SCREW-HEX FLANGE HEAD CAP
K120872HD	387 FAN BELT GREEN FLEETRANNER
K060637HD	387 ALT BELT GREEN FLEETRANNER
49563	TENSIONER GATORBACK HD

Repair Order Invoice

Page 2 / 4

Invoice Date	Invoice	A/C	Customer PO	Payment Term	CustomerTax#
Feb 9, 2015					

Activity Description	Part Number	Part Description	Quantity	Charge	Total
	4735-44003-12	BLADE-FAN 32"			
	3103015CUM	SEAL GROMMET LARGE BLUE PACKING			
	SR2000057	FILTER-FRESH AIR HVAC W/O META			
	SHOPPTS	SHOP PARTS			
	65495MON	SHOCK-ABSORBER GAS MAGNUM 65			
	AC	A/C MACHINE HOOK UP			
	R134A	FREON			
	0015	A/C O-RING # 10 HOSE			
	0011	A/C O-RING # 6 HOSE			
	0013	A/C O-RINGS			
	3682826CUM	SEAL GROMMET SMALL BLUE PACKING			
	N56-6000	PAWL-LATCH			
	J-N2-99-13	LATCH-TOOL BOX			
	888-5403	(R) HEADLAMP PETERBILT 386/87			
	888-5404	(L) HEADLAMP PETERBILT 386/87			
	61A3002-0474	HARNES-HEADLAMP W/O BULB SOCKET			
	65101MON	SHOCK-ABSORBER GAS MAGNUM 65			
	4928594CUM	SENSOR-PRESSURE			
	45300 51	2 1/4" HD FLEX GEAR CLAMP			
	13-05168	PIVOT ASSY-HOOD			
	MA28RD210-16	BUMPER-PETERBILT 387 SS CLAD A			
	12-008	GLADHAND, EMERGENCY, RED, STD			
	12-006	GLADHAND, SERVICE, BLUE, STD			
	17-1488	HD TENDER SPRING 20.5IN			
	30-2154	ELECTRICAL/AIR ASSEMBLY			
	MASC3AP3-42	ANTENNA-RAMI 42" BLK 387			
	P1030-3A	GLASS-SIGHT SURGE TANK			
	3678506CUM	SCREW,HEX FLANGE HEAD CAP			

Repair Order Invoice

Page 3 / 4

Invoice Date	Invoice	A/C	Customer PO	Payment Term	CustomerTax#
Feb 9, 2015					
Activity Description	Part Number	Part Description	Quantity	Charge	Total
	08-02713C	STICK-POGO 41" CHROME PLATED			
	15-06845	BOLT-J FAIRING 387			
	PP201070	HARNESS-RADIO 16 PIN ISO DIN			
	KENKDC-X599	BT USB / CD / R RADIO			
	HB9PB	BUTTON-HORN W/TERMINAL			
	121-0001-000	KNOB HEATER CONTROL FAN S			
	DT06-08SA-P012	CONNECTOR			
	CN40800	WEDGELOCK-8 CAV DEUTSCH SOCKET			
	CN24800	TERMINAL-END DEUTSCH SOCK			
	MATTRESS.TOP	MATTRESS TOP BUNK			
	4352289CUM	KIT-OVERHAUL ISX			
	HDA217P	ABS CHROME FRONT WHEEL AXLE COVERS			
	18-05114	BEZEL-HVAC CONTROL			
2. PM A Full Service					
	P550949	LUBE SPIN			
	P552200	FUEL FILTER			
	P552203	FUEL FILTER			
	55555-E	15W-40 HP EXPRESS OIL			
	FILTERW	OIL FILTER WASTE			
	55555-6	PRIDE SERIES EP1 GREASE			
	X869C	5TH WHEEL GREASE			
	74800.0970.12	REFRIGERATOR-1.8 CF			
	2D31161BSNSN	SEAT-ATLAS II DLX W/ARMS TAN L			

Repair Order Invoice

Page 4 / 4

Invoice Date	Invoice	A/C	Customer PO	Payment Term	CustomerTax#
Feb 9, 2015					

Activity Description	Part Number	Part Description	Quantity	Charge	Total
----------------------	-------------	------------------	----------	--------	-------

3. PM AIR Replace air filter

P549644 AIR FILTER PRMYRS

4. Sublet Repairs

SUBLET UTB SUBLET UNITED TRUCK & BODY DES MOINES

SUBLET:T_NM SUBLET REPAIR T_NM **20**

Authorized

Invoice Total: \$ 29,844.10

Signature: _____

Repair Order Invoice

Page 1 / 1

Invoice Date	Invoice	A/C	Customer PO	Payment Term	CustomerTax#
Aug 31, 2015					

Repair Aug 5, 2015

Unit 1031	VIN 1XP7D49X87D740634	License	Last Cert. ()
387 PET			
Make	Model	Year 2007	Engine

Activity Description	Part Number (0)	Part Description	Quantity	Charge	Total
1. Sublet Repairs, en route					
07-21-15 to 08-05-15 Peterbilt, Joplin, MO					
Engine miss. #1 injector bad, performed turbo and egr test, both passed, found oil coming out of exhaust manifold joint, possible head or cylinder problem, removed valve covers and found the #1 intake valve bridge gone, cam shaft bad, reinstalled valve bridge and reassembled valve covers, parked truck along fence.					
SUBLET T_NM SUBLET REPAIR T_NM **20**					

Technician

Authorized

Invoice Total: \$ 411.29

Signature: _____