
UNIT #	ODOMETER	HRS
V=HN977298	738,363	N/A

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
		<p>(A) CHECK TRANNY OP - R+R X4 BATTERIES. CLEANED POWERS + GROUNDS. PULLED INTO SHOP. HOOKED UP COMPUTER + PULLED CODES. PERFORMED TEST + FOUND CLUTCH NEEDS REPLACED. ADVISED CUSTOMER.</p> <p>- REMOVED DRIVE LINE, X2 FRONT SEATS, FLOOR MAT, DOG HOUSE, COVER/FLOOR PLATE, COOLANT/AIR LINES. DISCONNECTED ELECTRICAL & REMOVED BELL HOUSING BOLTS.</p> <p>- PULLED TRANNY + CLEANED AREA. R+R REAR MAIN SEAL + RESURFACED FLYWHEEL. INSTALLED NEW REAR MAIN SEAL + MOUNTED FLYWHEEL. REPLACED CLUTCH ACCUATOR + CLUTCH. MOUNTED CLUTCH W/NEW BELL HOUSING BOLTS. INSTALLED X2 NEW COOLANT LINES TO FILTER HOUSING. REPLACED FILTER + FILLED W/NEW OIL. REPAIRED AIR LEAKS W/NEW FITTINGS. COULD NOT GET UNIT TO CALIBRATE. R+R SOLENOID VALVE. CALIBRATED + RESET LEARNED DATA. ALL OK.</p>			

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
		- HAD TO PUT IN FUEL FOR TEST DRIVE.			
	BATTERY - THREADED (CCA 925)	(H) 31SXHD	4		
	Sales	NIPPLE = 22.90 ELBOW NIPPLE = 31.37 SOLENOID VALVE = 590.92	1		
	LABOR	(B) CHECK FOR DPF CODE - FOUND ACTIVE SOOT LEVEL CODE. DIAG UNIT + REPLACED DPF DIFFERENTIAL PRESSURE SENSOR. PERFROMED REGEN + CRYSTAL SUBLIMATION. ROAD TESTED. ALL OK.	4.50		
	Sales	DIFFERENTIAL PRESSURE SENSOR	1		
	Sales	FUEL	1		
	BRAKE CLEANER 19 OZ	(E) BERRYMAN	4		

LOCATION = SHOP

TECH = 2+3

SUBTOTAL

TAX

TOTAL

PAYMENT

BALANCE DUE

6,246.96