



Date	Invoice #
2/26/2019	.....

Bill To	Unit #	VIN	Engine
	19208	7C422841	ISX Cummins
Make/Model	Year		
IH 9900i	2006		

**PAID**  
02/10/2021

Quantity	Description	Rate	Amount
	<p>Mileage: 1,049,312    Engine S/N: 79207690</p> <p>Replaced engine block with good used part. Overhauled engine: replaced liners, pistons, and cylinder head. Replaced #1 injector. Replaced valve camshaft. Replaced intake and exhaust rocker arms. Replaced oil pump. Replaced clutch and front motor mounts. Rear motor mounts checked good and were reused. Full Service: change oil and filters; grease chassis; check fluids, boxes, brakes, and seals; test coolant; inspect chassis Counter bore charge: includes price of liner shims Removed top plate of transmission and inspected gear train. Found missing or damaged teeth on several gears. Tore transmission down and rebuilt with new parts as needed. Replaced all bearings, gaskets, and seals. Windshield repair Flywheel resurfacing charge Repaired right rear brake light wiring. Replaced left rear drive axle wheel seal and brakes. Replaced left front drive axle wheel seal.</p> <p>1 Used block 1 Used crankshaft 1 Clutch 2 Motor mount: front 12 Gallon of 50/50 engine coolant 1 Overhaul kit: OEM</p>		
1		<b>Total</b>	

Date	Invoice #
2/26/2019	-----

Bill To	Unit #	VIN	Engine
	19208	7C422841	ISX Cummins
Make/Model	Year		
IH 9900i	2006		

**PAID**  
**02/10/2021**

Quantity	Description	Rate	Amount
1	Cylinder head: OEM exchange		
6	Rod bearing		
1	Injector: OEM exchange		
1	Turbo: OEM exchange		
1	Oil pump: OEM exchange		
12	Rocker lever: intake and exhaust		
1	Camshaft: valve		
1	Shut off valve		
1	Shut off valve		
6	Bolt: injector hold down		
6	Piston oiler		
1	Thermostat		
1	Pick-up tube: engine oil		
1	O-ring		
1	Seal		
1	Seal		
1	Belt tensioner		
2	Head bolt		
1	Camshaft bolt		
1	Camshaft bolt		
1	Oil cooler install kit		
1	Gasket		
1	Gasket		
2	O-ring		
2	O-ring		
1	O-ring		
1	Freeze plug		
1	Freeze plug		
2	O-ring		
		<b>Total</b>	

Date	Invoice #
2/26/2019	.....

Bill To	Unit #	VIN	Engine
[REDACTED]	19208	7C422841	ISX Cummins
		Make/Model	Year
		IH 9900i	2006

**PAID**  
02/10/2021

Quantity	Description	Rate	Amount
12	Flywheel mounting bolt		.
4	Lock nut		.
1	Rear main seal		.
1	Gasket: rear structure		.
1	Front main seal		.
1	Seal: lower gear cover		.
1	Front structure gasket		.
1	O-ring		.
1	Gasket		.
1	Pilot bearing		.
6	Grommet		.
1	AC receiver drier		.
1	Air to Air: aftermarket		.
1	Mounting kit: AC condensor		.
1	Oil fill tube		.
1	Starter: New Delco Remy		.
2	5" flex pipe per foot		.
2	5" band clamp		.
1	Brake shoe kit		.
2	Wheel seal		.
2	Axel gasket		.
2	Spindle nut		.
2	Gallon of 75/90W synthetic fluid		.
3	lb of 134A freon		.
4	Gallon 50W synthetic fluid		.
1	Clutch brake		.
	Transmission parts:		.
1	Basic overhaul kit		.
		<b>Total</b>	

Date	Invoice #
2/26/2019	-----

Bill To	Unit #	VIN	Engine
██████████ ██████████ ██████████ ██████████	19208	7C422841	ISX Cummins
		Make/Model	Year
		IH 9900i	2006

**PAID**  
**02/10/2021**

Quantity	Description	Rate	Amount
1	Mainshaft key		
1	Gear: mainshaft: direct drive		
2	Gear: main countershaft: overdrive		
1	Bearing cover		
2	Snap ring		
1	Synchronizer assembly w/ hub		
1	Gear: mainshaft: overdrive		
2	Gear: main countershaft: direct drive		
1	Oil pump		
2	Hose		
1	Hose		
1	Hose		
1	Tail shaft nut		
1	O-ring		
1	O-ring		
2	Snap ring		
1	Snap ring		
1	Idler shaft: good used		
2	Auxilliary counter shaft		
	Freight charges		
	Discount		
	Sales Tax		
		<b>Total</b>	<b>\$42,125.79</b>