Cust. Unit #: VIN: 1XP5D49X55D872304	Make: Model #:	PETERBILT	Model: In Serv Date:	379 12/31	Tag #: Year:	626 2005
Engine S/N: 60810240	Model #:	cummins isx	In Serv Date:		Mileage:	879,212
Tran S/N:	Model #:		In Serv Date:		Eng Hrs:	0
Reefer S/N:	Model #:		In Serv Date:		Warr ID:	
APU S/N:	APU Gen S/N:		In Serv Date:		Date Creat	te: 03/06/2024
			BOM/Spec:			


Sold Operations

Condition CUSTOMER STATES LOW POWER AND ENGINE MISS

FOUND CAM SHAFTS WORN

Correction | REPLACED CAMSHAFTS

Qty	Item	Description	Price Each	Extended	
—	OTH-GEN	EXPRESS ASSESSMENT			
	OTH-GEN	REMOVE OIL PAN AND INSPECT			
	OTH-GEN	CAMSHAFT- REMOVE AND INSTALL			
	CMN-GEN	Engine - Diagnostic Road Test/Off-Highway Engine Verification			
	CMN-GEN	STEAM CLEAN COMPLETÉ ENGINE			
	CMN-GEN	R/R AIR FILTER			
	CMN-GEN	R/R INTAKE TUBE AT TURBO			
2	OWI 23519396	ANTFRZ-DDC PWRCOL ELC OAT 50/5			
2	3903112	SCREW, HEX FLANGE HEAD CAP			
1	3822567	TOOL, ENGINE BLOWBY			
4	3680781	SCREW, HEX FLANGE HEAD CAP			
1	4962721	SEAL, RECTANGULAR STRIP			
1	4299125	SEAL, O RING			
1	4299124	SEAL, O RING			
1	4985661	SEAL, RECTANGULAR RING			
1	4985660	SEAL, RECTANGULAR RING			
1	4298626	CAMSHAFT			
1	4101432	CAMSHAFT			
3	5484228	LEVER, ROCKER			
3	5484230	LEVER, ROCKER			



Prepay:

Taxes: Total:

12,197.71

Shop Supplies (ESC):

This document is subject to the General Terms and Conditions, the Mechanic's Lien Rider, the Abandoned Vehicle Rider, the Storage Fee & Lien Rider, Tampered Emissions Systems Policy, and Code of Conduct, which are expressly incorporated herein by reference, and are available at:

All claims must be accompanied by this invoice. Diagnostic and Technical service charge may apply.

CASH