

Ship to: N/A

Branch

Date
10/09/20

Time
19:02:57 (B)

Page
01

Phone No.

Invoice No.
W5527201

Ship Via

Purchase Order
D7812-753

Invoice to:

Tax Exemption Number

Federal ID Number

Salesperson
JVK / AKR

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
X583853	CRAWLER DOZER >130 750K	6126	1T0750KXACE230238	06/07/14 06/05/18	5000 H

SEGMENT# 1 C MCJ01 NA 09/30/20 09/30/20

Remove and install complete undercarriage

CONDITION:

Block machine, remove tracks, rollers, and idlers.

Look over machine.

Clean and reinstall new rollers, idlers, and tighten to spec.

Remove sprockets and inspect mounting hub surface.

Reinstall sprockets with new hardware and torque to spec.

Wrap tracks and tension to spec, lap yard and recheck.

CORRECTION:

-Raised machine and released track tension

-Removed master pad bolts and pads and removed tracks

-Removed sprocket segments, carrier rollers, bottom rollers and idlers

-Cleaned all mating surfaces on the machine and removed the paint

from mating surfaces on all new parts

-Installed new sprocket segs, torqued bolts to 525 lb-ft with loc tite

-Installed new bottom rollers, torqued bolt to 200 lb-ft with loc tite

-Installed new carrier rollers and adjusted

-Installed new idlers and adjusted



CONTINUED ON PAGE 02

Thank you for your business

Emp to.

Invoice to:

Date 10/09/20 Time 19:02:57 (B) Page 02
Account No. 1645005 Phone No. 9528901645 Invoice No. W5527201
Ship Via Purchase Order D7812-753
Tax Exemption Number Federal ID Number

Salesperson
JVK / AKR

SERVICE INVOICE

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS
X503853 CRAWLER DOZER >130 6126 1T0750KXACE230238 06/07/14
750K 06/05/18 5000 H

-Wrapped tracks and connected split links, installed master pad and bolts. Torqued bolt to 199 lb-ft and a 1/2 turn with anti-seize

-Adjusted track sag to 1 3/4 inches, tested tracks and adjusted again to spec

AT274298	BUSHING	8
PM37562	ANTI-SEIZE COMP	1
	ANTI-SEIZE Compound	
PM38656	GASKET	1
01051596	BOLT	72 S
01071569	S/F ROLLER	10
01071570	D/F ROLLER	6
01080551	TOP ROLLER	4
01090701	WASHER 5/8	72
05100028	FRONT IDLER	2
05120004	SPROCKT	2
08050200	SPROCK BOL	50
08050300	MNTG BOLT	8 S
11050113	WASHER, M20 HAR	8

PARTS
LABOR

10401099

SEGMENT TOTAL==>

SEGMENT# 2 C P1101 NA 09/30/20 09/30/20

PAD CHANGE TO NEW RAILS

CONDITION:

Pad Change to new rails.

CORRECTION:

-Removed dirt from top of tracks.

-Removed and discarded old hardware.

CONTINUED ON PAGE 03

Thank you for your business

Date 10/09/20 Time 19:02:57 (B) Page 03
 Account No. 1645005 Phone No. 9528901645 Invoice No. W5527201
 Ship Via Purchase Order D7812-753
 Tax Exemption Number Federal ID Number

Invoice to:

Salesperson
 JVK / AKR

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
X583853	CRAWLER DOZER >130 750K	6126	1T0750KXACE230238	06/07/14 06/05/18	5000 H

- Removed and discarded old track chains.
- Flipped over track pads.
- Cleaned mating surface of track pads.
- Cleaned paint off mating surface of track chains.
- Flipped track pads over onto track chains.
- Greased and installed new hardware.
- Tightened track pads to track chains.

01020754	45LINK SALT	2 S
01050023	NUT	352
01050030	BOLT	352

PARTS
 LABOR

10401099 24302001
 SEGMENT TOTAL==>

SEGMENT# 3 C MCJ01 RDO-900-080 09/30/20 09/30/20
 CUSTOMER MACHINE INSPECTION, CONSTRUCTION/FORESTRY/VERMEER
 CONDITION:

Machine Inspection.

- ___ Check machine over for any needed repairs or service.
- ___ Check Fluid Levels.
- ___ Check for leaks.
- ___ Check A/C and Heater function.
- ___ Check condition of hydraulic hoses and cylinders.
- ___ Check and note any stored or active codes.
- ___ Check for Loose or missing hardware.
- ___ Check operation of machine.
- ___ Check lights, wipers, and electrical system.
- ___ Check condition of battery.
- ___ Check condition of glass and sheet metal.
- ___ Check safety items (horn, back up alarm, seat belt,

CONTINUED ON PAGE 04

Thank you for your business