Invoice			
Bill To	Plate MO 1 Description 2012 Ran VIN 3C7WDN Odometer 256,864	5500 SLT L6 6.7 BL8CG233551	L 408CID VIN L
Home .			
Invoice # Work Order # Service Advisor Technician	Invoice Date 10/11/20 Appointment 9/23/202 Promised 9/23/202	1 1:42 PM	
Service			
Certi-Care Evaluation Initial diagnosis, including: Short road test where applicable, und condition), scanning of vehicle's computer system. Additional dia Customer Concern: No movement.	er car inspection, inspection gnosis and testing time may	of all drive-line flu be required at ad	uids (level and Iditional charges.
CT Found: Transmission fluid-high, old/degraded, red. Codes pr sensor shows no rpms in any gear. Internal transmission failure. Evaluation	esent. Did not drive. Vehicle h	as no movement	. Turbine speed
Techniciar		Sub	
Remanufactured Transmission Remove and Replace Transmission Technician: Powerflush Transmission Lines			
Technician: T6451AAR3000 - 402WHS2536 - Reman Transmission	1 Unit		
3100W - 3 year/100,000 Mile Warranty - Wholesale	1 Unit		
Mobil-MV-Qt - Mobil 1 ATF	22 Quart		
1212W - 12 Month/12,000 Mile Warranty - Wholesale	1 Unit 1 Unit		
005395 - PTO bolt	1 Unit		
CS - Customer supplied billet flexplate(no warranty)			
Replace transfer case input seal			
Technician:	1 Unit		
5019020AB - Input Seal Mopar		Discount	(\$1,069.30) \$9,816.44
		Sub	\$3,010.44
Results Found worn stock flexplate. Customer supplied their own billet	flexplate.		
Final Road Test Final road test, lift inspection, and fluid check after repairs are of Labor	completed.		\$0.00
Technician:		Sub	\$0.00
			\$0.00

\$0.00

Sub

## Maintenance Work Order

Priority: Due Date: Normal

Scheduling:

Mechanic Name	Schedule Date	Work Complete?
	1/4/2023	~
	1/7/2023	~
	2/3/2023	~

Status:

Closed

Status Date: Total Cost: 2/16/2023 \$16,950.07

Description:

2012 RAM 5500 SERVICE TRUCK

VIN#

Serial #

3C7WDNBL8CG233551

Make:

Model:

5500

Meter Reading:

Hours: 9944

on 2/15/2023

Odometer: 289820

on 2/15/2023

Last Hour Service (Lifetime):

on

Last Odometer Service (Lifetime):

on

Problem Description:

Engine rebuild, taking to Maschmeier

ST

-A/c pump -engine gaskets -water pump -fan clutch

Labor Items:

Work Code

Item Code

OT

DT

Total \$

Repair

Engine

Parts List:

AUTOMOTIVE AUTOMOTIVE		HE STREET, SPINGERS HE WAS A STREET, WHICH SERVICES		
Part Num	Name	UOM	Qty Used	Total S
A MALESTANIE	a ame	CON	Qty Cseu	And the second s
processors of the community and community	THE RESIDENCE AND ADDRESS OF THE PERSON NAMED IN COLUMN 1	THE RESERVE OF THE PARTY OF THE		

## Cost Ledger:

Туре	Ref Num	Description	Estimated Cost	Total \$
Parts		Lines		
Parts		Turbo		
Parts		Air filter		
Parts		Seals		
Parts		Oil		
Parts		Engine work		
Parts		Water pump, AC pump		
Parts		Bracket, dowel pins		
Parts		Shroud		
Parts		Paint		

## Maintenance Work Order

Work Order: Priority: Due Date:

Normal


Cost Ledger:

Туре	Ref Num	Description	Estimated Co	st Total \$
Parts		Turbo hose		
Parts		Misc		
Parts		Battery amd misc		
Parts		Fan clutch		
Parts		Heater core		
Parts		Misc		
Parts		Crankcase sensor		
Parts		Oil cooler and bypass k	it	
Parts		Gasket		
Reconciled Pure	rhases:			
Part Num	Description	Invoice# R	ef# Qty Used	Total S

Notes:

Date	1/23/2023
Number	

BILL TO



Customer CID 6.7 CUMMINS Core short block Sleeves Rods ARP 247-6303 Rod Bolts Engine kit MAHLE **Pistons** INC Rings INC Bearings Cam INC INC Mains Rods INC

Camshaft Intake Exhaust Seperation Intake Centerline Lifters Pushrods Intake Exhaust Rocker Arms Intake Exhaust Timing set Front cover Fasteners T/D Oil pump stud Heads

Intake Valve cover

Misc Valve covers

Cyl Heads Valves Intake Exhaust Valve Springs Retainers Locks Locators Seals Shims Guides Seats Oil Pan Oil Pump Pump Pick Up Oil pump shaft Gaskets Valve Cover Intake Head Pan Front cover Rear seal Timing pointer Damper

**NEW SPRINGS** 

VITON

Mallory
Jesel crank seal
Jesel thrust washer
Drive Mandrel
Freeze plug kit
Shipping

TOTAL 5940.18